

EXHIBIT D

JENNER & BLOCK LLP
Reid J. Schar (*pro hac vice*)
RSchar@jenner.com
353 N. Clark Street
Chicago, IL 60654-3456
Telephone: (312) 222-9350
Facsimile: (312) 527-0484

CLARENCE DYER & COHEN LLP
Kate Dyer (Bar No. 171891)
kdyer@clarencedyer.com
899 Ellis Street
San Francisco, CA 94109-7807
Telephone: (415) 749-1800
Facsimile: (415) 749-1694

CRAVATH, SWAINE & MOORE LLP
Kevin J. Orsini (*pro hac vice*)
korsini@cravath.com
825 Eighth Avenue
New York, NY 10019
Telephone: (212) 474-1000
Facsimile: (212) 474-3700

Attorneys for Defendant PACIFIC GAS AND
ELECTRIC COMPANY

UNITED STATES DISTRICT COURT

NORTHERN DISTRICT OF CALIFORNIA, SAN FRANCISCO DIVISION

UNITED STATES OF AMERICA,

Plaintiff,

vs.

PACIFIC GAS AND ELECTRIC
COMPANY,

Defendant.

Case No. 14-CR-00175-WHA

**DECLARATION OF [REDACTED] IN
SUPPORT OF RESPONSE TO ORDER
REQUESTING INFORMATION ON
DIXIE AND BADER FIRES**

Judge: Hon. William Alsup

1 I, [REDACTED], declare at follows:


2 1. I make this declaration based upon personal knowledge and if called as a witness I
3 could and would testify competently to the matters set forth herein.

4 2. I am a Senior Distribution Engineer at Pacific Gas and Electric Company
5 (“PG&E”). In the course of my duties at PG&E, I have become familiar with the operation of the
6 line reclosers used by the company, the electronic data they transmit and store, and the use of
7 appropriate software tools to read and analyze the stored data.

8 3. I have reviewed the electronic data files provided to me by [REDACTED], Senior
9 Manager of PG&E’s Distribution Planning Group. [REDACTED] advised me that these files were
10 downloaded on July 21, 2021 from the electronic controller on the Cooper line recloser located at
11 the substation for PG&E’s Bucks Creek 1101 12kV Line. I reviewed these data files using
12 Cooper Proview 5.0 software.

13 4. One data file I reviewed is labeled “bucks creek 1101_2_asfound_07212021.f6s”.
14 This data file contains the line recloser’s settings at the time the file was downloaded. The file
15 label indicates that the data is from the line recloser for the Bucks Creek 1101 line and that it was
16 downloaded on July 21, 2021.

17 5. The following is a true and correct screenshot of the setting group selector data in
18 the “bucks creek 1101_2_asfound_07212021.f6s” file:



23 This data shows that “Alternative #1” was the active setting group profile when the “bucks creek
24 1101_2_asfound_07212021.f6s” file was downloaded on July 21, 2021.

6. The following is a true and correct screenshot of the “Alternate 1” sensitive earth fault setting data in the “bucks creek 1101_2_asfound_07212021.f6s” file:

Sensitive Earth Fault

Edit Group **Alternate 1** Change Setting Group

Sensitive Earth

Minimum Trip 20 Amps

Time Delay 20 Seconds

Reclose Interval 20 Seconds

Operations to Lockout 1

☐ Block Sensitive Earth Fault Tripping

OK Cancel Help

7. The following is a true and correct screenshot of the “Alternate 1” operations sequence setting data in the “bucks creek 1101_2_asfound_07212021.f6s” file:

Simplified Setup

Group **Alternate 1** Cancel Help OK

Operations Sequence

	TCC1	TCC2	Min Trip	Trip #1	Trip #2	Trip #3	Trip #4
Ph	133	133	100	TCC2	TCC2	TCC2	TCC2
Ph Rcls Interval #1, #2, #3			10	15	5		
Gd	165	165	50	TCC2	TCC2	TCC2	TCC2
Gd Rcls Interval #1, #2, #3			10	15	5		
Trips to Lockout	3		Reset Time 90				

Complex TCC

	Time Multiplier	Time Adder	Min Rsp Time
TCC1 Ph	1	0	0.01
TCC1 Gd	1	0.1	0.01
TCC2 Ph	1	0	0.01
TCC2 Gd	1	0.1	0.01

High Current Trip

	HCT	Min Trip Mult	Time Delay
TCC1 Ph	En	8	0.01
TCC1 Gd	En	14	0.01
TCC2 Ph	En	8	0.01
TCC2 Gd	En	14	0.01

Complex TCC

	Disk Reset Coeff.
TCC1 Ph	15
TCC1 Gd	1e-006
TCC2 Ph	15
TCC2 Gd	1e-006

High Current Lockout

	Pickup	Trip #1	Trip #2	Trip #3
Ph	1440	En	En	En
Gd	1400	En	En	En

Reclose Retry

☒ Enable Interval 30 # of Attempts 10

Interrupter Duty

100% Duty Factor **Preset** Ph A% 6.28334 Ph B% 1.06445 Ph C% 0.615216

196 [kA*10⁻⁵]

8. A second data file I reviewed is labeled “bucks creek 1101_2_SOE_07212021.f6s.txt”. This data file contains the line recloser’s recording of certain events, including (1) a change in the active group setting profile, (2) a change in the control to a mode in which the line recloser will not automatically reclose after being opened, and (3) the opening of the line recloser. Once again, the file label indicates that the data is from the line recloser for the Bucks Creek 1101 line and that it was downloaded on July 21, 2021.

9. The following is a true and correct screenshot of the sequence of events data in the “bucks creek 1101_2_SOE_07212021.f6s.txt” file from the date of download back to February 16, 2021:


bucks creek 1101_2_SOE_07212021.f6s.txt - Notepad

File Edit Format View Help											
User device name = Bucks 1101 F6 Rev 28											
Evt	Date	Time	Type	IA	IB	IC	3I0	VA	VB	VC	
001	21/07/14	19:09:24.322	MAN/EXT TRIP/LO	0	0	0	0	119	120	118	
002	21/07/14	19:09:24.322	CONTROL LOCKOUT	0	0	0	0	119	120	118	
003	21/06/24	08:13:55.557	no control alarm	0	0	0	0	113	115	107	
004	21/06/24	04:16:52.628	CONTROL ALARMS	0	0	0	0	0	0	0	
005	21/05/06	13:39:30.988	NON-RECLOSE ON	2	3	2	0	117	119	117	
006	21/05/03	07:00:34.314	no control alarm	2	2	2	0	117	118	116	
007	21/05/03	07:00:28.512	CONTROL ALARMS	0	0	0	0	0	0	0	
008	21/02/17	17:20:45.231	ALT PROFILE #1	0	0	0	0	99	98	98	
009	21/02/16	10:46:08.572	NORMAL PROFILE	0	0	0	0	113	113	113	

This data shows that the “Alternate #1” setting group was selected on February 17, 2021 and was not changed through the date the data was downloaded. This data also shows that the mode in which the line recloser will not automatically reclose after being opened was selected on May 6, 2021 and was not changed through the date the data was downloaded. This data further shows that no events that should be recorded in this file if they occurred—including an opening of the line recloser—were recorded on July 13, 2021.


10. A third data file I reviewed is labeled “2021-07-13 05.57.18.414.evt”. This data file was created because the recloser detected a phase to phase fault event that involved current in excess of the “minimum to trip” amperage setting for such faults in the “Alternate #1” operations sequence setting.

11. The file name indicates that current in excess of the “minimum to trip” was detected at 5:57:18.414 on July 13, 2021 as reported by the line recloser’s internal clock. However, I received from [REDACTED] the following screen shot which he advises was taken at the time the data I reviewed was downloaded from the line recloser:




This shows that the internal clock on the recloser is running 50 minutes and 28.3 seconds behind the time reported by the internal clock on the laptop used to download the data. Adjusting for this fact would make the time when the current exceeded the “minimum to trip” approximately 6:47:46.714 a.m. on July 13, 2021.

12. The event file contains the recorded oscillography data for that phase to phase fault event. The following is a true and correct screen shot reflecting the time and amperage recorded in the oscillography data when I placed my cursor at the time interval where the phase to phase fault event begins:




This indicates that the phase to phase fault event involved just two of the three phases and began at approximately 22:57:18.4000 on July 12, 2021. The oscillography, however, uses Coordinated Universal Time (“UTC”), which is seven hours behind Pacific Daylight Time. Adjusting for this fact and for the difference between the internal clock of the line recloser and the internal clock on the laptop downloading the data would make the time when the current exceeded the “minimum to trip” approximately 6:47:46.7000 a.m. on July 13, 2021.


13. The following is a true and correct screen shot reflecting the time and amperage recorded in the oscillography data when I placed my cursor at the time interval when the above “minimum to trip” element in the controller asserts:



14. The following is a true and correct screen shot reflecting the time and amperage recorded in the oscillography data when I placed my cursor at the time interval when the amperage in the phase to phase fault event is at its maximum:




15. The following is a true and correct screen shot reflecting the time and amperage recorded in the oscillography data when I placed my cursor at the time interval where the phase to phase fault event ends:



This indicates that the phase to phase fault event ended at approximately 22:57:18.4395 on July 12, 2021. The oscillography, however, uses Coordinated Universal Time ("UTC"), which is seven hours behind Pacific Daylight Time. Adjusting for this fact and for the difference between the internal clock of the line recloser and the internal clock on the laptop downloading the data would

1 make the time when the current exceeded the “minimum to trip” approximately 6:47:46.7395 a.m.
 2 on July 13, 2021 (0.0395 seconds after it began).

3 16. The following is a true and correct screen shot reflecting the time and amperage recorded
 4 in the oscillography data when I placed my cursor at the time interval when the above “minimum
 5 to trip” element in the controller de-asserts:



19 I declare under penalty of perjury under the laws of the United States and the State of
 20 California that the foregoing is true and correct.

21 Executed this 28th day of July, 2021, in the City of Atascadero, County of San Luis
 22 Obispo, State of California.

[REDACTED]