Primary Maintenance Reason Code **WT 11477550**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11477550**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11477550**

Additional Notes: **WT 11477550**

PROCEDURE STEP DETAILS **WT 11477550**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11419108

WORK TASK DET

TASK PRIORITY	3 Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	PAC
		TRACKING STATUS			
RESPONSIBLE ORG	AFB - WATER AND FUELS MX - PLUMB INT - BOS-			**RESPONSIBLE PERSON**	(NU)
CUSTOMER ORG	AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	6 PM
EST HOURS		**PLANNED START**	05/27/2022 06:40:40	**PLANNED END**	
TASK NAME	3 S ADMIN, RM 115 - WT - INTPLUMB - MIXING VALVE HAS SLOW LEA 4591 - H - 405-200-3131 - -				
TASK DESCRIPTION	J S CLOSET, THE MIXING VALVE HAS A SLOW LEAK				

FOREMAN'S NOTES TO CRAFTSMEN

__ ty Precautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM __ Coordination R d

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Cleara equired

SERVICE REQUEST DETAILS WT 11 08

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PH E

FACILITY PROJECT DETAILS WT 11419108

ASSET DETAILS WT 11419108

WARRANTY DETAILS WT 11419108

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11419108

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11419108

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11419108**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11419108**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11419108**

Additional Notes: **WT 11419108**

PROCEDURE STEP DETAILS **WT 11419108**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

W ASK 11899930

WORK TASK DETAILS

TASK PRIORITY	3A - High Sust	**ATUS KING ATUS**	Closed	**PRIMARY WORK LOCATION**	CE
RESPONSIBLE ORG	TINKER AFB SYSTEM MX BMC		LS -	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB		0 - 63G		
TASK TYPE	Corrective	**LASS**	Leaks		PM
EST HOURS	0	**TART**	09/19/2022 08:28:54		
TASK NAME	3A - 9001 RC		PLUMB - POSSIBLE LE		- 7368784
TASK DESCRIPTION	Room 116, w water damag 19SEP22 10 19SEP22 12 19SEP22 13 THE LEAK,		116 in the South Admi et. BELLOWS ON SITE NE COMING OFF OF ADVISED REQUESTOR	e	kroom is showing ICE MAKER TO BE THE CAUSE OF 0.9 HOUR LABOR
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Pr __ Digging P		__Multi-Shop C __Environmenta	d	__ FD/SFS/COMM/_____ Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAI

WT 11899930

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3138365	09/19/2022 08:22:22	405-736-8784

FACILITY PROJECT DETAIL

WT 11899930

ASSET DETAILS

WT 11899930

WARRANTY DETAILS

WT 11899930

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11899930

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11899930

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11899930**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11899930**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11899930**

Additional Notes: **WT 11899930**

PROCEDURE STEP DETAILS **WT 11899930**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee

WORK TASK 120237

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMAR LOCATIO**	TINKER AE COMPLEX-9
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPON PERSON**	[redacted]
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**T**	ar 1, 2023,
EST HOURS	0	**PLANNED START**	10/12/2022 01:00:00		0/12/2022 1:00:00
TASK NAME	3C - 9001 S ADMIN ANNEX RM 119 MEN'S RR - WT - INT 622-7846				CLOGGED [redacted] -
TASK DESCRIPTION	3C - 9001 South Admin Annex Room 119 MRR - 2nd sink is				405.622.784 9
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coo __Environmental C		__ FD/SFS/COMM/_ Coordination Re Travel/Access Clearan quired

SERVICE REQUEST DETAILS

WT 120

REQUEST ID	CREATED DATE/TIME	WORK PH
3176432	10/11/2022 14:41:02	(405) 622-

FACILITY PROJECT DETAILS

WT 120

ASSET DETAILS

WT 120

WARRANTY DETAILS

WT 12023721

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12023721

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 12023721

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12023721**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12023721**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12023721**

Additional Notes: **WT 12023721**

PROCEDURE STEP DETAILS **WT 12023721**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

ORK TASK 119429 8

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMARY LOCATIO**	INK OMP
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPE STRUCTURES - BC		TM - TAC C	**RESPON PERSON**	
CUSTOMER ORG	TINKE B 6 M		TAC 9000 - 63G		
TASK TYPE	Corre	**UEST CLASS**	General Repairs	**E**	a
EST HOURS	0	**NNED START**	09/24/2022 01:00:00		
TASK NAME	3C - 405-7		- TAC STRUCTURES- pipe lea		
TASK DESCRIPTION	3C - POC REQ	P	- ROOF - pipe leaking on attend PLUMBING SHOP 405-734-27 OP CHECK FOR LEAKS AROUN		
FOREMAN'S NOTES TO CRAFTSMEN	__ S __ D	o R	quired ed	__Multi-Shop Co __Environmenta	/SFS/COM oordinatio ccess Cle uired

SERVICE REQUEST WT

REQUEST I	EATED DATE/TIME	WORK
314991	/23/2022 16:37:02	405)

FACILITY PROJECT WT

ASSET DETAILS WT

WARRANTY DETAILS

WT 11942958

ID	EAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11942958

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ WT 11942958

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11942958**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11942958**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11942958**

Additional Notes: **WT 11942958**

PROCEDURE STEP DETAILS **WT 11942958**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

RK TASK 12036002

WORK TASK DETAIL

TASK PRIORITY	3C -	**STATUS**	Completed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
		TRACKING STATUS	Awaiting Scheduling		
RESPONSIBLE ORG	TINK INSU		TM -	**RESPONSIBLE PERSON**	
CUSTOMER ORG					
TASK TYPE		**EST CLASS**	General Repairs	**N**	Mar 1, 2023, 9:08 PM
EST HOURS		**NED START**	10/14/2022 01:00:00		10/14/2022 01:00:00
TASK NAME			T - INSULATOR- F/U 11942958 -582-4496		EAKING ON ATTENDENTS WORK
TASK DESCRIPTION			T - INSULATOR- F/U 11942958 496		EAKIN ON ATTENDENTS WORK CAGE-
FOREMAN'S NOTES TO CRAFTSMEN		quired	__Multi-Shop Co		__ FD/SFS/COMM/_____ Coordination Required
		Required	__Environmental		ed __Travel/Access Clearance Required

SERVICE REQU **WT 12036002**

REQU	CREATED DATE/TIME	WORK PHONE
3181	10/13/2022 15:16:42	405-582-4496

FACILITY PRO **WT 12036002**

ASSET DETAIL **WT 12036002**

WARRANTY DE **WT 12036002**

ID	EAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 12036002**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 12036002**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12036002**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12036002**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12036002**

Additional Notes: **WT 12036002**

PROCEDURE STEP DETAILS **WT 12036002**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

K TASK 11694489

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS** / **ACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	TI CO CE
RESPONSIBLE ORG	TINKER AFB - WA SYSTEM MX - PLU BMC		FUELS BOS-	**RESPONSIBLE PERSON**	B
CUSTOMER ORG	TINKER AFB - 7 M		9000 - 63G		
TASK TYPE	Corrective	**T CLASS**	Leaks	E E	Ma
EST HOURS	0	**D START**	08/03/2022 01:00:00	D	08 01
TASK NAME	3B - 9001 Post S SR3056290		plumb - pipe leaking on atte	repair -	-4105 -
TASK DESCRIPTION	Bldg 9001, Cage information. Call		as a pipe leaking on attenda at 582-4105 for questions.	cage. Se	for more
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Preca __ Digging Perm	d	__Multi-Shop Co __Environmental	ired __T	/_____ equired ance Required

SERVICE REQUEST DETAILS 11694489

REQUEST ID	D DATE/TIME	HONE
3056290	2022 12:09:00	2-4105

FACILITY PROJECT DETAILS 11694489

ASSET DETAILS 11694489

WARRANTY DETAILS WT 11694489

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11694489

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11694489**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11694489**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11694489**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11694489**

Additional Notes: **WT 11694489**

PROCEDURE STEP DETAILS **WT 11694489**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK	**11479553**		
WORK TASK DE			
TASK PRIORITY	**STATUS** Completed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
	TRACKING STATUS		
RESPONSIBLE ORG	ER AND FUELS B INT - BOS-	**RESPONSIBLE PERSON**	
CUSTOMER OR	ES		
TASK TYPE	**REQUEST CLASS** Drainage		Mar 1, 2023, 2:26 PM
EST HOURS	**PLANNED START** 06/10/2022 01:00:00		06/10/2022 01:00:00
TASK NAME	0 -WT- PLUMB INT - DRAIN PIPE IS 582-4496		F/U FROM 11404075 - REPAIR -
TASK DESCRIPTION	0 -WT- PLUMB INT - DRAIN PIPE IS - 582-4496		F/U FROM 11404075 - REPAIR -
FOREMAN'S NOTES TO CRAFTSMEN	ns Required __Multi-Shop C		__ FD/SFS/COMM/_____ Coordination Required
	equired __Environmenta		ed __Travel/Access Clearance Required
SERVICE REQ			**WT 11479553**
REQU	**CREATED DATE/TIME**		**WORK PHONE**
29	06/09/2022 15:46:45		405-582-4496
FACILITY PRO			**WT 11479553**
ASSET DETA			**WT 11479553**

WARRANTY D **WT 11479553**

ID	AL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11479553**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11479553**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11479553**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11479553**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11479553**

Additional Notes: **WT 11479553**

PROCEDURE STEP DETAILS **WT 11479553**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

K TASK

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**TATUS CKING TATUS** Closed	**RK** TINKER AEROSPACE COMPLEX-9001
RESPONSIBLE ORG	TINKER AFB - S STRUCTURES -	TAC	**LE**
CUSTOMER ORG	TINKER AFB -	0 - 63G	
TASK TYPE	Corrective	**LASS** Leaks	**TE** Mar 1, 2023, 6:56 PM
EST HOURS	0	**TART** 08/31/2022 09:17:43	**ND** 08/31/2022 09:17:43
TASK NAME	3B - 9001 POS	STRUC - WATER LEAK	- 582-4196
TASK DESCRIPTION	Location: Bldg Description of p / Possibly coming from hole in roof Requester nam Phone number		
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Prec	__Multi-Shop Coo	__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Per	__Environmental	ired __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11811983

REQUEST ID	C	ATE/TIME	U	E	WORK PHONE
3109717	0 /2	09:07:26		R	405-582-4196

FACILITY PROJECT DETAILS

WT 11811983

ASSET DETAILS

WT 11811983

WARRANTY DETAILS

WT 11811983

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11811983

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11811983

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11811983**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11811983**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11811983**

Additional Notes: **WT 11811983**

PROCEDURE STEP DETAILS **WT 11811983**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11844602

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER A COMPLE
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE	Corrective	**REQUEST CLASS**	General Repairs		Mar 1, 202
EST HOURS	0	**PLANNED START**	09/08/2022 10:27:21		09/08/202 10:27:21
TASK NAME	3B - 9001 POST S32 - WT - TAC HVAC- ASSIST TAC ST				ATER LEAK - 582-4196
TASK DESCRIPTION	3B - 9001 POST S32 - WT - TAC HVAC- ASSIST TAC ST				ATER LEAK - 582-4196
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Co		_ FD C ed
	__ Digging Permit Required		__Environmenta	ed	__Travel/A Required

SERVICE REQUEST DETAILS

02

REQUEST ID	CREATED DATE/TIME
3121595	09/08/2022 10:26:24

E

FACILITY PROJECT DETAILS

02

ASSET DETAILS

02

WARRANTY DETAILS

WT 11844602

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11844602

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11844602

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11844602**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11844602**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11844602**

Additional Notes: **WT 11844602**

PROCEDURE STEP DETAILS **WT 11844602**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1401963

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WO LOCATION**	PACE
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBL PERSON**	(NU)
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Leaks	**PRINTED DA**	12 PM
EST HOURS		**PLANNED START**	05/24/2022 08:20:56	**PLANNED EN**	
TASK NAME	3B - 9001 POST S34 - WT - INTPLUMB - STORM DRAIN LEAK - REPAIR -				582-4495
TASK DESCRIPTION					

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required
__Multi-Shop Coordination Required
__ FD/SFS/COMM/_____ Coordination Required
__ Digging Permit Required
__Environmental Coordination Required
__Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11401963

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11401963

ASSET DETAILS

WT 11401963

WARRANTY DETAILS

WT 11401963

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11401963

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11401963

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11401963**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11401963**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11401963**

Additional Notes: **WT 11401963**

PROCEDURE STEP DETAILS **WT 11401963**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11712481

WORK TASK DE

TASK PRIORITY	n	**STATUS** Closed **TRACKING STATUS**	**PRIMARY WORK LOCATION** TINKER AEROSPACE COMPLEX-9001
RESPONSIBLE ORG	SPEC MX TM - TAC C		**RESPONSIBLE PERSON**
CUSTOMER ORG	76 MXW TAC 9000 - 63G		
TASK TYPE		**REQUEST CLASS** Leaks	**TE** Mar 1, 2023, 6:19 PM
EST HOURS		**PLANNED START** 08/08/2022 10:54:07	**D** 08/08/2022 10:54:07
TASK NAME	47 FOYER - WT - TAC HVAC - CHECK/RE 622-7846		VE CEILING INSIDE FOYER - REPAIR -
TASK DESCRIPTION	S47 Foyer - check/repair leaks above ceilin		of door S47 and replace stained/damaged

FOREMAN'S NOTES TO CRAFTSMEN

autions Required __Multi-Shop Coo d __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental C ired __Travel/Access Clearance Required

SERVICE REQUEST DETAILS — WT 11712481

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3062860	08/08/2022 10:51:48	(405) 622-7846

FACILITY PROJECT DETAILS — WT 11712481

ASSET DETAILS — WT 11712481

WARRANTY DETAILS — WT 11712481

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11712481

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — WT 11712481

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11712481**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11712481**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11712481**

Additional Notes: **WT 11712481**

PROCEDURE STEP DETAILS **WT 11712481**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11712277

WORK TASK DE

TASK PRIORITY	um	**STATUS** Closed **TRACKING STATUS**	**PRIMARY WORK LOCATION** TINKER AEROSPACE COMPLEX-9001
RESPONSIBLE ORG	AFB - SPEC MX TM - TAC OS-BMC		**RESPONSIBLE PERSON**
CUSTOMER ORG	AFB - 76 MXW TAC 9000 - 63G		
TASK TYPE	e	**REQUEST CLASS** Leaks	E Mar 1, 2023, 6:17 PM
EST HOURS		**PLANNED START** 08/08/2022 10:39:28	D 08/08/2022 10:39:28
TASK NAME	DR S54 FOYER - WT - TAC HVAC - CHECK/RE		VE DROP CEILING - REPAIR -
	622-7846		
TASK DESCRIPTION	door S54 Foyer - Check and repair leaks above		e stained damaged ceiling tiles.
FOREMAN'S NOTES TO CRAFTSMEN	_ ty Precautions Required	__Multi-Shop Co	__ FD/SFS/COMM/__ Coordination Requ
	__ Digging Permit Required	__Environmental	ired __Travel/Access Clearance d

SERVICE REQUEST DETAILS WT 11712

REQUEST ID	CREATED DATE/TIME	WORK PHO
3062717	08/08/2022 10:36:47	(405) 622-78

FACILITY PROJECT DETAILS WT 11712

ASSET DETAILS WT 11712

WARRANTY DETAILS WT 11712277

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11712277

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11712277

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11712277**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11712277**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11712277**

Additional Notes: **WT 11712277**

PROCEDURE STEP DETAILS **WT 11712277**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11493032

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINK MPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	Mar
EST HOURS		**PLANNED START**	06/13/2022 12:25:11	**PLANNED END**	06/ 12:
TASK NAME	3A - 9001 & MENS RESTROOM - WT - INT PLUMB - STOP OVERFLOWING - Repai				- 7368784
TASK DESCRIPTION	TOILETS OVERFLOWING ONTO THE FLOOR AT SOUTH ADMIN WEST END MENS 13JUN2022 13:03 MULLINS/SOLOMON ON SITE 13JUN2022 1404 TOILET WOULD NOT FLUSH, NOT OVERFLOWING. DIAPHRAM AND ISSUE RESOLVED. 1 HOUR LABOR.				GED OUT
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordination Required __Environmental Coordination Required		____ uired e Required

SERVICE REQUEST DETAILS

3032

REQUEST ID	CREATED DATE/TIME	FULL NAME	NE

FACILITY PROJECT DETAILS

3032

ASSET DETAILS

93032

WARRANTY DETAILS

WT 11493032

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11493032

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11493032

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11493032**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11493032**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11493032**

Additional Notes: **WT 11493032**

PROCEDURE STEP DETAILS **WT 11493032**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11776772

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMARY W RK LOCATION**	TINKER AEROS COMPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIB PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs		Mar 1, 2023, 10:1
EST HOURS	0	**PLANNED START**	08/24/2022 01:00:00		08/24/2022 01:00:00
TASK NAME	3C - 9001 T48 - WT - Intplumb - clear clogged line in fixtur e for problems - repair - 622-7846 - SR3095249				
TASK DESCRIPTION	3C - 9001 T48 - ongoing clogged drain line is causing floo e area, please clear clo drain line to determine what might be causing the ongoing issue 622.7846				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Co		__ FD/SFS/COMM Coordination R _
	__ Digging Permit Required		__Environmenta		red __Travel/Access Clear quired

SERVICE REQUEST DETAILS

WT 1

REQUEST ID	CREATED DATE/TIME	WORK P
3095249	08/23/2022 16:17:44	(405) 62

FACILITY PROJECT DETAILS

WT 1

ASSET DETAILS

WT 11

WARRANTY DETAILS

WT 11776772

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11776772

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11776772

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11776772**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11776772**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11776772**

Additional Notes: **WT 11776772**

PROCEDURE STEP DETAILS **WT 11776772**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11690542

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS TRACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AER COMPLEX-9
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000				
TASK TYPE	Corrective	**REQUEST CL**	o	**E**	Mar 1, 2023,
EST HOURS	0	**PLANNED ST**	[redacted]22		08/01/2022 10:10:11
TASK NAME	3B - 9001 POST T48 - WT - INT P[redacted]CLOGG[redacted]DING - REPAIR [redacted]H 582-4105 - SR# 3054240				
TASK DESCRIPTION	Priority 3B, Bldg 9001, Post T48. A[redacted] post th[redacted] logged and wate[redacted] in [redacted]om it causing flooding. Any questions c[redacted] at 582-				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Require		[redacted]hop Co [redacted]nmental		__ FD/SFS/COMM/_ Coordination Req d __ Travel/Access Clearan[redacted]uired

SERVICE REQUEST DETAILS

WT 1169[redacted]

REQUEST ID	CREATED D[redacted]	WORK PHO[redacted]
3054240	8/01/2022[redacted]	(405) 582-4[redacted]

FACILITY PROJECT DETAILS

WT 1169[redacted]

ASSET DETAILS

WT 1169[redacted]

[redacted]

WARRANTY DETAILS

WT 11690542

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11690542

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11690542

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11690542**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11690542**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11690542**

Additional Notes: **WT 11690542**

PROCEDURE STEP DETAILS **WT 11690542**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11606019

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSP COMPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	Mar 1, 2023, 3:11 P
EST HOURS		**PLANNED START**	07/08/2022 13:25:43	**PLANNED END**	07/08/2022 13:25:43
TASK NAME	3B - 9001 BTWN POSTS U28/U29 - WT - TAC HVAC - CONDENSATION WATER LEAK - REPAIR - 622-7846				
TASK DESCRIPTION	CONDENSATION WATER LEAKING; BETWEEN POSTS U28/U29; BUCKETS ARE CONTAINING				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	__Multi-Shop Coordination Required		__ FD/SFS/COMM/ Coordination Re	
	__ Digging Permit Required	__Environmental Coordination Required		__Travel/Access Cleara	d

SERVICE REQUEST DETAILS

WT 116

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PH

FACILITY PROJECT DETAILS

WT 116

ASSET DETAILS

WT 11606019

WARRANTY DETAILS

WT 11606019

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11606019

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11606019

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11606019**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11606019**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11606019**

Additional Notes: **WT 11606019**

PROCEDURE STEP DETAILS **WT 11606019**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11647 99

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMA LOCAT**	**WORK** TINKER AERO COMPLEX-90
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPO BLE PERSO**	
CUSTOMER ORG	R AFB - 72 CS				
TASK TYPE	tive	**REQUEST CLA**		**TE**	Mar 1, 2023, 3
EST HOURS		**PLANNED STA**	22	**D**	07/19/2022 10:55:41
TASK NAME	01 POST U32-U33 - WT - TA 56		CT COND	K - Repair - 3033483	
TASK DESCRIPTION	onditioning duct is leaking co f Contact: Don St. Hilaire (Su Supervisor, F108 Assembly),		eating a c 3 Disasse (USR/GS	dle BETWEEN POST	
FOREMAN'S NOTES TO CRAFTSMEN	ty Precautions Required ing Permit Required		hop Coor nmental C	d uired	__ FD/SFS/COMM Coordination __ Travel/Access Clea

SERVICE REQU TAILS **WT 1**

REQUE	CREATED DA	WORK
30334	7/19/2022 10	05-58

FACILITY PROJ TAILS **WT 1**

ASSET DETAILS **WT 1**

WARRANTY DETAILS

WT 11647599

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11647599

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11647599**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11647599**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11647599**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11647599**

Additional Notes: **WT 11647599**

PROCEDURE STEP DETAILS **WT 11647599**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11535701

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS** / **TRACKING STATUS**	Completed	**PRIMARY WORK LOCATION**	TINKER A COMPLE
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE	Corrective	**REQUEST CLASS**	General Repairs		Mar 1, 20
EST HOURS	0	**PLANNED START**	06/23/2022 01:00:00		06/23/20 01:00:00
TASK NAME	3B - 9001 ASH HOUSE 71 - WT - TAC HVAC - ASH HOU 582-4496				G - REPAIR
TASK DESCRIPTION	3B - 9001 ASH HOUSE 71 - WT - TAC HVAC - ASH HOU 582-4496				G - REPAIR
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Co __Environmental		_ ed __Trave

SERVICE REQUEST DETAILS

REQUEST ID	CREATED DATE/TIME
2988973	06/22/2022 12:05:50

FACILITY PROJECT DETAILS

ASSET DETAILS

WARRANTY DETAILS

WT 11535701

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11535701

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11535701

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11535701**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11535701**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11535701**

Additional Notes: **WT 11535701**

PROCEDURE STEP DETAILS **WT 11535701**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11712846

WORK TASK DE

TASK PRIORITY	Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	AFB - ENVIRONMENTAL L SYSTEMS - SUB - BOS-			**RESPONSIBLE PERSON**	
CUSTOMER ORG	AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	e	**REQUEST CLASS**	HVAC Service	**PRINTED DATE**	Mar 1, 2023, 6:26 PM
EST HOURS		**PLANNED START**	08/08/2022 11:28:07	**PLANNED END**	08/29/2022 11:28:07
TASK NAME	[redacted] U38/39 ASH 71 - WT - HONEYWELL - TURNED OFF DUE TO CHRONIC LEAK ISSUE - REPAIR 622-7846				
TASK DESCRIPTION	[redacted] U38/39 - ASH unit 71 is currently turned off as it has had chronic leak issue and has been turned o nt . we need to get the cause of the leak to be determined and fixed so the unit can be put back in servi us ve all been closed without resolution. 74, 11414069, T5582 , K6575, K6624, K6646, K6695, K6927, K7159, T2810, T5580, T5582, T5583				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coordination Required		__ FD/SFS/COMM/__ Coordination Requ
	__ Digging Permit Required		__Environmental Coordination Required		__Travel/Access Clearance d

SERVICE REQUEST DETAILS WT 11712

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHON
3063110	08/08/2022 11:00:59	LESLIE BROWN	(405) 622-784

FACILITY PROJECT DETAILS WT 117128

ASSET DETAILS WT 117128

WARRANTY DETAILS WT 11712846

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11712846

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11712846

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11712846**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11712846**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11712846**

Additional Notes: **WT 11712846**

PROCEDURE STEP DETAILS **WT 11712846**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TA K

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**ST US**	Closed	TINKER AEROSPACE COMPLEX-9001
		TRAC IG ST US		
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - T HVAC - BOS-BMC			
CUSTOMER ORG	TINKER AFB - 7	90	63G	
TASK TYPE		**SS**	Building Services	Feb 28, 2023, 6:44 PM
EST HOURS		**T**	06/17/2022 10:00:58	06/17/2022 10:00:58
TASK NAME	3A - 9001 & U3		STOP LEAK - Repai	227846 - T5582 - 11414069
TASK DESCRIPTION	WATER LEAKI 17JUN22 10:15 17JUN22 11:00 THAT IS WHY 17JUN22 12:00 17JUN22 12:46 TO THE LEAKI TANNER		POST U38 IN MULT AINTAINED BY HON OFF AND THATS WH ND SCOTT TANNER SE 69 AND VACCUU .5 HOUR LABOR FO	ENCE WT-11414069 AND WO - T5582 ARE DOING ENERGY TESTING AND ASH HOUSE TO CONDENSATE. ER THAT COULD BE CONTRIBUTING ND 0.8 HOUR LABOR FOR SCOTT
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Preca __ Digging Perm		__Multi-Shop Co __Environmental	d __ FD/SFS/COMM/_____ Coordination Required d __ Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11517974

REQUEST ID	DATE/TIME	L NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11517974

ASSET DETAILS

WT 11517974

WARRANTY DETAILS

WT 11517974

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11517974

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11517974

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11517974**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11517974**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11517974**

Additional Notes: **WT 11517974**

PROCEDURE STEP DETAILS **WT 11517974**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11599196

WORK TASK DE			
TASK PRIORITY	**STATUS** Closed **TRACKING STATUS**	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
RESPONSIBLE ORG	ATER AND FUELS LUMB INT - BOS-	**RESPONSIBLE PERSON**	
CUSTOMER ORG	MXW TAC 9000 - 63G		
TASK TYPE	**REQUEST CLASS** Leaks		Mar 1, 2023, 2:54 PM
EST HOURS	**PLANNED START** 07/08/2022 01:00:00		07/08/2022 01:00:00
TASK NAME	R. WHITE HOUSE - WT - PLUMB INT - F - 405-734-7098		R HEATER LEAK 9001-WH-42 - REPAIR -
TASK DESCRIPTION	R. WHITE HOUSE - WT - PLUMB INT - F - 405-734-7098		R HEATER LEAK 9001-WH-42 - REPAIR -
FOREMAN'S NOTES TO CRAFTSMEN	ions Required __Multi-Shop Coo Required __Environmental		__ FD/SFS/COMM/_____ Coordination Required ed __Travel/Access Clearance Required

SERVICE REQU — **WT 11599196**

REQUE	CREATED DATE/TIME	WORK PHONE
30131	07/07/2022 13:11:53	(405) 739-5767

FACILITY PROJ — **WT 11599196**

ASSET DETAILS — **WT 11599196**

WARRANTY DET — **WT 11599196**

ID	EAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11599196**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11599196**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11599196**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11599196**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11599196**

Additional Notes: **WT 11599196**

PROCEDURE STEP DETAILS **WT 11599196**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11441231

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Leaks	**PRINTED DATE**	Mar 1, 2023, 2:01
EST HOURS		**PLANNED START**	06/02/2022 11:16:32	**PLANNED END**	06/02/2022 11:16:32
TASK NAME	9001 POST V53 - WT - INTPLUMB - WATER FILTER SYSTEM LEAKING UNDER SINK - REPAIR 582-9576				
TASK DESCRIPTION	OCCUPANT TURNED WATER TO SINK OFF & PUT PIG MAT DOWN				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coordination Required		__ FD/SFS/C Coordina
	__ Digging Permit Required		__Environmental Coordination Required		__Travel/Access d

SERVICE REQUEST DETAILS

REQUEST ID	CREATED DATE/TIME	FULL NAME	WO

FACILITY PROJECT DETAILS

ASSET DETAILS

WARRANTY DETAILS

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11441231

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11441231

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11441231**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11441231**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11441231**

Additional Notes: **WT 11441231**

PROCEDURE STEP DETAILS **WT 11441231**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11460544

WORK TASK D					
TASK PRIORITY	ium	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	AFB - SPEC MX TM - TAC BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	Mar 1, 2023, 2:25 PM
EST HOURS		**PLANNED START**	06/07/2022 09:49:42	**PLANNED END**	06/07/2022 09:49:42
TASK NAME	1 POSTS W35/X35 - WT - F/U 11459773 TAC HVAC - DUCT LEAKING ONTO COMPUTERS - REPAIR 582-4196 - STORM				
TASK DESCRIPTION	022 0940 ROWLAND NOTES: NEED TO TRANSFER TO HVAC - THE LEAK IS COMING OUT BY THE POSSIBLY THE DUCT IS RUSTED OUT - HUNG A TARP TO CONTAIN THE LEAK. LEAK IS NOT HEA				
FOREMAN'S NOTES TO CRAFTSMEN	ty Precautions Required	__Multi-Shop Coordination Required		__ FD/SFS/COMM/_____ Coordination Require	
	__ Digging Permit Required	__Environmental Coordination Required		__Travel/Access Clearance R	

SERVICE REQUEST DETAILS — WT 1146054

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — WT 1146054

ASSET DETAILS — WT 1146054

WARRANTY DETAILS — WT 11460544

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11460544

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ — WT 11460544

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11460544**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11460544**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11460544**

Additional Notes: **WT 11460544**

PROCEDURE STEP DETAILS **WT 11460544**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11697701

WORK TASK D					
TASK PRIORITY	w Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	R AFB - WATER AND FUELS M MX - PLUMB INT - BOS-			**RESPONSIBLE PERSON**	
CUSTOMER ORG	R AFB - 72 CES				
TASK TYPE	tive	**REQUEST CLASS**	Leaks	E	Mar 1, 2023, 6:11 PM
EST HOURS		**PLANNED START**	08/04/2022 01:00:00		08/04/2022 01:00:00
TASK NAME	01 POST W-43 - WT- PLUMB INT - F/U 11403984 - 582-4496 - SR2953036				KING FROM PIPE - repair
TASK DESCRIPTION	01 POST W-43 - WT- PLUMB INT -F/U 11403984 ERS WENT OUT AND CONFIRMED NOT ROOF I				KING FROM PIPE
FOREMAN'S NOTES TO CRAFTSMEN	fety Precautions Required __ Digging Permit Required	__Multi-Shop Co __Environmenta		ed	__ FD/SFS/COMM/ Coordination R __ Travel/Access Cleara ired

SERVICE REQUEST DETAILS — WT 116

REQUEST ID	CREATED DATE/TIME	WORK PH
2953036	06/01/2022 10:25:33	405-582-4

FACILITY PROJECT DETAILS — WT 11697701

ASSET DETAILS — WT 11697701

WARRANTY DETAILS — WT 11697701

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11697701

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11697701**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11697701**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11697701**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11697701**

Additional Notes: **WT 11697701**

PROCEDURE STEP DETAILS **WT 11697701**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11403984

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	ACE
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Roof Leak	**PRINTED DATE**	M
EST HOURS		**PLANNED START**	05/24/2022 11:28:09	**PLANNED END**	
TASK NAME	3B - 9001 POST W43 - WT - TAC STRUC - STORM DRAIN LEAKING - REPAIR -				-4105
TASK DESCRIPTION	Water leaking from overhead pipe labeled storm drain located in Bldg 9001, Post W questions. Location: Bldg 9001, Tool cribe cage Post W43. -SENT VIA EMAIL				n at 582-4105 for
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordination Required __Environmental Coordination Required	_ F __Trave	/_____ Required rance Required

SERVICE REQUEST DETAILS 1403984

REQUEST ID	CREATED DATE/TIME	FULL NAME	PHONE

FACILITY PROJECT DETAILS 1403984

ASSET DETAILS 1403984

WARRANTY DETAILS WT 11403984

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11403984

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ WT 11403984

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11403984**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11403984**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11403984**

Additional Notes: **WT 11403984**

PROCEDURE STEP DETAILS **WT 11403984**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Open Work Tasks - CUI/SP-FNC

02/23/2023 13:06:59

Task ID	Task Priority	Task Name	Work Classification
11352627	3C - Low Sustain	3C - 9001 CC44 - WT - IntPlumb - Clogged floor drain - Repair - [redacted] - SR2921199	Repair
11354226	3C - Low Sustain	REJECT - 9001 - CHILL WATER LEAK	Repair
11363640	3B - Medium Sustain	3B - 9001 POST CC44 - WT - INT PLUMB - CLOGGED DRAIN - Repair - [redacted] - 405-582-4196 - SR#2925946	Repair
11363650	3B - Medium Sustain	3B - 9001 Post BB55/CC56 South - WT - PLUMB INT- Domestic Water Line leaking - Repair - [redacted] 582-4496 - SR#2925951	Repair
11363656	3B - Medium Sustain	3B - 9001 Roof - WT - TAC HVAC - Reconnect condenser drain piping - Repair - [redacted] 582-4496 - SR#2925957	Repair
11363806	1-Emergency	1 - 9001 Post S/T-44 - WT - INT PLUMB - Leak flooding area - Repair - IWIMS# - Requestor - Phone - SR# - Delay Status - UID	Repair
11364653	3A - High Sustain	C/O - 3A - 9001 Post S46-1 - WT - MACHINE MAINT - Overhead door won't close - Repair - [redacted] - 405-323-0319	Repair
11364775	3B - Medium Sustain	3B - 9001 POST V44 - WT - INTPLUMB - LEAK FROM SEWER PIPE - Repair - T5482 - [redacted] K - 405-736-3801	Repair
11364831	3B - Medium Sustain	3B - 9001 POST M21 - WT - TAC STRUC - ROOF LEAK - Repair - T5995 - [redacted] - 582-4105	Repair
11364832	3B - Medium Sustain	3B - 9001 POST Q20 - WT - TAC STRUC - ROOF LEAK - Repair - T5996 - [redacted] - 582-4105	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11364834	3B - Medium Sustain	3B - 9001 POST X25 - WT - TAC STRUC - ROOF LEAK - Repair - T6007 - [redacted] - 582-4105	Repair
11364835	3B - Medium Sustain	3B - 9001 POST EE51 - WT - TAC STRUC - ROOF LEAK - Repair - T6245 - [redacted] - 405-582-4105	Repair
11368221	3B - Medium Sustain	3B - 9001 POST F3-F4 - WT - SHEET METAL - CHECK ROOF VENT - Repair - T5193 - [redacted] - 582-4105	Repair
11368232	3B - Medium Sustain	3B - 9001 DOOR S31 - WT - TAC STRUC - REPLACE PIANO HINGE - Repair - T5612 - [redacted] - 582-4105 - 0 - 0	Repair
11368239	3B - Medium Sustain	3B - 9001 L62 - WT - INTPLUMB - STOPPED UP DRAIN ON ROOF - Repair - T5965 - [redacted] - 582-4497 - 0 - 0	Repair
11368252	3B - Medium Sustain	3B - 9001 POSTS P21, P22 - WT - TAC STRUC- ROOF LEAKS AT POSTS P21, P22 - SENT VIA EMAIL - Repair - T5994 - [redacted] - 582-4105 - 0 - 0	Repair
11368259	3B - Medium Sustain	3B - 9001 POST H19 - WT - TAC STRUC- ROOF LEAKS AT POST H19 - Repair - T5998 - [redacted] - 582-4105 - 0 - 0	Repair
11368275	3B - Medium Sustain	3B - 9001 B52 2S17 - WT - TAC STRUC - ROOF LEAK 2ND FLOOR, CURRENTLY CONTAINED - Repair - T6111 - [redacted] - 623-0072 - 0 - 0	Repair
11369333	4A - High Enhance	4A - 9001 Mezz 3 Post C54 - WT - OPS PLAN - ISWP 24100 Replace 3 existing water fountains - [redacted] - 582-1118 CSAG-265 MAD21-095	Repair
11369525	3B - Medium Sustain	3B - 9001 SW MECH ROOM - WT - LOCK - LOCK MECHANISM IS NOT WORKING - REPAIR - [redacted] 801-971-7286 - SR#2928189	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11369807	4A - High Enhance	4A - 9001 Post 2W-43 - WT - ENG EVAL - 25778 Assessment to determine design deficiencies - [redacted] - 582-4340	Repair
11372220	3B - Medium Sustain	3b - 9001 - room 186 - lock - lock isn't opening the door - [redacted] - 405-623-0072	Repair
11372288	3C - Low Sustain	3C - 9001 POST DD49 - WT - LOCK - INSTALL 4 CYPHER LOCKS - Repair - [redacted] - 582-4196	Repair
11372350	3B - Medium Sustain	3B - 9001 ASH HOUSE 76- WT - TAC HVAC - CLEAN CONDENSATE PAN IN ASH HOUSE 76 - Repair - [redacted] - 5824966	Repair
11372728	3B - Medium Sustain	3B - 9001 POST A32 - WT - LOCK - NEED EXTRA KEYS - REPAIR - [redacted] 323-0319	Repair
11372813	3B - Medium Sustain	3B - 9001 POST B7 - WT - TAC STRUC - ROOF LEAK WHEN RAINING - REPAIR - [redacted] 323-0319 - SR#2928929	Repair
11372818	3B - Medium Sustain	3B - 9001 POST D8 - WT - TAC STRUC - ROOF LEAKS WHEN RAINING - REPAIR - [redacted] 323-0319 - SR#2929836	Repair
11372970	3B - Medium Sustain	3B - 9001 POST BB24 - WT - TAC HVAC - ASH HOUSE 76 LEAK-REPAIR - [redacted] 582-4105	Repair
11373019	3B - Medium Sustain	3B - 9001 POST C69 - WT - ELEC INT - EMERGENCY LIGHT INOP - REPAIR - [redacted] 323-0319 - SR#2929976	Repair
11373029	3B - Medium Sustain	3B - 9001 POST G69 - WT - ELEC INT - EMERGENCY LIGHT INOP - REPAIR - [redacted] 323-0319 - SR#2929980	Repair
11373032	3B - Medium Sustain	3B - 9001 POST 2G70 - WT - ELEC INT - EMERGENCY LIGHT INOP - REPAIR - [redacted] 323-0319 - SR#2929982	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11373067	3B - Medium Sustain	3B - 9001 DOORS S32 - WT - ELEC INT - EMERGENCY EXIT LIGHT INOP - REPAIR - [redacted] 323-0319	Repair
11373078	3B - Medium Sustain	3B - 9001 A32 TRIPLE DOORS - WT - ELEC INT - EMERGENCY EXIT LIGHT INOP - REPAIR - [redacted] 323-0319	Repair
11373089	3B - Medium Sustain	3B - 9001 POST A32 - WT - ELEC INT - NO POWER TO EMERGENCY LIGHTING - REPAIR - [redacted] 323-0319	Repair
11373189	3B - Medium Sustain	3B - 9001 POST BB23 - WT - TAC HVAC - ASH HOUSE LEAKING - REPAIR - [redacted] 323-0319	Repair
11373324	3B - Medium Sustain	3B - 9001 POST BB26 - WT - TAC HVAC - ASH HOUSE 77 LEAK- REPAIR - [redacted] 582-4105	Repair
11373380	3B - Medium Sustain	3B - 9001 POST A31 - WT - TAC ALARMS - HANDICAP DOOR NEEDS REPAIRED - Repair - [redacted] - 5824496	Repair
11373452	3B - Medium Sustain	3B - 9306 MAU-1 - WT - TAC HVAC - REPLACE MOTOR AT MAU1 - Repair - [redacted] - 5824496 MAU1	Repair
11373766	3B - Medium Sustain	3B - 9001 & DD32/DD33 - WT - TAC HVAC - STOP BLACK POWDER - Repair - [redacted] - 405-739-5615	Repair
11375109	3B - Medium Sustain	3B - 9001 POST 2T41 - WT - HONEYWELL - REPAIR INOP LIGHTS - Repair - [redacted] - 5824105 - HONEY	Repair
11375602	3B - Medium Sustain	9001-WT- B52 2S17-WT-SHEET METAL-INSTALL UNIT METAL AROUND BOTTOM OF ASH HOUSE-[redacted]	Repair
11376770	3A - High Sustain	3A - 9001 Post 2X42 - WT - MOLD - DRTC - Check HVAC system & diffuser for mold - Repair - T6102 - [redacted] - 405-582-4105 - MOLD	Services

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11378427	3B - Medium Sustain	3B - 9001 POST 2D51C - WT - INT ELEC - DISABLE SURGE PROTECTOR - Repair - [redacted] - 7343142 - SR#2922411	Repair
11378494	3B - Medium Sustain	3B - 9001 POSTM45 - WT - PLUMB INT - WATER ON FLOOR - Repair - [redacted] - 7363547	Repair
11380744	3B - Medium Sustain	3B - 9001 POST W43 - WT - TAC STRUC - FIRE DOORS DO NOT CLOSE PROPERLY - REPAIR - [redacted] 323-0319	Repair
11381114	3B - Medium Sustain	3B - 9001 POST G38 BREAKROOM - WT - ELEC INT - MOTION SENSOR DAMAGED - REPAIR - [redacted] 582-4105	Repair
11381137	3B - Medium Sustain	3B - 9001 POST 2T41 - WT - ELEC INT - BREAKER BOX NEEDS BLANK PUNCH OUT PLATE - REPAIR - [redacted] 582-4105 - 9001-PNL-412	Repair
11381498	3A - High Sustain	3A - 9001 POST B51 MENS RR - WT - INTPLUMB - TOILET OVERFLOWED & CLOGGED - Repair - [redacted]	Repair
11383685	3A - High Sustain	3A - 9001 Mezz 3 Womens restroom - WT - Intplumb - Sink is running nonstop - Repair - [redacted] - 736-2705	Repair
11384047	3B - Medium Sustain	3B - 9001 POST B55 - WT - TAC PIPE - WATER LEAK - Repair - IWIMS#T5879 - [redacted] - 5824496 - SR#2934794 - REF#T5879	Repair
11384059	3B - Medium Sustain	DEFAULT - Work Task Template - Corrective Maintenance-Leaks	Repair
11384417	3A - High Sustain	3A - 9001 POST C20-D20 - WT - INT PLUMB - FAUCET NOT TURNING OFF - Repair - [redacted] - 4139373	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11390251	3B - Medium Sustain	3B - 9001 POST248-259 - WT - INT PLUMB - REPAIR HOLE/CAP IN FLOOR - Repair - [redacted] - 4139373	Repair
11390672	3A - High Sustain	3A - 9001 POST V44 - WT - INT PLUMB - BATHROOM BACKING UP - Repair - [redacted] - 622-7846	Repair
11391031	3B - Medium Sustain	3B - 9001 JANITORS CLOSETS UPSTAIRS - WT - TAC STRUC - SEAL AROUND FLOOR DRAINS - REPAIR - [redacted] - 622-7839	Repair
11391101	3B - Medium Sustain	3B - 9001 POST G-39 - WT - INTPLUMB - HANDLE BROKEN HANDICAP TOILET - Repair - [redacted] - 582-4105	Repair
11391827	3B - Medium Sustain	3B - 9001 POST 2W43 MENS RR - WT - INT PLUMB - URINAL REPAIR - Repair - [redacted] - 6227846	Repair
11391835	3B - Medium Sustain	3B - 9001 POST 2W43 WOMENS RR - WT - INT PLUMB - TOILET REPAIR - Repair - [redacted] - 6227846	Repair
11391853	3B - Medium Sustain	3B - 9001 POST 2W43 MENS RR - WT - INT PLUMB - MOP SINK FAUCET - Repair - [redacted] - 6227846	Repair
11392442	3B - Medium Sustain	3B - 9001 POST W-44 - WT - INT PLUMB - CAMERA 4 INCH SEWER LINE - Repair - [redacted] - 734-7223	Repair
11395742	3B - Medium Sustain	3B - 9001 KC46 - WT - TAC HVAC - FCU1-2 READING -58 ON GRAPHICS - REPAIR - [redacted] 200-3131	Repair
11395761	3B - Medium Sustain	3B - 9001 - WT - LOCK - NEED 3 CORES INSTALLED - REPAIR - [redacted] 582-4105	Repair
11396951	3B - Medium Sustain	3B - 9001 & POST F-6 - WT - TAC ROOF - FIX LEAK - Repair - [redacted] - 582-4105	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11397359	3B - Medium Sustain	3B - 9001 POST F12 - WT - HONEYWELL - LAB TEMP IS OUT OF TOLERANCE/AHU-2 - Repair - [redacted] - 622-7846	Repair
11397851	3B - Medium Sustain	3B - 9001 POST 2G39 - WT - INT PLUMB - TOILET CLOG - Repair - [redacted] - 8337049	Repair
11398992	4A - High Enhance	4A - 9001 Mezz 3 R101N - CBR - Request duct be added to CRAC units - [redacted] - 582-5516	Repair
11399152	3B - Medium Sustain	3B - 9001 POST C69 - WT - ELEC INT - F/U 11373019 EMERGENCY LIGHT INOP - REPAIR - [redacted] - 405-734-3142	Repair
11399240	3B - Medium Sustain	3B - 9001 POST G69 - WT - ELEC INT - F/U 11373029 EMERGENCY LIGHT INOP - REPAIR - [redacted] - 405-734-3142	Repair
11401358	3B - Medium Sustain	3B - 9001 - Posts T47 to T52 & Q47 to Q52 - WT - Honeywell - Lights are out - repair - [redacted] - 582-4105	Repair
11401585	3B - Medium Sustain	3B - 9001 POSTS Q48-Q52 - WT - HONEYWELL - OVERHEAD LIGHTS OUT - Repair - [redacted] - 855-3045 -	Repair
11401599	3A - High Sustain	3A - 9001 BETWEEN POSTS L51 AND L52 - WT - TAC STRUC - ROOF LEAKING PRETTY BAD - Repair - [redacted] - 550-9580	Repair
11401963	3B - Medium Sustain	3B - 9001 POST S34 - WT - INTPLUMB - STORM DRAIN LEAK - REPAIR - [redacted] - 582-4495	Repair
11402232	3B - Medium Sustain	3B - 9001 BETWEEN POSTS L51 AND L52 - WT - TAC STRUC - F/U 11401599 ROOF LEAKING PRETTY BAD - Repair - [redacted] - 550-9580	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11403367	3B - Medium Sustain	3B - 9001 ROOM 140 S ADMIN - WT - ELEC INT - NO TAG ON LOCKED OUT BREAKER - REPAIR - [redacted] 736-8784	Repair
11403540	3B - Medium Sustain	3B - 9001 & MEZZ 2 2T43 CUBE #86 - WT - TAC ROOF - FIX ROOF LEAK - Repair - [redacted] - 5821118 - STORM	Repair
11403613	3A - High Sustain	3A - 9001 POST AA40 - WT - TAC ROOF - ROOF LEAKING ONTO ELECTRICAL BOX ON POLE - Repair - [redacted] - 736-2207	Repair
11403652	3B - Medium Sustain	3B - 9001 5FT EAST OF POST AA38 - WT - TAC ROOF - ROOF LEAK - Repair - [redacted] - 736-2207	Repair
11403676	3B - Medium Sustain	3B - 9001 BETWEEN POSTS BB40 AND CC40 - WT - TAC ROOF - ROOF LEAK - Repair - [redacted] - 736-2207	Repair
11403902	3B - Medium Sustain	3B - 9001 POST 2T41 - WT - TAC STRUC - CEILING TILE BROKEN FROM ROOF LEAK - REPAIR - [redacted] 582-4105	Repair
11403984	3B - Medium Sustain	3B - 9001 POST W43 - WT - TAC STRUC - STORM DRAIN LEAKING - REPAIR - [redacted] 582-4105	Repair
11403993	3B - Medium Sustain	3B - 9001 POST L23 BREAKROOM - WT - TAC STRUC - ROOF LEAK INTO BREAKROOM - REPAIR - [redacted] 582-4105	Repair
11404063	3B - Medium Sustain	3B - 9001 POST 2T41 - WT - TAC STRUC - ROOF LEAK THROUGH CEILING TILE - REPAIR - [redacted] 582-4105	Repair
11404075	3B - Medium Sustain	3B - 9001 POST S30 - WT - TAC STRUC - ROOF LEAK - REPAIR - [redacted] 582-4105	Repair
11404764	3B - Medium Sustain	3B- 9001 POST H67 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 6227846 - STORM	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11404805	3B - Medium Sustain	3B- 9001 POST Q38 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 6227846 - STORM	Repair
11404883	3B - Medium Sustain	3B - 9001 POST AA40 - WT - TAC ROOF - FOLLOW UP 11403613 REPAIR ROOF LEAK - REPAIR - [redacted] 736-2207	Repair
11405762	3B - Medium Sustain	3B- 9001 & POST M56 - WT - TAC STRUC - FIX ROOF LEAK - Repair - [redacted] - 2004344	Repair
11406098	3C - Low Sustain	3C - 9001 POST C-35 - WT - INTPLUMB - LEAKING WATER OUTLET - REPAIR - K7919 - [redacted] - 405-274-2656	Repair
11409152	3B - Medium Sustain	3B - 9001 ROOM 148 - TAC STRUC - WT - ROOF LEAK - Repair - [redacted] - 4922496 - STORM	Repair
11411058	3B - Medium Sustain	3B - 9001 POST CC44 - WT - PLUMB INT-F/U T6008- ROOF DRAIN CLOGGED - REPAIR - [redacted] - 5824496 - SR#2945381	Repair
11411081	3B - Medium Sustain	3B - 9001 POST Q58 - WT - INT PLUMB - ROOF DRAIN CLOGGED - REPAIR - [redacted] - 5824496 - SR#2945388	Repair
11411586	3B - Medium Sustain	3B - 9001 - WT - TAC HVAC CONT - REPAIR VAV 4107A - Repair - [redacted] - 582-4497 - VAV 4107A	Repair
11413063	3C - Low Sustain	3C - 9001 ASH HOUSE 33 - WT - TAC HVAC - REPLACE DRIVE KIT FOR BLOWER - REPAIR - T3954 - [redacted] - 582-4497 - - 9001-ASH-33	Repair
11413064	3C - Low Sustain	3C - 9001 MEZZ 3 CRAC 2 - WT - TAC HVAC - COMPRESSOR IS SHORTED THE GROUND - REPAIR - T0214 - [redacted] - 200-3131 - - 9001-CRAC-2	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11413412	3C - Low Sustain	3C - 9001 E-59 - WT - TAC HVAC - FF/TROUBLESHOOT UPPER NORTH NAC PANEL - REPAIR - T2049 - [redacted] - 582-4496 - - FA-1385A	Repair
11413476	3C - Low Sustain	3C - 9001 POST 2S-17-ASH 23 - WT - SHEET - METAL SKIRTING NEEDED/ROOF LEAK - REPAIR - T2735 - [redacted] - 582-1118 - -	Repair
11413500	3C - Low Sustain	3C - 9001 ASH HOUSE 36 - WT - TAC HVAC - BAD BLOWER BEARINGS - REPAIR - T2949 - [redacted] - 582-4496 - - 9001-AHU-36	Repair
11413671	3C - Low Sustain	3C - 9001 POST 2T41 - WT - TAC STRUC - REPLACE 10 WATER-STAINED CEILING TILES - REPAIR - T5088 - [redacted] - 582-4105 - -	Repair
11413683	3C - Low Sustain	3C - 9001 POST EE34 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5128 - [redacted] - 582-4497 - -	Repair
11413693	3C - Low Sustain	3C - 9001 - Post A32/33 Women's - WT - Tac Struc - Replace ceiling tile - Repair - T5659 - [redacted] - 622-7846	Repair
11413794	3C - Low Sustain	3C - 9001 Post DD56 - WT - Tac Struc - Rain water getting in through the doors, causing flooding in the shop - repair - T5773 - [redacted] - 582-4196	Repair
11413843	3C - Low Sustain	3C - 9001 Post A33, WRR NW - WT - Tac Struc - Check for leaks & replace stained / missing ceiling tile - repair - T5824 - [redacted] - 622-7846	Repair
11413850	3C - Low Sustain	3C - 9001 POST A33 CMXG FACILITY - WT - TAC STRUC - CHECK FOR LEAKS & REPLACE STAINED/MISSING CEILING TILES - REPAIR - T5825 - [redacted] - 622-7846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11413851	3C - Low Sustain	3C - 9001 POST A33 S CORNER OFC - WT - TAC STRUC - CHECK FOR LEAKS & REPLACE STAINED/MISSING CEILING TILES - REPAIR - T5826 - [redacted] - 622-7846	Repair
11413853	3C - Low Sustain	3C - 9001 POST A33 CENTER ADMIN - WT - TAC STRUC - CHECK FOR LEAKS & REPLACE STAINED/MISSING CEILING TILES - REPAIR - T5827 - [redacted] - 622-7846	Repair
11413873	3C - Low Sustain	3C - 9001 POST X40 - WT - TAC STRUC - BIG CHUNK OF CONCRETE MISSING - REPAIR - T5533 - [redacted] - 582-4196 - -	Repair
11413908	3C - Low Sustain	3C - 9001 POST BB29 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5539 - [redacted] - 582-4196 - STORM -	Repair
11413909	3C - Low Sustain	3C - 9001 POST C10 - WT - INTPLUMB - FLOOR DRAINS OVERFLOW WHEN JANITORS POUR THEIR MOP BUCKETS - REPAIR - T6112 - [redacted] - 622-7846 - -	Repair
11413912	3C - Low Sustain	3C - 9001 POST BB31 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5540 - [redacted] - 582-4196 - STORM -	Repair
11413913	3C - Low Sustain	3C - 9001 POST BB39 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5542 - [redacted] - 582-4196 - STORM -	Repair
11413916	3B - Medium Sustain	3B - 9001 POST BB44 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5543 - [redacted] - 582-4196 - STORM	Repair
11413918	3C - Low Sustain	3C - 9001 POST DD52 - WT - INTPLUMB - TOILET FLUSH VALVE LEAKING IN THE WOMENS RR - REPAIR - T6114 - [redacted] - 622-7846 - -	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11413923	3C - Low Sustain	3C - 9001 POST CC30 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5545 - [redacted] - 582-4196 - STORM -	Repair
11413925	3C - Low Sustain	3C - 9001 POST CC48 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5546 - [redacted] - 582-4196 - STORM -	Repair
11413927	3C - Low Sustain	3C - 9001 POST CC50 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5547 - [redacted] - 582-4196 - STORM -	Repair
11413941	3C - Low Sustain	3C - 9001 POST CC53 - WT - TAC STRUC - (08-16-22/09-16-2022?) RAM COLD TAR ON ORDER ROOF LEAK - REPAIR - T5549 - [redacted] - 582-4196 - STORM -	Repair
11413943	3C - Low Sustain	3C - 9001 POST DD27 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5550 - [redacted] - 582-4196 - STORM -	Repair
11413949	3C - Low Sustain	3C - 9001 POST DD30 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5553 - [redacted] - 582-4196 - STORM -	Repair
11413950	3C - Low Sustain	3C - 9001 POST M38 - WT - TAC STRUC - INSIDE SINK BASIN CABINET IS WATER LOGGED & BROKEN - REPAIR - T6205 - [redacted] - 582-4105 - -	Repair
11413962	3C - Low Sustain	3C - 9001 POST DD33 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5559 - [redacted] - 582-4196 - STORM -	Repair
11413965	3C - Low Sustain	3C - 9001 POST EE28 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5564 - [redacted] - 582-4196 - STORM -	Repair
11413968	3C - Low Sustain	3C - 9001 POST EE29 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5565 - [redacted] - 582-4196 - STORM -	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11413969	3C - Low Sustain	3C - 9001 POST EE20 - WT - TAC STRUC - STEEL BOLLARD HAS BEEN KNOCKED OVER AND NEEDS TO BE RE-ANCHORED - REPAIR - T6302 - [redacted] - 582-4105 -	Repair
11413978	3C - Low Sustain	3C - 9001 POST EE35 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5570 - [redacted] - 582-4196 - STORM -	Repair
11413980	3C - Low Sustain	3C - 9001 POST EE44 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5571 - [redacted] - 582-4196 - STORM -	Repair
11413987	3C - Low Sustain	3C - 9001 POST S34 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5572 - [redacted] - 582-4196 - STORM -	Repair
11414021	3C - Low Sustain	3C - 9001 - WT - Lock - Need keys made - Repair - [redacted] - 582-4105	Repair
11414031	3C - Low Sustain	3C - 9001 POST S44 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5574 - [redacted] - 582-4196 - STORM -	Repair
11414049	3B - Medium Sustain	3B - 9001 POST T33 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5579 - [redacted] - 582-4196 - STORM	Repair
11414060	3C - Low Sustain	3C - 9001 POST U37 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5580 - [redacted] - 582-4196 - STORM -	Repair
11414069	3B - Medium Sustain	3B - 9001 POST U38 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5582 - [redacted] - 582-4196 - STORM -	Repair
11414073	3C - Low Sustain	3C - 9001 POST U39 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5583 - [redacted] - 582-4196 - STORM -	Repair
11414078	3C - Low Sustain	3C - 9001 POST U47 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5584 - [redacted] - 582-4196 - STORM -	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11414081	3C - Low Sustain	3C - 9001 POST U49 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5585 - [redacted] - 582-4196 - STORM -	Repair
11414085	3C - Low Sustain	3C - 9001 POST V38 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5586 - [redacted] - 582-4196 - STORM -	Repair
11414094	3C - Low Sustain	3C - 9001 POST W48 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5587 - [redacted] - 582-4196 - STORM -	Repair
11414099	3C - Low Sustain	3C - 9001 POST X32 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5588 - [redacted] - 582-4196 - STORM -	Repair
11414102	3C - Low Sustain	3C - 9001 POST X47 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5589 - [redacted] - 582-4196 - STORM -	Repair
11414106	3C - Low Sustain	3C - 9001 POST X48 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5590 - [redacted] - 582-4196 - STORM -	Repair
11414111	3C - Low Sustain	3C - 9001 POST Y32 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5591 - [redacted] - 582-4196 - STORM -	Repair
11414116	3C - Low Sustain	3C - 9001 POST Y39 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5592 - [redacted] - 582-4196 - STORM -	Repair
11414124	3C - Low Sustain	3C - 9001 POST Y47 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5593 - [redacted] - 582-4196 - STORM -	Repair
11414147	3C - Low Sustain	3C - 9001 POST E34 - WT - TAC STRUC - ADJUST DOOR CLOSER - REPAIR - T5623 - [redacted] - 582-4105	Repair
11414760	3B - Medium Sustain	3B - 9001 POST M59 AND 60 - WT - TAC STRUC - ROOF LEAK - REPAIR - [redacted] - 2197894 - STORM	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11415653	4A - High Enhance	4A - 9001 MULTI - WT - ENG EVAL - Request CE perform roof penetrations for duct work - [redacted] - 582-5091	Repair
11415742	3B - Medium Sustain	3B - 9001 POST F3-F4 - WT - WELD - REF 11368221 CHECK ROOF VENT - REPAIR - T5193 - [redacted] 582-4105 - SR# 2946843	Repair
11417823	3B - Medium Sustain	3B - 9001 CC56 TO EE56 - WT - TAC STRUC - WATER COMING THROUGH THE FLOOR - REPAIR - [redacted] 622-7846	Repair
11417972	3C - Low Sustain	3C - 9001 POST 21.59 WHITE HOUSE - WT - TAC STRUC - RE-GLUE CARPET TILES TO FLOOR - REPAIR - K9179 - [redacted] - 855-300	Repair
11417976	3C - Low Sustain	3C - 9001 POST H-70 - WT - INTPLUMB - CLEAN OUT SUMP PUMP - REPAIR - R6477 - [redacted] - 582-4340	Repair
11418095	3C - Low Sustain	3C - 9001 POST E-59 - WT - TAC ALARM - FF/TROUBLESHOOT LOWER S NAC PANEL - REPAIR - T2051 - [redacted] - 582-4496 - - FA-1385A	Repair
11418119	3C - Low Sustain	3C - 9001 ROOF - WT - TAC STRUC - REPAIR ROOF SUCTION 4 FLR WITH RAM COLD TAR - REPAIR - T2144 - [redacted] - 582-4496 - - 9001-RF-4	Repair
11418578	3C - Low Sustain	3C - 9001 AC 5A S ADMIN - WT - TAC HVAC - FF/OUTSIDE AIR DAMPER INOP - REPAIR - T3010 - [redacted] - 582-4495 - -	Repair
11418579	3C - Low Sustain	3C - 9001 AC 5A S ADMIN - WT - TAC CONTROLS - FF/OUTSIDE AIR DAMPER INOP - REPAIR - T3010 - [redacted] - 582-4495 - -	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11418605	3C - Low Sustain	3C - 9001 POST F13 CATWALK - WT - TAC ALARM - FF/REPLACE FA BATTERIES - REPAIR - T3131 - [redacted] - 582-4497 - - FA-1387	Repair
11418663	3C - Low Sustain	3C - 9001 S ADMIN - WT - TAC HVAC - VAV4107 INOP - REPAIR - T3555 - [redacted] - 405-582-4495 - -	Repair
11418667	3C - Low Sustain	3C - 9001 S ADMIN - WT - TAC CONTROLS - VAV4107 INOP - REPAIR - T3555 - [redacted] - 405-582-4495 - -	Repair
11418673	3C - Low Sustain	3C - 9001 S ADMIN - WT - TAC HVAC - VAV 5127 INOP - REPAIR - T3614 - [redacted] - 582-4495 - -	Repair
11418676	3C - Low Sustain	3C - 9001 S ADMIN - WT - TAC CONTROLS - VAV 5127 INOP - REPAIR - T3614 - [redacted] - 582-4495 - -	Repair
11418684	3B - Medium Sustain	3B - 9001 POST EE-44 - WT - MACHINE MAINT - HIGH SPEED OH DOOR HIT & INOP - REPAIR - T1774 - [redacted] - 582-4340 - - N/44OH	Repair
11418939	3C - Low Sustain	3C - 9001 - WT - TAC HVAC - REPLACE DRIVE KIT FOR BLOWER - REPAIR - T3831 - [redacted] - 582-4497 - - ASH-36	Repair
11418997	3C - Low Sustain	3C - 9001 KC46, HUMIDIFIER 1 - WT - TAC HVAC - TEMP SENSOR DEFECT ALARM - REPAIR - T4174 - [redacted] - 736-7554 - -	Repair
11418998	3C - Low Sustain	3C - 9001 KC46, HUMIDIFIER 1 - WT - TAC CONTROLS - TEMP SENSOR DEFECT ALARM - REPAIR - T4174 - [redacted] - 736-7554 - -	Repair
11419108	3C - Low Sustain	3C - 9001 S ADMIN, RM 115 - WT - INTPLUMB - MIXING VALVE HAS SLOW LEAK - REPAIR - T4591 - [redacted] - 405-200-3131 - -	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11419122	3C - Low Sustain	3C - 9001 - WT - TAC HVAC - REPLACE BLOWER BEARINGS - REPAIR - T4648 - [redacted] - 582-4496 - - ASH-33	Repair
11419634	3C - Low Sustain	3C - 9001 MEZZ 3, RM 215 - WT - TAC HVAC - VAV-211 STAYING TOO COLD - REPAIR - T5418 - [redacted] - 405-736-7554	Repair
11419646	3C - Low Sustain	3C - 9001 POST K39 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5472 - [redacted] - 582-4105 - WEATHER -	Repair
11419655	3C - Low Sustain	3C - 9001 POSTS D12, E12 & F12 - WT - TAC STRUC - ROOF LEAK IN COMPOSITE CAGE - REPAIR - T5491 - [redacted] - 582-4105 - - 9001-MAU-1	Repair
11419821	3B - Medium Sustain	3B - 9001 - ENTIRE ROOF - WT - TAC STRUC - REPAIR ROOF SECTION 12 - [redacted] - 582-4496	Repair
11421032	3B - Medium Sustain	3B - 9001 POST Q60 - WT - INT ELEC - EMEGENCY EXIT LIGHT INOP - Repair - [redacted] - 2197894 - STORM	Repair
11421172	3A - High Sustain	3A - 9001 AA30 - WT - TAC HVAC - FIRE DEPT REQUESTING HVAC TO ASSIST - REPAIR - [redacted] 734-7964	Repair
11421189	3A - High Sustain	3A - 9001 AA30 - WT - SPRINK - FIRE DEPT REQUESTING SPRINKLER SHOP TO ASSIST - REPAIR - [redacted] 734-7964	Repair
11421194	3A - High Sustain	3A - 9001 AA30 - WT - TAC ALARM - FIRE DEPT REQUESTING ALARM TO ASSIST - REPAIR - [redacted] 734-7964	Repair
11421233	3C - Low Sustain	3C - 9001 POST X41 - WT - INTPLUMB - WATER DRIPPING FROM CEILING - REPAIR - T4843 - [redacted] - 582-4196 - -	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11421235	3B - Medium Sustain	3B - 9001 POST L32 - WT - INTELEC - WATER HEATER INOP - REPAIR - T4881 - [redacted] - 582-4105 - -	Repair
11421238	3C - Low Sustain	3C - 9001 - WT - TAC HVAC - SEAL UP CONDENSATE PANS - REPAIR - T4968 - [redacted] - 582-4497 - - ASH-72	Repair
11421260	3C - Low Sustain	3C - 9001 SW - WT - DOORELEC - FF/BAD ELEC MOTOR FOR SWING ARM - REPAIR - T5034 - [redacted] - 582-4497 - - EGD-57	Repair
11421270	3C - Low Sustain	3C - 9001 - WT - TAC HVAC - ORDER PAN PADS FOR ASH-1 - REPAIR - T5125 - [redacted] - 582-4497 - - ASH-1	Repair
11421277	3C - Low Sustain	3C - 9001 - WT - TAC HVAC - ORDER PAN PADS FOR ASH-2 - REPAIR - T5126 - [redacted] - 582-4497 - - ASH-2	Repair
11421280	3C - Low Sustain	3C - 9001 TRF RM 3 - WT - TAC ALARM - FF/REPLACE BATTERIES - REPAIR - T5139 - [redacted] - 582-4497 - - FA-292D	Repair
11421282	3C - Low Sustain	3C - 9001 TRF RM 3 - WT - TAC HVAC - FF/REPLACE BATTERIES - REPAIR - T5139 - [redacted] - 582-4497 - - 9001-FA-292D	Repair
11421351	3B - Medium Sustain	3B - 9001 POST Q62 - WT - METAL - OVERHEAD DOOR HIT BY FORKLIFT - Repair - [redacted] - 323-0319	Repair
11421424	3B - Medium Sustain	3B - 9001 ASH HOUSE 78 - WT - TAC HVAC - FOLLOW UP 11421172 TO REPLACE BELT - REPAIR - [redacted] 734-7964	Repair
11421506	3A - High Sustain	C/O - 3A - 9001 North Side by door 4408 - WT - EXTELEC - light pole hit by work truck - Repair - [redacted] 405-734-3737	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11427843	3B - Medium Sustain	3B - 9001 POST Q62 - WT - TAC STRUC - PEDESTRIAN DOOR WILL NOT LATCH CLOSED - REPAIR - [redacted] 622-7846	Repair
11427867	3B - Medium Sustain	3B - 9001 POST Q62 - WT - INT ELEC - EXIT SIGN INOP - REPAIR - [redacted] 622-7846	Repair
11427874	3B - Medium Sustain	3B - 9001 POST S62 - WT - INT ELEC - EXIT SIGN INOP - REPAIR - [redacted] 622-7846	Repair
11429643	3B - Medium Sustain	3B - 9001 D10 - WT - TAC HVAC - FF REPLACE BELTS - REPAIR - [redacted] - 582-4495 - EF11	Repair
11430261	3B - Medium Sustain	3B - 9001 S56 - WT - INT ELEC - EMERGENCY LIGHT INOP - REPAIR - [redacted] - 3237846	Repair
11434267	3C - Low Sustain	3C- 9001 POST Q38 - WT - PLUMB INT - F/U 11404805 DRAIN PIPE LEAK - REPAIR - [redacted] - 6227846 - SR#2952957	Repair
11434312	3B - Medium Sustain	3B- 9001 POST M38 - WT - PLUMB INT - F/U 11413950 DRAIN PIPE LEAK - REPAIR - [redacted] - 6227846 - SR#2952970	Repair
11435811	3B - Medium Sustain	3B - 9001 & MEZZ 2 2T43 CUBE #86 - WT - HONEYWELL - F/U 11403540 - PIPE CHASE UNIT LEAKING - Repair - [redacted] - 582-4496 - SR# 2953494	Repair
11439307	3B - Medium Sustain	3B - 9001 & Location - WT - PAVE - MOVE LIFT - Repair - [redacted] - 5824496	Repair
11439594	3B - Medium Sustain	3B- 9001 & SOUTH ADMIN AREA - WT - TAC STRUC - ADDRESS SINKHOLE - Repair - [redacted] - 7368784	Repair
11439983	3B - Medium Sustain	3B - 9001 KC46 POST B50 - WT - TAC STRUC - DOOR REPAIR - Repair - [redacted] - 7368784	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11440015	3B - Medium Sustain	3B - 9001 AHU - 21 - WT - HONEYWELL - AHU 21 MIXED AIR SENSOR IS BAD AND C/W VALVE IS INOP - REPAIR - [redacted] - 582-4496 - 9001-CNTR-21	Repair
11440062	3B - Medium Sustain	3B - 9001 POST L44 OFFICE - WT - LOCK - REPLACE DOOR KNOB AND SWAP CORE - REPAIR - [redacted] 582-4105	Repair
11440286	3B - Medium Sustain	3B - 9001 EXHAUST FAN BB -27 - WT - TAC HVAC - REPAIR FAN IT IS NOT TURNING ON - REPAIR - [redacted] - 582-4496 - STR#2955402	Repair
11440693	3B - Medium Sustain	3B - 9001 KC46 - WT - TAC ALARM - ALARM PANEL IN COM FAILURE - REPAIR - [redacted] 736-8784	Repair
11440933	3B - Medium Sustain	3B - 9001 POST H69 - WT - INT ELEC - EMERGENCY LIGHT INOP - REPAIR - [redacted] - 6227846	Repair
11441231	3C - Low Sustain	9001 POST V53 - WT - INTPLUMB - WATER FILTER SYSTEM LEAKING UNDER SINK - REPAIR - [redacted] - 582-9576	Repair
11442494	4A - High Enhance	4A - 9001 Various Posts - OP - 54631 - need fire alarm notifications installed - [redacted] - 739-4975	Repair
11442723	4A - High Enhance	4A 9001 Multiple Posts - OP - 24139 13 New Supervisor offices installed by MSXG - [redacted] - 739-4975	Repair
11446694	3B - Medium Sustain	3B - 9001 & POST S30 - WT - TAC STRUC - HANG AED BOX - Repair - [redacted] - 5824105	Repair
11446706	3B - Medium Sustain	3B - 9001 & POST S30 - WT - TAC STRUC - HANG FIRE EXTINGUISHER - Repair - [redacted] - 5824105	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11452934	3B - Medium Sustain	3B - 9001 & POST X-42 - WT - ELEVATOR - FIX DOORS - Repair - [redacted] - 5824105	Repair
11452995	3A - High Sustain	3A - 9001 & G 24 - WT - TAC CONTROL - STOP PIPE LEAK - Repair - [redacted] - 582-4105	Repair
11453540	3B - Medium Sustain	3B - 9001 EGD 54 - WT - TAC STRUC - DAMAGED EXTERIOR DOOR A15 NEEDS REPAIR - REPAIR - [redacted] 622-7846	Repair
11453558	3B - Medium Sustain	3B - 9001 & G 24 - WT -PLUMB INT - STOP PIPE LEAK - Repair - [redacted] - 582-4105	Repair
11453641	3B - Medium Sustain	3B - 9004 EGD 51 - WT - TAC STRUC - EXTERIOR DOOR AT C5 WILL NOT CLOSE ON IT'S OWN - REPAIR - [redacted] 622-7846	Repair
11453664	3B - Medium Sustain	3B - 9001 EGD S31 - WT - TAC STRUC - EXTERIOR DOOR WILL NOT CLOSE - REPAIR - [redacted] 622-7846	Repair
11454728	3B - Medium Sustain	3B - 9001 POST 2J23 - WT - LOCK - LOCK OLD ABANDONED OFFICE SPACES - REPAIR - [redacted] 323-0319	Repair
11455554	3B - Medium Sustain	3B - 9001 POST C10 - WT - INT PLUMB - BREAK ROOM/FOUNTAIN INOP - [redacted] - 3230319	Repair
11456337	2A - Preventive Maintenance	D10151101950 - A - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11456545	3B - Medium Sustain	3B - 9001 POST 2V41 - WT - BAS - TOO HOT - [redacted] - 6227846	Repair
11459446	3B - Medium Sustain	3B - 9001 POST U55 - WT - TAC STRUC - ROOF ACCESS DOOR NOT WORKING - Repair - [redacted] - 323-0319	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11459773	3B - Medium Sustain	3B - 9001 POSTS W35/X35 - WT - TAC STRUC - ROOF LEAKING ONTO COMPUTERS - REPAIR - [redacted] 582-4196 - STORM	Repair
11459962	3B - Medium Sustain	3B - 9001 MEZZ 3 MEN'S RR - WT - INT PLUMB - SINK CONTINUOUSLY RUNNING; SHUT OFF WATER - REPAIR - [redacted] 736-2705	Repair
11460544	3B - Medium Sustain	3B - 9001 POSTS W35/X35 - WT - F/U 11459773 TAC HVAC - DUCT LEAKING ONTO COMPUTERS - REPAIR - [redacted] 582-4196 - STORM	Repair
11462253	3C - Low Sustain	3C - 9001 - WT - TAC ALARMS - REPLACE BATTERIES - REPAIR - [redacted] - 582-4496 - 9001-FA-1386B	Repair
11462309	3C - Low Sustain	3C - 9001 - WT - TAC ALARMS - REPLACE BATTERIES - REPAIR - [redacted] - 582-4496 - 9001-FA-1386C	Repair
11462343	3C - Low Sustain	3C - 9001 - WT - TAC ALARMS - REPLACE BATTERIES - REPAIR - [redacted] - 582-4496 - 9001-FA-1386D	Repair
11462349	3B - Medium Sustain	3B - 9001 - WT - TAC ALARMS - REPLACE BATTERIES - REPAIR - [redacted] - 582-4496 - 9001-FA-1386A	Repair
11462375	3B - Medium Sustain	3B - 9001 POST 2J23 - WT - TAC STRUC - SECURE/INSTALL HASP - REPAIR - [redacted] 323-0319	Repair
11462404	3B - Medium Sustain	3B - 9001 - WT - LOCK -NEED KEYS MADE - REPAIR - [redacted] 323-0319	Repair
11462448	3B - Medium Sustain	3B - 9001 POST X31 - WT - TAC STRUC- ROOF LEAK - REPAIR - [redacted] - 323-0319 - STORM	Repair
11462668	3B - Medium Sustain	3B - 9001 POST H43, J42 - WT - TAC STRUC - ROOF LEAKS - REPAIR - [redacted] - 5824105 - STORM	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11462704	3C - Low Sustain	3C - 9001 PL9001W-1 - WT - PAVE - PARKING LOT RESTRIPED - REPAIR - [redacted] - 5824105	Repair
11469674	3B - Medium Sustain	3B - 9001 POST B7 - WT - PEST - ANT PROBLEM - REPAIR - [redacted] - 5824105	Repair
11470555	3B - Medium Sustain	3B - 9001 POST L59 - WT - LOCK - CHANGE BATTERIES OUT IN 2 CYPHER LOCKS - Repair - [redacted] - 200-4344	Repair
11471288	3B - Medium Sustain	3B - 9001 POST X41 - WT - PLUMB INT - F/U 11421233 WATER DRIPPING FROM CEILING - REPAIR - T4843 - [redacted] - 405-734-7098	Repair
11471748	3B - Medium Sustain	3B - 9001 POST S51 T51 U51 - WT - TAC STRUC - ROOF LEAK/CURRENTLY CONTAINED - Repair - [redacted] - 582-4105	Repair
11472358	3B - Medium Sustain	3B- 9001 & POST G24- WT - TAC STRUC - STOP ROOF LEAK - Repair - [redacted] - 5824105	Repair
11472714	3B - Medium Sustain	3B - 9001 POST 2W41/ROOF - WT - TAC HVAC - F/U 11456545 REPLACE #1 COMPRESSOR ON AHU-3 - Repair - [redacted] - 323-0319	Repair
11473605	3B - Medium Sustain	3B - 9001 POST G24 - WT - PLUMB INT - F/U 11472358 ROOF LEAK COMMING FROM HVAC TIE IN - REPAIR - [redacted] - 405-734-7098	Repair
11475922	3A - High Sustain	3A- 9001 - Post G-63 - 1G70, 2G70 - WT - Mold - DRTC - Check registers for mold - repair - [redacted] - 582-1118 - Emailed User w/ Options 08/10/2022	Services
11476929	3B - Medium Sustain	3B - 9001 POST E68 - WT - LOCK - NEW LOCK CORE NEEDS INSTALLED - REPAIR - [redacted] 622-7846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11477121	3B - Medium Sustain	3B - 9001 POST DD55 - WT - LOCK - INSTALL 4 CYPHER LOCKS - Repair - [redacted] - 582-4196	Repair
11477550	3B - Medium Sustain	3B - 9001 & MENS RR 113- WT - INT PLUMB - UNCLOG URINAL - Repair - [redacted] - 7368784	Repair
11478616	3B - Medium Sustain	3B - 9001 S30 - WT - LOCK - NEED KEY MADE - Repair - [redacted] - 5824105	Repair
11478816	4A - High Enhance	4A - 9001 F31- CBR - Review location of contractor provided foundation - [redacted] - 582-4095	Repair
11479291	3C - Low Sustain	3C - 9001 POSTS W35/X35 - WT - F/U 111460544 TAC STRUCTURES - REPAIR ROOF CURB- REPAIR - [redacted] 582-4196 - STORM	Repair
11479430	3C - Low Sustain	3C - 9001 POST 2J23 OLD UNION HALL F/U 11462375 and 11479430 - WT - LOCK - REQUEST FOR 3 LOCKS - REPAIR - [redacted] -582-4496	Repair
11479553	3C - Low Sustain	3C- 9001 POST S-30 -WT- PLUMB INT - DRAIN PIPE IS LEAKING AT ELBOW F/U FROM 11404075 - REPAIR - [redacted] - 582-4496	Repair
11479573	3B - Medium Sustain	3B - 9001 L23 - WT - TAC HVAC - F/U 11403993 ASH HOUSE 32 IS LEAKING FROM 3 DIFFERENT SPOTS - REPAIR- [redacted] - 582-4496	Repair
11481253	3B - Medium Sustain	3B - 9001 ASH HOUSE 32 F/U 11403993 - WT - TAC HVAC - CONDENSATION LEAK - REPAIR - [redacted] 582-4496	Repair
11481557	3B - Medium Sustain	3B - 9001 & POST 2L 22 - WT - INT PLUMB - CLEAR FLOOR DRAIN - Repair - [redacted] - 6227846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11481644	3B - Medium Sustain	3B - 9001 S ADMIN E WOMENS RR - WT - INT PLUMB - TOILET KEEPS FLUSHING - Repair - [redacted] - 2003131	Repair
11482561	3C - Low Sustain	3C - 9001 G24 - WT- PLUMB INT - PIPE LEAKING AT TOP CONNECTION NOT CATCHING WATER TO POLE F/U 11472358- REPAIR - [redacted] - 582-4496	Repair
11483651	3B - Medium Sustain	3B - 9001 & POST 2J23 - WT - INT PLUMB - STOP LEAK - Repair - [redacted] - 3230319	Repair
11483877	3B - Medium Sustain	3B - 9001 POST 2J23 - WT - TAC HVAC -(parts on other wt) EXHAUST FANS NEED CHECKED - REPAIR - [redacted] 622-7846	Repair
11486974	2A - Preventive Maintenance	D5015234195001 - A - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11486975	2A - Preventive Maintenance	D5015234195001 - A - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11486976	2A - Preventive Maintenance	D5015234195001 - A - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11486977	2A - Preventive Maintenance	D5015234195001 - A - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11486978	2A - Preventive Maintenance	D5015234195001 - A - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11486979	2A - Preventive Maintenance	D5015234195001 - A - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11486992	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11486993	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11486994	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11486995	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11486996	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11486997	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11486998	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11486999	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11487000	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487001	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487002	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487003	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487004	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487005	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487006	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487007	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487008	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11487009	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487012	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487014	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487016	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487018	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487020	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487022	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487024	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487026	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11487028	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487030	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487032	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487034	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487036	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487038	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487040	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487042	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11487045	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11487047	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11491566	3B - Medium Sustain	3C- 9001 NODE 8 -WT- TAC ALARMS- FF TRF 6 IS SHOWING TROUBLE NEED TO INVESTIGATE - REPAIR - [redacted] - 582-4496	Repair
11492629	3A - High Sustain	3A - 9001 POST DD49 - WT - TAC HVAC - TOO HOT IN AREA - Repair - [redacted] - 5824105	Repair
11493032	3A - High Sustain	3A - 9001 & MENS RESTROOM - WT - INT PLUMB - STOP OVERFLOWING - Repair - [redacted] - 7368784	Repair
11493796	3B - Medium Sustain	3B - 9001 POST DD46 - WT - TAC HVAC - TWO AC'S ARE OFFLINE AND NOT BLOWING - Repair - [redacted] - 7364730	Repair
11494452	3B - Medium Sustain	3B - 9001 POST DD49 - WT - F/U 11492629 TAC HVAC - TOO HOT IN AREA - Repair - [redacted] - 5824105	Repair
11494663	3B - Medium Sustain	3B - 9001 FIRE ALARM ROOM - WT - TAC HVAC - AIR CONDITIONING NOT WORKING IN FIRE ALARM ROOM - REPAIR - [redacted] - 582-4496	Repair
11494689	3B - Medium Sustain	3B - 9001 KC46 B50/51 - WT - TAC CONTROLS -(vfd picked up) EXHAUST FANS INOP - Repair - [redacted] - 2003131	Repair
11496641	3B - Medium Sustain	3B - 9001 Post G39 women's restroom - WT - Intplumb - not enough water pressure when flushing covered unit- repair - [redacted] - 582-2105	Repair
11497055	3B - Medium Sustain	3B - 9001 ROOFTOP UNIT 4 MEZZ 2 - WT - HONEYWELL - ADJUST AC UNIT - Repair - [redacted] - 7367554 - HONEYWELL	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11497301	3C - Low Sustain	3B - 9001 ASH 78 - WT - TAC HVAC - REPAIR CONDENSATE LINES ON ASH HOUSE 78 - REPAIR - [redacted] -582-4496	Repair
11498449	3A - High Sustain	3A - 9001 & Q25 AND P25 - WT - TAC HVAC - STOP LEAK - Repair - [redacted] - 5824105	Repair
11500187	3B - Medium Sustain	3B- 9001 ASH HOUSE 90 - WT - TAC HVAC - SHUT OFF ASH HOUSE 90 DUE TO LOW SPEED - REPAIR- [redacted] -582-4496	Repair
11500206	3B - Medium Sustain	3B - 9001 MEZZ 1 AND 2 - WT - INT PLUMB - PULL FIXTURES AND CAP DRAINS - REPAIR - [redacted] - 6227846	Repair
11500782	3B - Medium Sustain	3B- 9001- WT - TAC STRUC - NEED TAGS FOR LADDER INSPECTIONS - REPAIR - [redacted] - 582-4496	Repair
11501642	3B - Medium Sustain	3B - 9001 POST J69 - WT - TACX HVAC- AREA TOO HOT (79 DEG) - REPAIR - [redacted] - 622-7846	Repair
11501715	3B - Medium Sustain	3B - 9001 POST J69 - WT - HONEYWELL - AREA TOO HOT (79 DEG) - REPAIR - [redacted] - 622-7846 - HONEYWELL	Repair
11504063	3B - Medium Sustain	3B - 9001 & POST Q42 - WT - TAC HVAC - FIX AC - Repair - [redacted] - 2742656-9001-AHU-57	Repair
11504828	3B - Medium Sustain	3B - 9001 & ELECTRICAL ROOM 6 - WT - TAC STRUC - ADDRESS DOOR LATCH - Repair - [redacted] - 2742656	Repair
11505911	3B - Medium Sustain	3B - 9001 POST D36 - WT - HONEYWELL - ADJUST LIGHT TIMERS FOR 24HR USE - REPAIR - [redacted] 736-5081	Repair
11506147	3B - Medium Sustain	3B - 9001 SE CORNER ROOF - WT - TAC HVAC - BAS: BAD CONDENSER FAN - REPAIR - [redacted] 582-5009	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11508042	3B - Medium Sustain	3B - 9001 POST 2T41 - WT - SPRINKLERS- F/U 11403902 REPLACE SPRINKLER HEAD TILE- REPAIR- [redacted] - 582-4496	Repair
11510168	3B - Medium Sustain	3B - 9001 POST 2W41 & 2W40 - WT - HONEYWELL - HVAC UNITS NEED CONNECTED TO EBI - REPAIR - [redacted] 622-7846	Repair
11510291	3B - Medium Sustain	3B - 9001 - WT - INT ELEC - FU 11427874 ORDER MATERIAL FOR EXIT SIGN - REPAIR - [redacted] 734-5043	Repair
11510336	3B - Medium Sustain	3B - 9001 POST U44 - WT - INSULATE - INSULUATION INSTALL - REPAIR - [redacted] - 6227846	Repair
11511270	4A - High Enhance	4A - 9001 - SVC FLOORING-CARPET PURCHASE REQUEST - [redacted] - 405 582 4946	Repair
11512730	3B - Medium Sustain	3B - 9001 S ADMIN ROOM 157 MEN'S RR - WT - INT PLUMB - TOILET NOT FLUSHING PROPERLY - REPAIR - [redacted] 736-8784	Repair
11514848	3B - Medium Sustain	3B - 9001 PRODUCTION AREA - WT - HONEYWELL - NEED NIGHT LIGHTS SET UP - REPAIR - [redacted] 622-7846	Repair
11517437	3B - Medium Sustain	3B - 9301 pkg3- WT - INT ELEC - F/U 11511050 Need electrician to turn power on. Lost a phase of power. Repair - [redacted] - 582-4496	Repair
11517517	3B - Medium Sustain	3B - 9001 POST L32 - WT - INTPLUMB - F/U 11421235 WATER HEATER INOP - REPAIR - T4881 - [redacted] - 582-4105	Repair
11517575	3B - Medium Sustain	3B - 9001 POST CC45 - WT - HONEYWELL - LIGHTS OUT IN PARTS OF THE BUILDING - REPAIR - [redacted] 622-7846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11517974	3A - High Sustain	3A - 9001 & U38 - WT - TAC HVAC - STOP LEAK - Repair - [redacted] - 6227846 - T5582 - 11414069	Repair
11518220	3B - Medium Sustain	3B - 9001 POST B60 - WT - LOCK - SECURITY ISSUE; NEED INTO CLASSIFIED SAFE - REPAIR - [redacted] 323-0319	Repair
11519425	2A - Preventive Maintenance	D30251301950 - A - Boiler, hot water, oil, gas, or comb. fired, up to 120 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 36	Maintenance
11519597	3B - Medium Sustain	3B - 9001 KC46 - WT - Tac Alarms - FF 9001 Node 20 Showing Trouble Need to Investigate - Repair - [redacted] 582-4496 - FA-1829	Repair
11520686	2A - Preventive Maintenance	D3035160295002 - A - Boiler/Chilled Water loops, Chemical Treatment - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 33	Maintenance
11520749	3C - Low Sustain	3C - 9001 MEN'S/WOMEN'S RR POST A33 - WT - INT PLUMB - NO HOT WATER - REPAIR - [redacted] 622-7846	Repair
11520761	2A - Preventive Maintenance	D3035160295005 - A - Chiller, Scroll, Air Cooled 30 to 130 Ton - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 33	Maintenance
11520776	3B - Medium Sustain	3B - 9001 POST EE45 DOOR N45 - WT - TAC STRUC - WEATHER STRIPPING NEEDS REPLACED - REPAIR - [redacted] 582-4105	Repair
11520795	2A - Preventive Maintenance	D3035160295005 - M - Chiller, Scroll, Air Cooled 30 to 130 Ton - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 33	Maintenance
11520796	2A - Preventive Maintenance	D3035160295005 - M - Chiller, Scroll, Air Cooled 30 to 130 Ton - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 33	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11520918	2A - Preventive Maintenance	D30352201950 - A - Condensing unit, air cooled, 3 to 25 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 36	Maintenance
11521506	2A - Preventive Maintenance	D30352201950 - A - Condensing unit, air cooled, 3 to 25 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 42	Maintenance
11521684	2A - Preventive Maintenance	D30451101950 - A - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 38	Maintenance
11521685	2A - Preventive Maintenance	D30451101950 - A - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 38	Maintenance
11521694	2A - Preventive Maintenance	D30451101950 - A - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 39	Maintenance
11521695	2A - Preventive Maintenance	D30451101950 - A - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 39	Maintenance
11521696	2A - Preventive Maintenance	D30451101950 - A - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 39	Maintenance
11521697	2A - Preventive Maintenance	D30451101950 - A - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 39	Maintenance
11521714	2A - Preventive Maintenance	D30451101950 - A - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 40	Maintenance
11521719	2A - Preventive Maintenance	D30451101950 - A - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 42	Maintenance
11524597	2A - Preventive Maintenance	D30451102950 - A - Air handling unit, 25 thru 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 36	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11524602	2A - Preventive Maintenance	D30451102950 - A - Air handling unit, 25 thru 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 38	Maintenance
11524603	2A - Preventive Maintenance	D30451102950 - A - Air handling unit, 25 thru 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 38	Maintenance
11524664	2A - Preventive Maintenance	D30451102950 - A - Air handling unit, 25 thru 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 36	Maintenance
11525019	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 34	Maintenance
11525020	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 34	Maintenance
11525021	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 34	Maintenance
11525036	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 36	Maintenance
11525042	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 37	Maintenance
11525043	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 37	Maintenance
11525044	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 37	Maintenance
11525045	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 37	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11525046	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 37	Maintenance
11525068	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 38	Maintenance
11525069	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 38	Maintenance
11525087	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 39	Maintenance
11525097	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 42	Maintenance
11525098	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 42	Maintenance
11525552	2A - Preventive Maintenance	D30451121950 - A - Air handling unit, computer room - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 36	Maintenance
11525553	2A - Preventive Maintenance	D30451121950 - A - Air handling unit, computer room - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 36	Maintenance
11529540	2A - Preventive Maintenance	D30451121950 - A - Air handling unit, computer room - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 37	Maintenance
11529542	2A - Preventive Maintenance	D30451121950 - A - Air handling unit, computer room - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 37	Maintenance
11529544	2A - Preventive Maintenance	D30451121950 - A - Air handling unit, computer room - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 37	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11529546	2A - Preventive Maintenance	D30451121950 - A - Air handling unit, computer room - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 37	Maintenance
11529549	2A - Preventive Maintenance	D30451121950 - A - Air handling unit, computer room - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 37	Maintenance
11529577	3B - Medium Sustain	3B - 9001 S END - WT - HONEYWELL - EXT LIGHTS INOP - REPAIR - [redacted] - 622-7846	Repair
11529886	3A - High Sustain	3A - 9001 POST DD55 - WT - INT ELEC - CIRCUT BREAKERS NEED RESET - REPAIR - [redacted] 736-4945	Repair
11529978	2A - Preventive Maintenance	D30454101950 - A - Centrifugal, over 1 HP - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 33	Maintenance
11529979	2A - Preventive Maintenance	D30454101950 - A - Centrifugal, over 1 HP - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 33	Maintenance
11530439	3A - High Sustain	3A - 9001 MEZZ 3 RM 103 - WT - TAC HVAC - CONDENSATE PUMP LEAKING - REPAIR - [redacted] 582-1118	Repair
11530491	3B - Medium Sustain	3B - 9001 POST BB33 - WT - INT PLUMB - PIPE ACTIVELY DRIPPING INTO TRASH CAN - REPAIR - [redacted] 323-0319	Repair
11530905	3B - Medium Sustain	3B - 9001 MEZZ 3 RM 103 - WT - TAC HVAC - FU 11530439 CONDENSATE PUMP LEAKING - REPAIR - [redacted] 582-1118	Repair
11533975	2A - Preventive Maintenance	D30551101950 - A - Unit heater, gas radiant - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 43	Maintenance
11533976	2A - Preventive Maintenance	D30551101950 - A - Unit heater, gas radiant - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 43	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11533978	2A - Preventive Maintenance	D30551101950 - A - Unit heater, gas radiant - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 43	Maintenance
11533979	2A - Preventive Maintenance	D30551101950 - A - Unit heater, gas radiant - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 43	Maintenance
11533982	2A - Preventive Maintenance	D30551101950 - A - Unit heater, gas radiant - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 43	Maintenance
11534624	2A - Preventive Maintenance	D30552101950 - A - Package unit, air cooled, 3 thru 24 ton - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 32	Maintenance
11534627	2A - Preventive Maintenance	D30552101950 - A - Package unit, air cooled, 3 thru 24 ton - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 32	Maintenance
11534702	3B - Medium Sustain	3B - 9001 BOEING POST B60 - WT - TAC ALARM - REF 11518220 SECURITY ALARM NOT FUNCTIONING PROPERLY - REPAIR - [redacted] 622-7846	Repair
11534775	2A - Preventive Maintenance	D30552101950 - A - Package unit, air cooled, 3 thru 24 ton - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 33	Maintenance
11534778	2A - Preventive Maintenance	D30552101950 - A - Package unit, air cooled, 3 thru 24 ton - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 33	Maintenance
11534845	2A - Preventive Maintenance	D30552101950 - A - Package unit, air cooled, 3 thru 24 ton - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 36	Maintenance
11535701	3B - Medium Sustain	3B - 9001 ASH HOUSE 71 - WT - TAC HVAC - ASH HOUSE 71 COIL LEAKING - REPAIR - [redacted] - 582-4496	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11535787	2A - Preventive Maintenance	D30552301950 - A - Package unit, computer room - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 34	Maintenance
11535790	2A - Preventive Maintenance	D30552301950 - A - Package unit, computer room - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 34	Maintenance
11535793	2A - Preventive Maintenance	D30552301950 - A - Package unit, computer room - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 34	Maintenance
11535871	2A - Preventive Maintenance	D30552301950 - A - Package unit, computer room - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 36	Maintenance
11535872	2A - Preventive Maintenance	D30552301950 - A - Package unit, computer room - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 36	Maintenance
11536097	2A - Preventive Maintenance	D30552401950 - A - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 32	Maintenance
11536249	2A - Preventive Maintenance	D30552401950 - A - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 33	Maintenance
11536251	2A - Preventive Maintenance	D30552401950 - A - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 33	Maintenance
11536252	2A - Preventive Maintenance	D30552401950 - A - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 33	Maintenance
11536254	2A - Preventive Maintenance	D30552401950 - A - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 33	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11536349	2A - Preventive Maintenance	D30552401950 - A - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 34	Maintenance
11536351	2A - Preventive Maintenance	D30552401950 - A - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 34	Maintenance
11536445	2A - Preventive Maintenance	D30552401950 - A - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 45	Maintenance
11536446	2A - Preventive Maintenance	D30552401950 - A - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 45	Maintenance
11536447	2A - Preventive Maintenance	D30552401950 - A - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 45	Maintenance
11536470	2A - Preventive Maintenance	D30452102950 - A - Fan, axial, 5,000 to 10,000 CFM - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 36	Maintenance
11536506	2A - Preventive Maintenance	D30452102950 - A - Fan, axial, 5,000 to 10,000 CFM - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 42	Maintenance
11536509	2A - Preventive Maintenance	D30452102950 - A - Fan, axial, 5,000 to 10,000 CFM - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 42	Maintenance
11536510	2A - Preventive Maintenance	D30452102950 - A - Fan, axial, 5,000 to 10,000 CFM - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 42	Maintenance
11536511	2A - Preventive Maintenance	D30452102950 - A - Fan, axial, 5,000 to 10,000 CFM - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 42	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11536513	2A - Preventive Maintenance	D30452102950 - A - Fan, axial, 5,000 to 10,000 CFM - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 42	Maintenance
11536516	2A - Preventive Maintenance	D30452102950 - A - Fan, axial, 5,000 to 10,000 CFM - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 42	Maintenance
11536518	2A - Preventive Maintenance	D30452102950 - A - Fan, axial, 5,000 to 10,000 CFM - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 42	Maintenance
11536552	2A - Preventive Maintenance	D30452102950 - A - Fan, axial, 5,000 to 10,000 CFM - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 37	Maintenance
11536592	2A - Preventive Maintenance	D30452102950 - A - Fan, axial, 5,000 to 10,000 CFM - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 39	Maintenance
11536595	2A - Preventive Maintenance	D30452102950 - A - Fan, axial, 5,000 to 10,000 CFM - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 39	Maintenance
11536789	3B - Medium Sustain	3B - 9001 ASH 33 -WT - TAC HVAC - RESTORE AND SEAL CONDENSATE PANS ON ASH HOUSE 33 - REPAIR - [redacted] -582-4496	Repair
11536845	2A - Preventive Maintenance	D30552401950 - A - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 39	Maintenance
11536846	2A - Preventive Maintenance	D30552401950 - A - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 39	Maintenance
11537151	2A - Preventive Maintenance	D30552501950 - A - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 39	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11537154	2A - Preventive Maintenance	D30552501950 - A - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 39	Maintenance
11537157	2A - Preventive Maintenance	D30552501950 - A - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 39	Maintenance
11537159	2A - Preventive Maintenance	D30552501950 - A - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 39	Maintenance
11537161	2A - Preventive Maintenance	D30552501950 - A - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 39	Maintenance
11539540	2A - Preventive Maintenance	D30454101950 - A - Centrifugal, over 1 HP - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11539541	2A - Preventive Maintenance	D30454101950 - A - Centrifugal, over 1 HP - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11539573	3B - Medium Sustain	3B - 9001 POST A32 FM OFFICE - WT - TAC STRUC - HANG FIRE EXTINGUISHER AND 3 KEY BOXES - REPAIR - [redacted] 622-7846	Repair
11539608	2A - Preventive Maintenance	D30552101950 - A - Package unit, air cooled, 3 thru 24 ton - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11539637	2A - Preventive Maintenance	D30552101950 - Q - Package unit, air cooled, 3 thru 24 ton - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11539677	2A - Preventive Maintenance	D30552401950 - A - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11539680	2A - Preventive Maintenance	D30552401950 - A - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11539710	2A - Preventive Maintenance	D30552401950 - Q - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11539713	2A - Preventive Maintenance	D30552401950 - Q - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11539774	2A - Preventive Maintenance	D30552501950 - A - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11539778	2A - Preventive Maintenance	D30552501950 - A - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11539780	2A - Preventive Maintenance	D30552501950 - A - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11539782	2A - Preventive Maintenance	D30552501950 - A - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11539785	2A - Preventive Maintenance	D30552501950 - A - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11539816	2A - Preventive Maintenance	D30552501950 - Q - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11539817	2A - Preventive Maintenance	D30552501950 - Q - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11539819	2A - Preventive Maintenance	D30552501950 - Q - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11539821	2A - Preventive Maintenance	D30552501950 - Q - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11539822	2A - Preventive Maintenance	D30552501950 - Q - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11540063	3B - Medium Sustain	3B - 9001 & F40 AND F41 - WT - TAC HVAC - STOP DRIPPING PIPE - Repair - [redacted] - 5824105	Repair
11540079	3B - Medium Sustain	3B - 9001 & G40 - WT - INT PLUMB - STOP DRAINAGE SPILLING - Repair - [redacted] - 5824105	Repair
11540416	3B - Medium Sustain	3B - 9001 & POST KC46 - WT - TAC HVAC - TURN ON AHU - Repair - [redacted] - 6230072	Repair
11540535	3C - Low Sustain	duplicate 11398992 - 9001 Mezz 3 R101N G50 - WT - CBR - add duct to CRAC units - [redacted] - 405 582 5516	Repair
11540693	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11540694	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11540736	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11540743	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11540779	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11540782	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11540810	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11541023	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11541024	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11541025	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11541026	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11541027	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11541065	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11541068	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11541069	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11541072	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11541074	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11541085	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 31	Maintenance
11541088	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 31	Maintenance
11541118	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 31	Maintenance
11541120	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 31	Maintenance
11541148	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11541149	2A - Preventive Maintenance	D30451103950 - A - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11541170	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11541171	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11541183	2A - Preventive Maintenance	D30451121950 - A - Air handling unit, computer room - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 31	Maintenance
11541203	2A - Preventive Maintenance	D30451121950 - Q - Air handling unit, computer room - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 31	Maintenance
11541820	3B - Medium Sustain	3B - 9001 POST 220 W2-2 - WT - TAC STRUC - PERSONNEL DOOR HAS LOOSE HINGE - REPAIR - [redacted] 582-4105	Repair
11541869	2A - Preventive Maintenance	D30351601950 - A - Chiller, screw, water cooled, up to 100 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11541896	2A - Preventive Maintenance	D30351601950 - Q - Chiller, screw, water cooled, up to 100 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11541905	2A - Preventive Maintenance	D30351601950 - M - Chiller, screw, water cooled, up to 100 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11541906	2A - Preventive Maintenance	D30351601950 - M - Chiller, screw, water cooled, up to 100 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11542180	4A - High Enhance	4A - 9001 Y 28 - CBR - INSTALL 2 FOUNDATION PADS - [redacted] - 405 739 4975	Repair
11542205	2A - Preventive Maintenance	D30352101950 - A - Condenser, air cooled, 3 tons to 25 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11542227	2A - Preventive Maintenance	D30352101950 - Q - Condenser, air cooled, 3 tons to 25 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11542285	2A - Preventive Maintenance	D30351601950 - A - Chiller, screw, water cooled, up to 100 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11542324	2A - Preventive Maintenance	D30351601950 - Q - Chiller, screw, water cooled, up to 100 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11542336	2A - Preventive Maintenance	D30351601950 - M - Chiller, screw, water cooled, up to 100 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11542339	2A - Preventive Maintenance	D30351601950 - M - Chiller, screw, water cooled, up to 100 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11542372	2A - Preventive Maintenance	D30352101950 - A - Condenser, air cooled, 3 tons to 25 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11542393	2A - Preventive Maintenance	D30352101950 - Q - Condenser, air cooled, 3 tons to 25 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 30	Maintenance
11542440	2A - Preventive Maintenance	D30352201950 - A - Condensing unit, air cooled, 3 to 25 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11542441	2A - Preventive Maintenance	D30352201950 - A - Condensing unit, air cooled, 3 to 25 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11542458	2A - Preventive Maintenance	D30352201950 - Q - Condensing unit, air cooled, 3 to 25 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11542459	2A - Preventive Maintenance	D30352201950 - Q - Condensing unit, air cooled, 3 to 25 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 29	Maintenance
11542494	2A - Preventive Maintenance	D30451101950 - A - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11542497	2A - Preventive Maintenance	D30451101950 - A - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11542499	2A - Preventive Maintenance	D30451101950 - A - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11542501	2A - Preventive Maintenance	D30451101950 - A - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11542502	2A - Preventive Maintenance	D30451101950 - A - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11542506	2A - Preventive Maintenance	D30451101950 - A - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11542507	2A - Preventive Maintenance	D30451101950 - A - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11542509	2A - Preventive Maintenance	D30451101950 - A - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11546051	3B - Medium Sustain	3B - 9001-FAN-FLT-15 - WT - TAC HVAC - REPLACE 1 BOX 16 X 16 X 1 FILTER FOR PM 9001-8084-16 - REPAIR - [redacted] 582-4496	Repair
11546056	3B - Medium Sustain	3B - 9001-FAN-FLT-14 - WT - TAC HVAC - REPLACE 1 BOX 16 X 16 X 1 FILTER FOR PM 9001-8084-15 - REPAIR - [redacted] 582-4496	Repair
11546063	3B - Medium Sustain	3B - 9001-FAN-FLT-09 - WT - TAC HVAC - REPLACE 1 BOX 16 X 16 X 1 FILTER FOR PM 9001-8084-10 - REPAIR - [redacted] 582-4496	Repair
11546064	3B - Medium Sustain	3B - 9001-FAN-FLT-16 - WT - TAC HVAC - REPLACE 1 BOX 16 X 16 X 1 FILTER FOR PM 9001-8084-17 - REPAIR - [redacted] 582-4496	Repair
11546069	3B - Medium Sustain	3B - 9001-FAN-FLT-13 - WT - TAC HVAC - REPLACE 1 BOX 16 X 16 X 1 FILTER FOR PM 9001-8084-14 - REPAIR - [redacted] 582-4496	Repair
11547840	3B - Medium Sustain	3B - 9001 MULTI POSTS - WT - HONEYWELL - ADJUST LIGHT SCHEDULE TO STAY ON - REPAIR - [redacted] - 413-9373	Repair
11550039	3A - High Sustain	3A - 9001 post K21 to l21 - WT - TAC HVAC- A/C isn't working, need a thermostat - repair - [redacted] - 582-4292	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11550080	3B - Medium Sustain	3B - 9001 POST A33 - WT - INT ELEC - LIGHTS HAVING POWER ISSUES - T5830 - REPAIR - [redacted] 734-3142	Repair
11550090	3B - Medium Sustain	3B - 9001 - WT - INT ELEC - NW CORNER ADMIN LIGHTS NOT WORKING - T5831 - REPAIR - [redacted] 734-3142	Repair
11550106	3B - Medium Sustain	3B - 9001 S ADMIN GARAGE - WT - INT ELEC - LIGHT FIXTURES NOT WORKING - T5833 - REPAIR - [redacted] 734-3142	Repair
11553827	3B - Medium Sustain	3B - 9001 POST S30 - WT - LOCK - TWO CYPHER LOCKS NEED CORE AND KEYS AND NEED COMBO SET - Repair - [redacted] - 582-4105	Repair
11553857	3B - Medium Sustain	3B - 9001 POST X30 - WT - LOCK - TWO CYPHER LOCKS NEED CORE AND KEYS AND NEED COMBO SET - Repair - [redacted] - 582-4105	Repair
11553882	3B - Medium Sustain	3B - 9001 POST S31 - WT - LOCK - ONE CYPHER LOCK NEED CORE AND KEY AND NEED COMBO SET - Repair - [redacted] - 582-4105	Repair
11553926	3B - Medium Sustain	3B - 9001 POST X30 - WT - LOCK - 6 DOORS NEED CORE A KEY/REQUESTER HAS CORE AND KEYS - Repair - [redacted] - 582-4105	Repair
11554110	3B - Medium Sustain	3B - 9001 Posts T47 to T52 & Q47 to Q52 - WT - INT ELEC - Lights are out SENT FROM HONEYWELL 11401358 POWER ISSUE - repair - [redacted] - 582-410	Repair
11555350	3B - Medium Sustain	3B- 9001 ASH HOUSE 211 - WT - TAC CONTROLS - ADJUST FAN SPEED ON ASH HOUSE 211 TO PREVENT CONDENSATE LEAK - REPAIR - [redacted] -582-4496	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11560852	3B - Medium Sustain	3B - 9001 POST L23 BREAKROOM - WT - TAC STRUC - CEILING TILES NEED REPLACED - REPAIR - [redacted] - 5824105	Repair
11563700	3B - Medium Sustain	3B - 9001 L27/28 - WT - HONEYWELL - LIGHTS NOT WORKING PROPERLY - REPAIR - [redacted] - 5824105	Repair
11564674	3A - High Sustain	3A - 9001 POST W22 WOMEN'S RR - WT - INT PLUMB - WATER LEAK COMING FROM THE WALL - REPAIR - [redacted] 323-0319	Repair
11564675	3B - Medium Sustain	3B - 9001 POST W22 WOMEN'S RR - WT - TAC STRUC - DOOR TO WOMEN'S RR NOT SHUTTING PROPERLY - REPAIR - [redacted] 323-0319	Repair
11564928	3B - Medium Sustain	3B - 9001 & ROOF ACCES 2W23 - WT - INT ELEC - REPAIR EXIT LIGHT - Repair - [redacted] - 3230319	Repair
11564938	3B - Medium Sustain	3B - 9001 & 2W23 - WT - INT PLUMB - TURN PRESSURE DOWN - Repair - [redacted] - 3230319	Repair
11569618	3B - Medium Sustain	3B - 9001 POST X22 BREAKROOM - WT - TAC STRUC - HANG 2 EXTINGUISHERS - REPAIR - [redacted] - 2742656	Repair
11569914	4A - High Enhance	4A - 9001 G16 & G17 - WT - OP - 76 CMXG Eng wants to get approval to extend the autoclave pit - [redacted] - 405 582 6916 wesley programming	Repair
11571961	3B - Medium Sustain	3B - 9001 POST A69 RESTROOMS - WT - INT PLUMB - TOILETS VERY SLOW - REPAIR - [redacted] 323-0319	Repair
11573207	3A - High Sustain	3A - 9001 post A36 - WT - AFTER PLUMB - mop closet floor drain is backed up and there is standing water - repair - [redacted] 323-0319	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11574501	2A - Preventive Maintenance	Copy of D30451103950 - S - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 1	Maintenance
11574502	2A - Preventive Maintenance	Copy of D30451103950 - S - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 1	Maintenance
11574506	2A - Preventive Maintenance	Copy of D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 1	Maintenance
11574507	2A - Preventive Maintenance	Copy of D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 1	Maintenance
11574532	2A - Preventive Maintenance	Copy of D30251302950 - S - Boiler, hot water, oil, gas, or comb. fired, 120 to 500 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 5	Maintenance
11574543	2A - Preventive Maintenance	Copy of D30251302950 - Q - Boiler, hot water, oil, gas, or comb. fired, 120 to 500 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 5	Maintenance
11574552	2A - Preventive Maintenance	Copy of D30251302950 - M - Boiler, hot water, oil, gas, or comb. fired, 120 to 500 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 5	Maintenance
11574553	2A - Preventive Maintenance	Copy of D30251302950 - M - Boiler, hot water, oil, gas, or comb. fired, 120 to 500 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 5	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11574988	2A - Preventive Maintenance	Copy of D30251302950 - M - Boiler, hot water, oil, gas, or comb. fired, 120 to 500 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11574989	2A - Preventive Maintenance	Copy of D30251302950 - M - Boiler, hot water, oil, gas, or comb. fired, 120 to 500 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11574990	2A - Preventive Maintenance	Copy of D30251302950 - M - Boiler, hot water, oil, gas, or comb. fired, 120 to 500 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11574991	2A - Preventive Maintenance	Copy of D30251302950 - M - Boiler, hot water, oil, gas, or comb. fired, 120 to 500 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11574992	2A - Preventive Maintenance	Copy of D30251302950 - M - Boiler, hot water, oil, gas, or comb. fired, 120 to 500 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11574993	2A - Preventive Maintenance	Copy of D30251302950 - M - Boiler, hot water, oil, gas, or comb. fired, 120 to 500 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11574995	2A - Preventive Maintenance	Copy of D30251302950 - M - Boiler, hot water, oil, gas, or comb. fired, 120 to 500 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11574997	2A - Preventive Maintenance	Copy of D30251302950 - M - Boiler, hot water, oil, gas, or comb. fired, 120 to 500 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11574999	2A - Preventive Maintenance	Copy of D30251302950 - M - Boiler, hot water, oil, gas, or comb. fired, 120 to 500 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11575002	2A - Preventive Maintenance	Copy of D30251302950 - M - Boiler, hot water, oil, gas, or comb. fired, 120 to 500 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11575004	2A - Preventive Maintenance	Copy of D30251302950 - M - Boiler, hot water, oil, gas, or comb. fired, 120 to 500 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11575006	2A - Preventive Maintenance	Copy of D30251302950 - M - Boiler, hot water, oil, gas, or comb. fired, 120 to 500 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11575514	2A - Preventive Maintenance	Copy of D3035160295005 - M - Chiller, Scroll, Air Cooled 30 to 130 Ton - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 33	Maintenance
11575606	2A - Preventive Maintenance	D30251301950 - M - Boiler, hot water, oil, gas, or comb. fired, up to 120 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 36	Maintenance
11575607	2A - Preventive Maintenance	D30251301950 - M - Boiler, hot water, oil, gas, or comb. fired, up to 120 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 36	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11575608	2A - Preventive Maintenance	D30251301950 - M - Boiler, hot water, oil, gas, or comb. fired, up to 120 MBH - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 36	Maintenance
11575829	2A - Preventive Maintenance	D30352201950 - Q - Condensing unit, air cooled, 3 to 25 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 42	Maintenance
11575857	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11575858	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11575859	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11575860	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11575861	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11575862	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11575863	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11575864	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 28	Maintenance
11575899	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 42	Maintenance
11575938	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 42	Maintenance
11575940	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 42	Maintenance
11575975	2A - Preventive Maintenance	D30452102950 - S - Fan, axial, 5,000 to 10,000 CFM - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 14	Maintenance
11575976	2A - Preventive Maintenance	D30452102950 - S - Fan, axial, 5,000 to 10,000 CFM - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 14	Maintenance
11575991	2A - Preventive Maintenance	D30552401950 - Q - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 45	Maintenance
11575993	2A - Preventive Maintenance	D30552401950 - Q - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 45	Maintenance
11575994	2A - Preventive Maintenance	D30552401950 - Q - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 45	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11576049	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 49	Maintenance
11576050	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 49	Maintenance
11576052	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 49	Maintenance
11576053	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 49	Maintenance
11576054	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 49	Maintenance
11576055	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 49	Maintenance
11576056	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 49	Maintenance
11576057	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 49	Maintenance
11576058	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 49	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11576059	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 49	Maintenance
11576060	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 49	Maintenance
11576061	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 49	Maintenance
11576062	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 49	Maintenance
11576063	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 49	Maintenance
11576243	2A - Preventive Maintenance	D30552401950 - Q - Package unit with duct gas heater - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 49	Maintenance
11576325	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 50	Maintenance
11576326	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 50	Maintenance
11576327	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 50	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11576328	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 50	Maintenance
11576329	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 50	Maintenance
11576330	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 50	Maintenance
11576331	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 50	Maintenance
11576332	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 50	Maintenance
11576333	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 50	Maintenance
11576334	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 50	Maintenance
11576335	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 50	Maintenance
11576336	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 50	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11576337	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 50	Maintenance
11576338	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 50	Maintenance
11576371	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 50	Maintenance
11576372	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 50	Maintenance
11576383	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 51	Maintenance
11576384	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 51	Maintenance
11576385	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 51	Maintenance
11576386	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 51	Maintenance
11576387	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 51	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11576388	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 51	Maintenance
11576389	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 51	Maintenance
11576390	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 51	Maintenance
11576391	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 51	Maintenance
11576392	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 51	Maintenance
11576393	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 51	Maintenance
11576427	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 53	Maintenance
11576428	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 53	Maintenance
11576429	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 53	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11576430	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 53	Maintenance
11576431	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 53	Maintenance
11576432	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 53	Maintenance
11576433	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 53	Maintenance
11576434	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 53	Maintenance
11576435	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 53	Maintenance
11578191	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 22	Maintenance
11578256	2A - Preventive Maintenance	D10151101950 - A - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 32	Maintenance
11578257	2A - Preventive Maintenance	D10151101950 - A - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 32	Maintenance
11578321	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 32	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11578322	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 32	Maintenance
11578382	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 37	Maintenance
11578383	2A - Preventive Maintenance	REJECTED - ASSET # WWYK0010332 RETIRED	Maintenance
11578384	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 37	Maintenance
11578407	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 38	Maintenance
11578408	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 38	Maintenance
11578657	2A - Preventive Maintenance	D10151101950 - Q - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11578671	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11578672	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11579156	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11579157	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11579158	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11579159	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11579160	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11579161	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11579356	2A - Preventive Maintenance	D5095210295002 - S - Diesel Generator, >5 - 25 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 12	Maintenance
11579358	2A - Preventive Maintenance	D5095210295002 - M - Diesel Generator, >5 - 25 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 12	Maintenance
11579359	2A - Preventive Maintenance	D5095210295002 - M - Diesel Generator, >5 - 25 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 12	Maintenance
11579360	2A - Preventive Maintenance	D5095210295002 - M - Diesel Generator, >5 - 25 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 12	Maintenance
11579369	2A - Preventive Maintenance	D5095210295002 - J - Diesel Generator, >5 - 25 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 12	Maintenance
11579370	2A - Preventive Maintenance	D5095210295002 - J - Diesel Generator, >5 - 25 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 12	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11579371	2A - Preventive Maintenance	D5095210295002 - J - Diesel Generator, >5 - 25 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 12	Maintenance
11579372	2A - Preventive Maintenance	D5095210295002 - J - Diesel Generator, >5 - 25 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 12	Maintenance
11583378	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 18	Maintenance
11583379	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 18	Maintenance
11583380	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 18	Maintenance
11583421	2A - Preventive Maintenance	D30352202950 - Q - Condensing unit, air cooled, 26 to 100 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 23	Maintenance
11583422	2A - Preventive Maintenance	D30352202950 - Q - Condensing unit, air cooled, 26 to 100 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 23	Maintenance
11583423	2A - Preventive Maintenance	D30352202950 - Q - Condensing unit, air cooled, 26 to 100 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 23	Maintenance
11583424	2A - Preventive Maintenance	D30352202950 - Q - Condensing unit, air cooled, 26 to 100 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 23	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11583437	2A - Preventive Maintenance	D30451102950 - Q - Air handling unit, 25 thru 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 23	Maintenance
11583438	2A - Preventive Maintenance	D30451102950 - Q - Air handling unit, 25 thru 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 23	Maintenance
11583536	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 23	Maintenance
11583537	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 23	Maintenance
11583538	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 23	Maintenance
11583539	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 23	Maintenance
11583540	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 23	Maintenance
11583556	2A - Preventive Maintenance	D30552301950 - Q - Package unit, computer room - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 23	Maintenance
11583557	2A - Preventive Maintenance	D30552301950 - Q - Package unit, computer room - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 23	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11583584	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 27	Maintenance
11583585	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 27	Maintenance
11583586	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 27	Maintenance
11583587	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 27	Maintenance
11583588	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 27	Maintenance
11583609	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 27	Maintenance
11583610	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 27	Maintenance
11583611	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 27	Maintenance
11583612	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 27	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11583625	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 19	Maintenance
11583626	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 19	Maintenance
11583641	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 24	Maintenance
11583642	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 24	Maintenance
11583643	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 24	Maintenance
11583644	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 24	Maintenance
11583645	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 24	Maintenance
11583660	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 24	Maintenance
11583661	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 24	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11583673	2A - Preventive Maintenance	D30352102950 - Q - Condenser, air cooled, 26 tons through 100 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11583674	2A - Preventive Maintenance	D30352102950 - Q - Condenser, air cooled, 26 tons through 100 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11583675	2A - Preventive Maintenance	D30352102950 - Q - Condenser, air cooled, 26 tons through 100 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11583686	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11583687	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11583699	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11583700	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11583701	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 20	Maintenance
11583723	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 25	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11583724	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 25	Maintenance
11583725	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 25	Maintenance
11583726	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 25	Maintenance
11583727	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 25	Maintenance
11583728	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 25	Maintenance
11583729	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 25	Maintenance
11583753	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 25	Maintenance
11583754	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 25	Maintenance
11583755	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 25	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11583756	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 25	Maintenance
11583766	2A - Preventive Maintenance	D30451103950 - S - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 17	Maintenance
11583769	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 17	Maintenance
11583788	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 21	Maintenance
11583789	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 21	Maintenance
11583790	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 21	Maintenance
11583791	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 21	Maintenance
11583792	2A - Preventive Maintenance	D30451101950 - Q - Air handling unit, 3 thru 24 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 21	Maintenance
11583811	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 21	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11583812	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 21	Maintenance
11583813	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 21	Maintenance
11583814	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 21	Maintenance
11583829	2A - Preventive Maintenance	D30552501950 - Q - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 21	Maintenance
11583830	2A - Preventive Maintenance	D30552501950 - Q - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 21	Maintenance
11583831	2A - Preventive Maintenance	D30552501950 - Q - Air conditioning,split system,DX air cooled,to 10 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 21	Maintenance
11583842	2A - Preventive Maintenance	D30352102950 - Q - Condenser, air cooled, 26 tons through 100 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 22	Maintenance
11583843	2A - Preventive Maintenance	D30352102950 - Q - Condenser, air cooled, 26 tons through 100 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 22	Maintenance
11583861	2A - Preventive Maintenance	D30451102950 - Q - Air handling unit, 25 thru 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 22	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11583862	2A - Preventive Maintenance	D30451102950 - Q - Air handling unit, 25 thru 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 22	Maintenance
11583863	2A - Preventive Maintenance	D30451102950 - Q - Air handling unit, 25 thru 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 22	Maintenance
11583864	2A - Preventive Maintenance	D30451102950 - Q - Air handling unit, 25 thru 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 22	Maintenance
11583878	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 22	Maintenance
11583879	2A - Preventive Maintenance	D30451103950 - Q - Air handling unit, over 50 tons - TINKER AFB - 9001 - TACX_HVAC_PM - ANNUALWEEK 22	Maintenance
11585275	3A - High Sustain	3A - 9001 B-52 - WT - TAC ALARM - KC-46 Comm failure - Repair - [redacted] - 405-623-0072	Repair
11586704	2A - Preventive Maintenance	D5095210295004 - S - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586705	2A - Preventive Maintenance	D5095210295004 - S - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586707	2A - Preventive Maintenance	D5095210295004 - S - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586728	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11586729	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586732	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586733	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586734	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586735	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586737	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586739	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586740	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586762	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586764	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586766	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11586768	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586769	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586770	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586773	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586774	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586776	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586777	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586778	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586780	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11586890	3B - Medium Sustain	3B - 9001 POST A33 - WT - TAC HVAC - CLEAN FILTERS - REPAIR - [redacted] - 582-4496	Repair
11587814	3B - Medium Sustain	3B - 9001 POST E13 AND F16 - WT - INT ELEC - 2 SETS OF LIGHTS NOT WORKING - REPAIR - [redacted] 582-4105	Repair
11587918	3B - Medium Sustain	3B - 9001 & POST V45 - WT - INT ELEC - FIX LIGHTS - Repair - [redacted] - 5824196	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11588026	3C - Low Sustain	3C - 9001 POST F69 - WT - TAC STRUC - AUTO CLOSER DRAGS AND MAKES GRINDING NOISE - REPAIR - [redacted] 622-7846 - SR# 3007649	Repair
11588104	3B - Medium Sustain	3B - 9001 ROOM 121 - WT - HVAC A - NO A/C - REPAIR - [redacted] - 2003131	Repair
11588187	3C - Low Sustain	3C - 9001FM OFFICE POST A32 - WT - INT PLUMB - WATER FOUNTAIN UNPLUGGED AND FILTER HANGING OFF WALL - REPAIR - [redacted] 622-7846 - SR# 3007746	Repair
11588700	3C - Low Sustain	3C - 9001 FOYER BTWN A47/A48 - WT - TAC STRUC - REPLACE CEILING TILES - REPAIR - [redacted] 622-7846 - SR# 3008028	Repair
11588983	3B - Medium Sustain	3B - 9001 POST H28 UPPER NAC PANEL - WT - TAC ALARM - FF REPLACE BATTERIES ON 9001-FA-1388A ON PM 8978-66 - REPAIR - [redacted] 582-4496	Repair
11588989	3C - Low Sustain	3C - 9001 POST H28 UPPER RIGHT NAC PANEL - WT - TAC ALARM - FF REPLACE BATTERIES ON 9001-FA-1388B ON PM 8978-67 - REPAIR - [redacted] 582-4496	Repair
11589001	3C - Low Sustain	3C - 9001 POST H28 UPPER LEFT NAC PANEL - WT - TAC ALARM - FF REPLACE BATTERIES ON 9001-FA-1388C ON PM 8978-68 - REPAIR - [redacted] - 582-4496	Repair
11589238	3C - Low Sustain	3C - 9001 POSTS S-31A, S-31B, & S-31C - WT - TAC STRUC - NEED DOOR CLOSERS ADJUSTED - Repair - [redacted] - 622-7846 - 3008342	Repair
11589251	3B - Medium Sustain	3B - 9001 & POST A 61- WT - INSULATE - INSULATE GAP - Repair - [redacted] - 6227846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11589274	3B - Medium Sustain	3B - 9001 POST X41 ROOFTOP - WT - TAC HVAC - UNINSULATED PIPE ON ROOF IS LEAKING - REPAIR - [redacted] 622-7846	Repair
11589278	3B - Medium Sustain	3B - 9001 ROOFTOP POST J-K 38/39 - WT - TAC HVAC - CONDENSATION WATER LINE LEAK - REPAIR - [redacted] 622-7846 - SR# 3008376	Repair
11589314	3C - Low Sustain	3C - 9001 BTWN POSTS A23&A33 - WT - TAC STRUC - SEAL/INSULATE LARGE GAP IN CONCRETE - REPAIR - [redacted] 622-7846 - SR# 3008403	Repair
11591213	3C - Low Sustain	3C - 9001- WT - LOCK - MAKE KEYS - Repair - [redacted] - 5824105	Repair
11593465	2A - Preventive Maintenance	D5095210295006 - Q - EAID Generator - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11593467	2A - Preventive Maintenance	D5095210295006 - Q - EAID Generator - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11593481	2A - Preventive Maintenance	D5095210295006 - M - EAID Generator - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11593482	2A - Preventive Maintenance	D5095210295006 - M - EAID Generator - TINKER AFB - 9001 - POWER_PRO - ANNUALWEEK 4	Maintenance
11593828	3B - Medium Sustain	3B - 9001 POST A32 - WT - INT ELEC - OUTLET NOT WORKING IN STORAGE ROOM - Repair - [redacted] - 622-7846	Repair
11593861	3B - Medium Sustain	3B - 9001 CAGED AREA POST V42 - WT - INT ELEC - EMERGENCY EXIT LIGHT FAILED TEST - REPAIR - [redacted] 622-7846 - SR# 3010819	Repair
11593980	3C - Low Sustain	3C - 9001 Post L23 BRKRM - WT - Tac Alarms - FF Replace bad ceiling tile where alarm device is located in breakroom - Repair - [redacted] 582-4496	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11593998	3C - Low Sustain	3C - 9001 X37 - WT - Tac Alarm - Pull station at X37 showing no answer. Need to troubleshoot - Repair - [redacted] 582-4496	Repair
11594319	3B - Medium Sustain	3B - 9001 MEN'S/WOMEN'S RR POST E30 - WT - INT ELEC - LIGHTS OUT IN BATHROOMS - REPAIR - [redacted] 622-7846 - SR# 3010979	Repair
11594374	3C - Low Sustain	3C - 9001 K69 - WT - TAC CONTROLS- CHECK CARBON MONOXIDE ALARM DETECTOR NEXT TO OH DOOR E69-3 - REPAIR - [redacted] 622-7846 - SR# 3011000	Repair
11596821	3C - Low Sustain	3C - 9001 POST F12 - WT - INT PLUMB - LABEL WATER LINE AS POTABLE OR INDUSTRIAL - REPAIR - [redacted] 739-4246	Repair
11597836	3C - Low Sustain	3C - 9001 2nd flr R/R- WT - INT ELEC - ISWP - INSTALL HAND DRYERS - Repair - [redacted] 622-7846 - CSAG-263 MAD22-179	Repair
11598197	3C - Low Sustain	3C - 9001 POST J27&J30 - WT - INT ELEC - KNOCK OUT FILLER PLUGS NEEDED - REPAIR - [redacted] 734-5043	Repair
11598198	3C - Low Sustain	3C - 9001 POST H41 BUSSWAY - WT - INT ELEC - KNOCK OUT PLUG REQUIRED - REPAIR - [redacted] 734-5043	Repair
11598201	3B - Medium Sustain	3B - 9001 POST E-25 - WT - INT ELEC - DISCONNECT HAS BEEN DAMAGED - REPAIR - [redacted] - 734-5043	Repair
11598890	3C - Low Sustain	3C - 9001 ROOF - WT - TAC HVAC - PICK UP DEBRIS ON ROOF - REPAIR - [redacted] 582-4496	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11599115	3C - Low Sustain	3C - 9001 2ND FLR. R.R. W. DOGLEG JANITORS CLOSET - W.T - PLUMB INT - REPAIR LEAK ON MIXING VAVLE - REPAIR - [redacted] - 405-734-7098	Repair
11599164	3C - Low Sustain	3C - 9001 2ND FLR R.R. W DOGLEG JANITORS CLOSET - WT - PLUMB INT - F/F REPAIR WATER HEATER LEAK 9001-WH-D10 - REPAIR - [redacted] - 405-734-7098	Repair
11599196	3C - Low Sustain	3C - 9001 V-46 R.R. WHITE HOUSE - WT - PLUMB INT - F/F REPAIR WATER HEATER LEAK 9001-WH-42 - REPAIR - [redacted] - 405-734-7098	Repair
11600164	3B - Medium Sustain	3B - 9001 ASH HOUSE 203 POST H68 - WT - TAC HVAC - VERY HOT; RETURN AIR TEMP IS 81 - REPAIR - [redacted] 323-0319	Repair
11602394	3C - Low Sustain	3C - 9001 Rm 107 - WT - BUG - Roaches in Rm 107 - Repair - [redacted] - 736-2705	Services
11602414	3B - Medium Sustain	3B - 9001 Post 2V45 - WT - Intplumb - Water pressure very low - Repair - [redacted] - 582-4105	Repair
11603566	3A - High Sustain	3A - 9001 SOUTH SIDE OF BLDG - WT - EXT PLUMB - NO GAS FLOWING TO BOOTHS - Repair - [redacted] - 5829577	Repair
11604321	3A - High Sustain	C/O - 3A - 9001 ROOM 115 - WT - INT PLUMB - WATER HEATER PILOT LIGHT OUT - Repair - [redacted] - 7362705	Repair
11604839	3B - Medium Sustain	3B - 9001 POST T48 - WT - INT PLUMB - DRAIN BACKING UP - Repair - [redacted] - 58254105	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11604964	3B - Medium Sustain	3B - 9001 POST 2J23 WRR - WT - INT PLUMB - LEAKING TOILET AND 2 OTHERS BAGGED DUE TO LOW WATER PRESSURE - REPAIR - [redacted] 622-7846 - SR# 3015174	Repair
11604991	3B - Medium Sustain	3B - 9001 2J23 MRR - WT - INT PLUMB - 1 TOILET/1 URINAL HAVE LOW WATER PRESSURE - REPAIR - [redacted] 622-7846 - SR# 3015185	Repair
11605008	3C - Low Sustain	3C - 9001 POST S50 - WT - INT PLUMB - WATER DRIPPING FROM OVERHEAD PIPE - REPAIR - [redacted] 622-7846 - SR# 3015190	Repair
11605063	3C - Low Sustain	3C - 9001 2C54 WRR - WT - INT PLUMB - FAUCET HAS WATER TURNED OFF DUE TO CONTINUOUSLY RUNNING - REPAIR - [redacted] 622-7846 - SR# 3015200	Repair
11606019	3B - Medium Sustain	3B - 9001 BTWN POSTS U28/U29 - WT - TAC HVAC - CONDENSATION WATER LEAK - REPAIR - [redacted] 622-7846	Repair
11606583	3C - Low Sustain	3C - 9001 W44 - WT - TAC STRUC - RELOCATE FIRE EXTINGUISHER - REPAIR - [redacted] - 622-7846	Repair
11606675	3C - Low Sustain	3C - 9001 V44 - WT - HONEYWELL - READD LIGHT SWITCH THAT DOES NOT WORK AFTER SWITCHING TO LEDS - REPAIR - [redacted] 622-7846 - SR# 3015744	Repair
11606712	3B - Medium Sustain	3B - 9001 MEN'S/WOMEN'S RR POST E30 - WT - HONEYWELL - LIGHTS OUT IN BATHROOMS - REPAIR - [redacted] 622-7846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11606750	3C - Low Sustain	3C - 9001 2U38(ISH) ORANGE DOOR - WT - TAC STRUC - DOOR CLOSER DOES NOT WORK - REPAIR - [redacted] 622-7846 - SR# 3015778	Repair
11606761	3C - Low Sustain	3C - 9001 RTPOST U-T 30/31 ASH 66 - WT - TAC STRUC - (PARTS 09-21/ 10-30) EXTERIOR ACCESS DOOR RUSTED;NEEDS REPLACED - [redacted] - 622-7846	Repair
11606834	3B - Medium Sustain	3B - 9001 K55 - WT - TAC HVAC - OPEN CHILLED WATER ISOLATION VALVE TO ASH 49 - REPAIR - [redacted] 622-7846 - SR# 3015828	Repair
11606877	3B - Medium Sustain	3B - 9001 BOILERS - WT - TAC HVAC - BAS: BOILERS ON MAIN 2 ARE IN ALARM - REPAIR - [redacted] 582-5009	Repair
11610140	3B - Medium Sustain	3B - 9001 between Post P36 and P37 - WT - TAC HVAC - chilled water line is leaking - [redacted] 818-6609	Repair
11611052	3A - High Sustain	3A- 9001 Post H30 Clean rm / upstairs - WT - HVAC TAC - Temp is to low - repair - [redacted] - 734--0322	Repair
11612784	3B - Medium Sustain	3B - 9001 POST G5 - WT - METAL - BAY DOOR NOT OPEING AUTOMATICALLY - Repair - [redacted] - 2742656	Repair
11613795	3C - Low Sustain	3C - 9001 2N-31 MEN ROOM - WT - INT PLUMB - TOILET IS BAGGED AND INOP - Repair - [redacted] - 2742656	Repair
11614005	3C - Low Sustain	3C - 9001 POST F23 - WT - LOCK - MAKE/INSTALL CORE FOR OFFICE DOOR 713D32 & MAKE 2 KEYS - REPAIR - [redacted] 582-4105	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11614640	3C - Low Sustain	3C - 9001 B46 - WT - TAC ALARMS - FF STROBE SHOWING NO ANSWER IN ROOM 225. NEED TO INVESTIGATE - REPAIR - [redacted] 582-4496	Repair
11614951	3B - Medium Sustain	3B - 9001 2S18, KC46A AT POST B52 - WT - LOCK - BUILD CORE FOR DOOR, KEY NOT WORKING - REPAIR - [redacted] - 6230072	Repair
11618844	3A - High Sustain	3A - 9001 POST B68 - WT - INT PLUMB - 3 BATHROOMS BACKING UP INTO BREAKROOM - REPAIR - [redacted] 622-7846	Repair
11618870	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 9001 - ALARMS - ANNUALWEEK 50	Maintenance
11618935	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - ALARMS - ANNUALWEEK 50	Maintenance
11619555	3C - Low Sustain	3C - 9001 ASH HOUSE 212 - WT - TAC HVAC - F/U K7446 REPAIR VFD DRIVE - REPAIR - [redacted] 582-4496 - 9001- ASH-212	Repair
11620030	3A - High Sustain	3A - 9001 DD31 - WT - INT PLUMB - STOP LEAK - Repair - [redacted] - 5826491	Repair
11620189	3C - Low Sustain	3C - 9001 POST AA40- WT - INT PLUMB - NOT HOT WATER TO BREAKROOM SINK - Repair - [redacted] - 582419	Repair
11620634	4A - High Enhance	4A - 9001 Post H48 - WT - CBR - Lease/Purchase & Install Modular SCI-Facility - [redacted] 736-2700 MAD22-176	Repair
11620701	3C - Low Sustain	3C - 9001 G5 - OP - Replace existing overhead door at post G5 - [redacted] 622-7846 MAD22-182 wesley programming	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11620955	4A - High Enhance	4A - 9001 B64 - WT - ENG EVAL - MXSG to install Fire Suppression for dust collector - [redacted] [redacted] 734-9453 MAD22-185	Repair
11621420	3B - Medium Sustain	3B - 9001 2C10 MRR - WT - INT PLUMB - SEVERAL TOILETS BAGGED DUE TO LOW WATER FLOW - REPAIR - [redacted] 622-7846 - SR# 3021474	Repair
11622069	3B - Medium Sustain	3B - 9001 2P53 MRR - WT - INT PLUMB - LOW WATER FLOW/SEVERAL CLOGGED AND BAGGED TOILETS - REPAIR - [redacted] 622-7846 - SR# 3021632	Repair
11622091	3C - Low Sustain	3C - 9001 2P53 - WT - TAC STRUC - SEVERAL DAMAGED/MISSING TILES IN STAIRWELL - REPAIR - [redacted] 622-7846 - SR# 3021642	Repair
11622104	3B - Medium Sustain	3B - 9001 2P53 WRR - WT - INT PLUMB - BRADLEY SINK NEEDS ADJUSTMENT - REPAIR - [redacted] [redacted] 622-7846 - SR# 3021650	Repair
11623875	3C - Low Sustain	3C - 9001 POST G27 - WT - LOCK - NEED CORE 713D32 MADE AND INSTALLED ON OFFICE DOOR - REPAIR - [redacted] 582-4105 - SR# 3022359	Repair
11624394	3B - Medium Sustain	3B - 9001 POST T44 - WT - METAL - ROLL UP OH DOOR OPENS AS SOON AS IT CLOSES - REPAIR - [redacted] 622-7846	Repair
11624821	3B - Medium Sustain	3B - 9001 S END - WT - INT ELEC - EXT LIGHTS INOP SENT FROM HONEYWELL - REPAIR - [redacted] [redacted] - 622-7846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11625008	3A - High Sustain	3A - 9001 MRR POST N45 - WT - INT PLUMB - MRR HAS LOW WATER PRESSURE, WRR IS WORKING FINE - REPAIR - [redacted] 582-4105	Repair
11626116	3C - Low Sustain	3C - 9001 ROOF TOP Q/P 36/37 - WT - LOCK - LOCKS ON DOORS TO ASH 56 INOP - REPAIR - [redacted] - 622-7846	Repair
11626130	3C - Low Sustain	3C - 9001 ROOF TOP Q/P 36/37 - WT - TAC STRUC- ROOF DRAIN CLOGGED - REPAIR - [redacted] - 622-7846	Repair
11626154	3C - Low Sustain	3C - 9001 ROOF TOP AA/BB 28/29 - WT - TAC STRUC- ROOF DRAIN COVER MISSING - REPAIR - [redacted] - 622-7846	Repair
11626550	3B - Medium Sustain	3B - 9001 NEAR POST D56 WAREHOUSE SR57 - WT - TAC HVAC - WATER LEAKING FROM CEILING - Repair - [redacted] - 541-9535	Repair
11626710	3B - Medium Sustain	3B - 9001 - WT - HONEYWELL - ADJUST LIGHTING SCHEDULES FOR ASH HOUSES - REPAIR - [redacted] 622-7846	Repair
11630033	3C - Low Sustain	3C - 9001 D25 - WT - TAC ALARM - FF 9001 WEST NAC PANEL SHOWING CHANNEL 2 TROUBLE. NEED TO TROUBLESHOOT - REPAIR - [redacted] - 582-4496	Repair
11630467	3C - Low Sustain	3C - 9001 POST EE44 - WT - PLUMB INT - F/U T5571 AND 11413980 LEAK IN DRAIN PIPE - REPAIR - [redacted] - 582-4196 - STORM	Repair
11630554	3B - Medium Sustain	3B - 9001 ROOM 115 - WT - INT PLUMB - FU 11604321 WATER HEATER PILOT LIGHT OUT - Repair - [redacted] - 7362705	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11631643	3A - High Sustain	3A - 9001 ROOM 125 SOUTH ADMIN - WT - INT ELEC - LOST POWER TO COMMS ROOM 125 - Repair - [redacted] - 736-2705	Repair
11631749	3B - Medium Sustain	3B - 9001 M19 - WT - INT ELEC - EMERGENCY EXIT LIGHTS OVER DOOR ARE VERY DIM/NOT WORKING - REPAIR - [redacted] 622-7846 - SR# 3026191	Repair
11631935	3C - Low Sustain	3C - 9001 B68 BREAKROOM - WT - INT PLUMB - PUT PLUGS INTO FLOOR DRAINS TO FORCE BACKUP INTO BATHROOMS - REPAIR - [redacted] 622-7846 - SR# 3026280	Repair
11632414	3C - Low Sustain	3C - 9001 POST O19 - WT - TAC ALARMS - F/U T3132 (PARTS ADD 03-06-23 REPAIR CHARGING BOARD AT 0-19 - REPAIR - [redacted] - 582-4496 - 9001-FA-1391	Repair
11633927	3B - Medium Sustain	3B - 9001 POST F12 - WT - BAS - LAB TEMP IS OUT OF TOLERANCE/AHU-2 - REPAIR - [redacted] 734-9377	Repair
11633935	3B - Medium Sustain	3B - 9001 POST 2W41 & 2W40 - WT - BAS - HVAC UNITS NEED CONNECTED TO EBI - REPAIR - [redacted] 734-9377	Repair
11635393	3C - Low Sustain	3C - 9001 CC49 DD47 and S56 - WT - LOCK - Need (3) lock cores for Key 701C17 - REPAIR- [redacted] - 582-4496	Repair
11636392	3B - Medium Sustain	3B - 9001 POST U44 - WT - TAC STRUC - CONCRETE FLOOR SUNKEN CAUSING TRIP/SLIP/FALL HAZARD - REPAIR - [redacted] 622-7846 - SR# 3028819	Repair
11636415	3C - Low Sustain	3C - 9001 I70 - WT - INT ELEC - EXPOSED WIRES HANGING OUT OF BOX AT WEST UPPER CORNER OF OH DOOR 9001-OD-07 - REPAIR - [redacted] 622-7846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11636435	3B - Medium Sustain	3B - 9001 S62 - WT - INT ELEC - EMERGENCY LIGHT IS VERY DIM - REPAIR - [redacted] 622-7846 - SR# 3028839	Repair
11636439	3C - Low Sustain	3C - 9001 Q62 - WT - INT ELEC - EMERGENCY LIGHT DIM - REPAIR - [redacted] 622-7846 - SR# 3028842	Repair
11636453	3C - Low Sustain	3C - 9001 POST A32 - WT - LOCK - REQUESTING 3 KEYS 720A7 - REPAIR - [redacted] 622-7846 - SR# 3028852	Repair
11639397	3A - High Sustain	3A - 9001 MRR E30 - WT - INT PLUMB - TOILET BACKED UP;WATER ON THE FLOOR - REPAIR - [redacted] 582-4105	Repair
11642057	3C - Low Sustain	3C - 9001 POST D6 ADMIN/BREAKROOM - WT - STRUC - DOOR HANDLE MISSING - REPAIR - [redacted] - 6227846	Repair
11642103	3C - Low Sustain	3C - 9001 POST E7 BREAKROOM - WT - LOCK - NEED TO FIND OUT WHAT LOCK CODE IS - REPAIR - [redacted] - 6227846	Repair
11642115	3C - Low Sustain	3C - 9001 POST E7 BREAKROOM - WT - TAC STRUC - DOOR WILL NOT CLOSE/LATCH - REPAIR - [redacted] 622-7846 - SR# 3031086	Repair
11642292	3B - Medium Sustain	3B - 9001 POST ROOM 149 S ADMIN - WT - LOCK- LOCK NOT WORKING RIGHT - Repair - [redacted] - 6230072	Repair
11642305	3B - Medium Sustain	3B - 9001 POST C5 OH DOOR - WT - METAL - AUTO/OPEN CLOSE IS NOT WORKING - REPAIR - [redacted] - 6227846	Repair
11642332	3B - Medium Sustain	3B - 9001 POST A15 - WT - TAC STRUC - EMERGENCY DOOR WILL NOT CLOSE - REPAIR - [redacted] - 6227846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11642353	3B - Medium Sustain	3B - 9001 POST Q30 - WT - LOCK - CAGE DOOR NEEDS REKEYED - REPAIR - [redacted] - 6227846	Repair
11643178	3C - Low Sustain	3C - 9001 ASH 212 - WT - TAC HVAC - F/U 11619555 REPAIR SHROUD ON MOTOR ON ASH 212 - REPAIR - [redacted] - 582-4496	Repair
11645784	3B - Medium Sustain	3B - 9001 POST E33 - WT - TAC STRUC - REINSTALL STRIKE PLATE - [redacted] - 2742656	Repair
11646397	3B - Medium Sustain	3B - 9001 ROOM 118 S ADMIN - WT - LOCK - 2 CORES BUILT - Repair - [redacted] - 6230072	Repair
11647599	3B - Medium Sustain	3B - 9001 POST U32-U33 - WT - TAC HVAC - DUCT CONDENSATION LEAK - Repair - 3033483 - [redacted] - 582-4256	Repair
11647854	3C - Low Sustain	DEFAULT - Work Task Template - Corrective Maintenance-Other Electrical Need	Repair
11647909	3B - Medium Sustain	3B - 9001 POST CDX33 - WT - INT ELEC - EMERGENCY LIGHT INOP - REPAIR - [redacted] - 6227846	Repair
11649492	3B - Medium Sustain	3B - 9001 Room 186 - WT - ALARM - Security alarm, alarm point 3885 - repair - [redacted] 582-1965	Repair
11651179	3B - Medium Sustain	3B -9001 B52 ELEV - WT - ELEVATOR - ELEVATOR MAKING GRINDING NOISES - Repair - [redacted] - 8211118	Repair
11652449	3C - Low Sustain	3C - 9001 POST 2J21 - WT - TAC HVAC - EXHAUST FAN MAKING NOISE - REPAIR - [redacted] - 6227846	Repair
11652467	3B - Medium Sustain	3B - 9001 POST A65 - WT - INT ELEC - EMERGENCY LIGHT INOP - REPAIR - [redacted] - 6227846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11652488	3C - Low Sustain	3C - 9001 POST A65 DOOR S65 - WT - TAC STRUC - DOOR WILL NOT CLOSE ON ITS OWN - REPAIR - [redacted] - 6227846	Repair
11653169	3C - Low Sustain	3C - 9001 F55 - WT - INT PLUMB - LEAK COMING THOUGH METAL FLOOR - [redacted] - 623-0072	Repair
11655908	3B - Medium Sustain	40	Repair
11656146	3B - Medium Sustain	3B- 9001 Post AA40 - WT - TAC HVAC - air conditioner is leaking in outside breakroom - repair - [redacted] 582-4196	Repair
11656869	3B - Medium Sustain	3B - 9001 ZONE 4 - WT - TAC ALARM - SUPERVISORY ALARM GOING OFF - Repair - [redacted] - 734-7964	Repair
11657066	3B - Medium Sustain	3B - 9001 POST C5 DOOR W5-3 - WT - METAL - OVERHEAD WILL NOT SHUT - Repair - [redacted] - 274-2656	Repair
11657120	3B - Medium Sustain	3B - 9001 POST G5 - WT - METAL - OH DOOR NOT WORKING, TRACKS NEED ADJUSTED - Repair - [redacted] - 2742656	Repair
11657241	3C - Low Sustain	3C-9001 TRF 4- WT- TAC ALARM- FF NODE 6 SHOWING CARD TROUBLE ON TRF 4- REPAIR- [redacted] - 582-4496	Repair
11657257	3C - Low Sustain	3C- 9001 TRF 3- WT - TAC ALARM- NODE 5 SHOWING TROUBLE ON DUCT DETECTOR THAT IS NORMAL. NEED TO INVESTIGATE- REPAIR- [redacted] -582-4496	Repair
11659195	3B - Medium Sustain	3B - 9001 ASH 203 - WT - HONEYWELL - LITTLE TO NOT CHILL WATER FLOW/CHECK STRAINER/VALVE/ACTUATORS - REPAIR - [redacted] 622-7846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11659202	3B - Medium Sustain	3B - 9001 Ash 202 - WT - TAC HVAC - Restricyed water flow in coil - Repair - [redacted] - 622-7846 - SR3040639	Repair
11659207	3B - Medium Sustain	3B - 9001 ASH 201 - WT - TAC HVAC - Restricted flow through coil - repair - [redacted] - 622-7846 - SR3040645	Repair
11659306	3B - Medium Sustain	3B - 9001 EXT "A" SOUTH WALL - WT - INT ELEC - EXTERIOR WALL HAS NO POWER TO EXT LIGHTS - REPAIR - [redacted] - 6227846	Repair
11659449	3B - Medium Sustain	3B - 9001 POST F67 - WT - INT ELEC - EMERGENCY LIGHT INOP - REPAIR - [redacted] - 6227846	Repair
11660711	3B - Medium Sustain	3B - 9001 Posts E67 & E68 - WT - TAC HVAC - repair leaking chilled water line - repair - [redacted] - 622-7846 - SR3041475	Repair
11663683	3B - Medium Sustain	3B - 9001 ROOM 186 - WT - ALARM CONT - VINDICATOR TESTING - REPAIR - [redacted] - 7345806	Repair
11663702	3B - Medium Sustain	3B - 9001 POST AA40 - WT - TAC HVAC - CHILLED WATER LINE DRIPPING - REPAIR - [redacted] 622-7846	Repair
11663726	3B - Medium Sustain	3B - 9001 C5 OH DOOR - WT - METAL - OH DOOR WILL NOT CLOSE - REPAIR - [redacted] 622-7846	Repair
11663897	3B - Medium Sustain	3B - 9001 - WT - PEST - SKUNK REPORTED - REPAIR - [redacted] - 7343848	Services
11664320	3C - Low Sustain	3C - 9001 COL DD23 - SVC FLOORING - 20999 - Construct REACT Phase II Training and Materials Testing Lab - [redacted] - 405 582 9034	Repair
11664735	3B - Medium Sustain	3B - 9001 POST D69 - WT - HONEYWELL - EMERGENCY LIGHTS CYCLING ON AND OFF - REPAIR - [redacted] 622-7846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11664817	3A - High Sustain	C/O - 3A - 9001 POST U31 - WT - INT ELEC - BLOWN BREAKER - Repair - [redacted] - 5824105	Repair
11666061	3B - Medium Sustain	3B - 9001 ROOM 186 - WT - LOCK - NEED KEYS AND CORES - REPAIR - [redacted] - 6230072	Repair
11667788	3B - Medium Sustain	3B - 9001 Post X39 - WT - TAC HVAC - A/C leak - repair - [redacted] 582-4196 - SR 3044696	Repair
11670176	3B - Medium Sustain	3B - 9001 ASH21 WT - TAC HVAC - belts are broken and need to be replaced - repair - [redacted] 622-7846 - SR 3046072	Repair
11672036	3C - Low Sustain	3C - 9001 - WT - POWER PRO - GENERATOR SHOWING LOW COOLANT - Repair - [redacted] - 734-5806 - EG09001-E	Repair
11672454	3B - Medium Sustain	3B - 9001 J56 - WT - EXT PLUMB - FF HYDRO WASH MANHOLES FULL OF DEBRIS - REPAIR - [redacted] - 7342753	Repair
11672509	3C - Low Sustain	3C - 9001 POST DD50 - WT - EVAL COMPLETE - LSA TO SUPPORT INSTALL OF NEW WALLS, DOORS, DROP CEILING, UTILITIES - [redacted] - 405 734 7954	Repair
11672577	3C - Low Sustain	3C - 9001 551 OFFICES & TRAINING RM - CBM - REMOVE & REINSTALL TILE & CARPET - [redacted] - 405 582 6912	Repair
11672583	3B - Medium Sustain	3B - 9001 POST E13 AND F16 - WT - HONEYWELL - F/U 11587814-2 SETS OF LIGHTS NOT WORKING - REPAIR - [redacted] - 734-6281 - HONEYWELL	Repair
11673046	3C - Low Sustain	3C - 9001 F68 HVAC AHUS - WT - OP - Correct lack of cooling - [redacted] - 405 622 7846 - 450	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11673607	3C - Low Sustain	3C - 9001 POST BX33 S ADMIN - WT - PAINT - FRONT DOOR TO FACILITY MANAGER OFFICE NEEDS REPAINTED - REPAIR - [redacted] 622-7846 - PAINT	Repair
11673867	3C - Low Sustain	3C - 9001 C68/E68 - WT - HONEYWELL - SEVERAL LIGHTS OUT IN CAGED AREA - REPAIR - [redacted] 622-7846 - SR# 3048534	Repair
11674211	3B - Medium Sustain	3B - 9001 POST DD20 - WT - TAC STRUC - REPAIR STEEL BOLLARD - Repair - [redacted] - 5824105	Repair
11674220	3B - Medium Sustain	3B - 9001 MEZZ 3 2ND FLR - WT - TAC ALARM - STROBE MAKING WEIRD NOISES - Repair - [redacted] - 5821118	Repair
11674658	3C - Low Sustain	3C-9001 ASH HOUSE 202 - WT - F/U 11660711 INSULATE- INSULATE CHILL WATER LINES IN ASH HOSUE 202-REPAIR-[redacted] -582-4496	Repair
11674824	3C - Low Sustain	3C - 9001 MEZZ 3 NE SECTION - WT - HONEYWELL - MOTION SENSOR FOR LIGHT IS MAKING A NOISE LIKE IT IS GOING DEAD - REPAIR - [redacted] 582-1118	Repair
11676795	3A - High Sustain	3A - 9001 WOMENS RR POST G39 - WT - INT PLUMB - TOILET LEAKING - Repair - [redacted] 2742656	Repair
11678724	3B - Medium Sustain	3B - 9001 H42 - WT - STRUC - West door to paint storage room doesn't latch - [redacted] 622-7846 - SR3051071	Repair
11680409	3B - Medium Sustain	3B - 9001 POST L23 BREAKROOM - WT - TAC STRUC - NEED CABINET FLOOR REPLACED - REPAIR - [redacted] - 5824105	Repair
11680457	3B - Medium Sustain	3B - 9001 POST A32 - WT - LOCK - NEED KEY MADE - REPAIR - [redacted] - 5824105	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11680603	3B - Medium Sustain	3B - 9001 POST EE39, DOOR N38 - WT - TAC STRUC - EXT DOOR WILL NOT CLOSE - REPAIR - [redacted] - 8820901	Repair
11681123	3B - Medium Sustain	3B - 9001 K55 ASH HOUSE 49-WT - HONEYWELL - F/U 11606834 CHECK ON VALVE, TAC HVAC NEEDS OPEN AT THIS TIME - REPAIR - [redacted] - 582-4496	Repair
11683910	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 14	Maintenance
11683911	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 14	Maintenance
11684265	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 15	Maintenance
11684266	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 15	Maintenance
11684267	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 15	Maintenance
11684268	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 15	Maintenance
11684269	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 15	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11684270	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 15	Maintenance
11684271	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 15	Maintenance
11684273	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 15	Maintenance
11684274	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 15	Maintenance
11684275	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 15	Maintenance
11684276	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 15	Maintenance
11684278	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 15	Maintenance
11684279	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 15	Maintenance
11684280	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 15	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11684281	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 15	Maintenance
11684282	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 15	Maintenance
11684283	2A - Preventive Maintenance	B20352251950 - S - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 15	Maintenance
11689813	3B - Medium Sustain	3B - 9001 POST Q20 to Q44 - F/U WT 11655908 - HONEYWELL - REPAIR LIGHTS - REPAIR - POC'S ARE [redacted] @ 405.546.9124 - SR3053764	Repair
11690076	3C - Low Sustain	3C - 9001 POST F12 LAB - WT - INT ELEC - PAINT SAMPLE STORAGE CABINETS NEED TO BE GROUNDED - REPAIR - [redacted] 739-4246	Repair
11690084	3B - Medium Sustain	3B - 9001 2W43 MRR - WT - INT PLUMB - URINAL CONSTANTLY RUNNING - REPAIR - [redacted] 582-4105 - SR# 3053973	Repair
11690407	3C - Low Sustain	3C - 9001 Q52 - WT - INT PLUMB - MOP CLOSET FAUCET LEAKS WHEN TURNED ON - REPAIR - [redacted] 622-7846 - SR# 3054149	Repair
11690408	3B - Medium Sustain	3B - 9001 E30 MRR - WT - INT PLUMB - TOLET CLOGGED/BAGGED - REPAIR - [redacted] 622-7846 - SR# 3054150	Repair
11690427	3C - Low Sustain	3C - 9001 E30 WRR - WT - INT PLUMB - FARTHEST RIGHT SINK DRAINING SLOWLY - REPAIR - [redacted] 622-7846 - SR# 3051466	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11690475	3C - Low Sustain	3C - 9001 ROOFTOP Q/R53 - WT - TAC STRUC- 2 STORM DRAIN SCREENS NEED CLEANED - REPAIR - [redacted] 622-7846 - SR# 3054201	Repair
11690534	3C - Low Sustain	3C - 9001 2W22 WRR - WT - PEST - ERADICATE DRAIN FLIES - REPAIR - [redacted] 622-7846	Services
11690542	3B - Medium Sustain	3B - 9001 POST T48 - WT - INT PLUMB - DRAIN CLOGGED; CAUSING FLOODING - REPAIR - [redacted] 582-4105 - SR# 3054240	Repair
11690552	3C - Low Sustain	3C - 9001 BX33 S ADMIN - WT - PEST - NEED MOUSE TRAPS - REPAIR - [redacted] 622-7846	Services
11690556	3B - Medium Sustain	3B - 9001 POST D8 - WT - INT PLUMB - RELIEF VALVE LEAKING WATER - REPAIR - [redacted] 582-4105 - SR# 3054254	Repair
11690564	3C - Low Sustain	3C - 9001 POST BX33 South Admin MRR - WT - TAC STRUC - REPAIR HOLE IN WALL - Repair - [redacted] - 622-7846	Repair
11690681	3A - High Sustain	3A - 9001 POST Q59 - WT - INT PLUMB - TOILETS ARE BACKING UP WITH DIRTY WATER (ORANGE COLOR) - REPAIR - [redacted] - 855-3012	Repair
11692039	3B - Medium Sustain	3B- 9001 post D63 - WT - intplumb - video scope sewer line in problem area - repair - [redacted] - 622-7846 - SR3055105	Repair
11693628	3A - High Sustain	3A - Bldg 9001, base of post H42 - WT - TAC HVAC - base of post H42 has significant leak - repair - [redacted] - 582-4105 - SR3055717	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11693783	3B - Medium Sustain	3B - 9001 ASH-67 NEAR COLUMN U32 - WT - HONEYWELL - FREEZE STAT IN ALARM FAN IS STILL OPERATION - REPAIR - [redacted] - 405-886-5386 - CNTR - SR3055814	Repair
11694408	3A - High Sustain	3A - 9001 BASE OF POST H42 - WT - INT PLUMB - REF 11693628 SIGNIFICANT LEAK - REPAIR - [redacted] 582-4105	Repair
11694489	3B - Medium Sustain	3B - 9001 Post S-29 - WT - Intplumb - pipe leaking on attendents work cage - repair - [redacted] - 582-4105 - SR3056290	Repair
11694501	3C - Low Sustain	3C - 9001 Post R61 Overhead door - WT - Metal - adjust sensors, door to open when vehicle entering - repair - [redacted] - 582-4105 - SR3056303	Repair
11694718	3B - Medium Sustain	3B - 9001 N 38 - WT - TAC STRUC - DOOR HINGE FELL OFF - Repair - [redacted]	Repair
11694795	2A - Preventive Maintenance	B20352251950 - A - Door, emergency egress, swinging - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 38	Maintenance
11695175	3C - Low Sustain	3C -9001 Cx - WT - TAC Structures - repaint facility manager's garage door - repair - [redacted] - 622-7846 - SR3056700	Repair
11695183	3B - Medium Sustain	3B - 9001 A54 foyer ent- WT - INT ELEC - Emergency exit/light combo does not test - [redacted] 622-7846 - SR3056704	Repair
11695192	3C - Low Sustain	3C - 9001 B62-63 - WT - TAC HVAC - Chilled water supply line is dripping or has condensation - [redacted] 622-7846 - SR3056708	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11695249	3C - Low Sustain	3C - 9001 X23 - WT - INT ELEC - several breakroom emergency exit lights do not test - repair - [redacted] 622-7846 - SR3056727	Repair
11695335	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 39	Maintenance
11695336	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 39	Maintenance
11695337	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 39	Maintenance
11695338	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 39	Maintenance
11695339	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 39	Maintenance
11695340	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 39	Maintenance
11695341	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 39	Maintenance
11695343	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 39	Maintenance
11695344	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 39	Maintenance
11695345	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 39	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11695406	3B - Medium Sustain	3B - 9001 A32 - WT - HONEYWELL - program exterior lights to turn off during the day - repair - [redacted] 622-7846 - SR3056811	Repair
11697072	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 40	Maintenance
11697073	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 40	Maintenance
11697074	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 40	Maintenance
11697075	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 40	Maintenance
11697076	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 40	Maintenance
11697077	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 40	Maintenance
11697078	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 40	Maintenance
11697079	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 40	Maintenance
11697263	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 44	Maintenance
11697264	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 44	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11697266	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 44	Maintenance
11697267	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 44	Maintenance
11697268	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 44	Maintenance
11697269	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 44	Maintenance
11697271	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 44	Maintenance
11697272	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 44	Maintenance
11697273	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 44	Maintenance
11697274	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 44	Maintenance
11697275	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 44	Maintenance
11697276	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 44	Maintenance
11697324	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 38	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11697351	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 44	Maintenance
11697352	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 44	Maintenance
11697353	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 44	Maintenance
11697404	3A - High Sustain	3A - 9001 ROOM 104 - WT - TAC HVAC - UNIT IN COMM CLOSET POWERING OFF RANDOMLY - Repair - [redacted] 4922496	Repair
11697411	3C - Low Sustain	3C- 9001 BX - WT - Lock - replace door handle assembly - repair - [redacted] - 622-7845 - SR3057546	Repair
11697432	3B - Medium Sustain	3B - 9001 NW S-32 Doors - WT - TAC HVAC - foyer ventilation is too hot/not working - repair - [redacted] - 622-7846 - SR3057551	Repair
11697436	3B - Medium Sustain	3B - 9001 Post X-31 MRR - WT - Intplumb - 2nd handicap toilet is bagged and leaking - repair - [redacted] - 622-7846 - SR3057552	Repair
11697450	3B - Medium Sustain	3B - 9001 Post C-20 WRR - WT - Intplumb - bagged toilet will not flush - repair - [redacted] - 622-7846 - SR3057559	Repair
11697556	3C - Low Sustain	3C- 9001 BOILER G31- WT- TAC HVAC- REPAIR BOILER FLUE STACK BOILER G31- REPAIR - [redacted] -582-1196 - SR3057624	Repair
11697701	3C - Low Sustain	3C - 9001 POST W-43 - WT- PLUMB INT - F/U 11403984 STORM DRAIN LEAKING FROM PIPE - repair - [redacted] - 582-4496 - SR2953036	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11697705	3C - Low Sustain	3C-9001 ROOM 215 Mezz 3- WT-Intelec - F/U 11674220 LIGHT MOTION SENSOR MAKING A HIGH PITCH NOISE - repair - [redacted] - 582-4496 - SR3057670	Repair
11699406	3A - High Sustain	3A - 9001 POST H45 - WT - LOCK - DOOR TO SECURE ROOM WON'T LATCH LEAVING ROOM UNSECURED - REPAIR - [redacted] - 550-9580 - KH080502	Repair
11699784	3B - Medium Sustain	3B - 9001 2241 - WT - LOCK - CIPHER LOCKS HAVE NO CODES OR CORES - REPAIR - [redacted] 582-4105 - RE0022	Repair
11700282	3C - Low Sustain	3C - 9001 E30 WRR - WT - INT PLUMB - F/U 11690427 FARTHEST RIGHT SINK DRAINING SLOWLY - REPAIR - [redacted] - 405-734-7098	Repair
11702464	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 38	Maintenance
11702465	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 38	Maintenance
11702466	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 38	Maintenance
11703221	2A - Preventive Maintenance	C10251102950 - A - Fire doors, sliding - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 41	Maintenance
11703222	2A - Preventive Maintenance	C10251102950 - A - Fire doors, sliding - TINKER AFB - 9001 - TACX_STRUCTURES - ANNUALWEEK 41	Maintenance
11703284	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 1	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11703287	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 1	Maintenance
11703372	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703373	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703374	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703381	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703382	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703383	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703437	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703438	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703439	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703440	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11703441	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703442	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703443	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703458	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703459	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703460	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703461	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703462	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703463	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703464	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703537	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11703538	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703539	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703540	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703550	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703551	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703552	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703553	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703603	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703604	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11703605	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703606	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703615	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703616	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703617	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703618	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 23	Maintenance
11703673	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703674	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703675	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703676	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11703677	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703678	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703723	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703724	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703725	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703726	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703837	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703838	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703839	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703840	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11703841	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703842	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703843	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703844	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703845	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703846	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703847	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703848	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703849	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11703850	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 32	Maintenance
11703909	2A - Preventive Maintenance	D5035710195005 - A - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 36	Maintenance
11703910	2A - Preventive Maintenance	D5035710195005 - A - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 36	Maintenance
11703911	2A - Preventive Maintenance	D5035710195005 - A - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 36	Maintenance
11703912	2A - Preventive Maintenance	D5035710195005 - A - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 36	Maintenance
11703913	2A - Preventive Maintenance	D5035710195005 - A - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 36	Maintenance
11703914	2A - Preventive Maintenance	D5035710195005 - A - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 36	Maintenance
11703915	2A - Preventive Maintenance	D5035710195005 - A - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 36	Maintenance
11703944	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 36	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11703945	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 36	Maintenance
11703946	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 36	Maintenance
11703947	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 36	Maintenance
11703948	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 36	Maintenance
11703949	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 36	Maintenance
11703950	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 50	Maintenance
11704768	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 50	Maintenance
11704769	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 50	Maintenance
11704775	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 50	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11704776	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 50	Maintenance
11704875	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 7	Maintenance
11704876	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 7	Maintenance
11704877	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 7	Maintenance
11704878	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 7	Maintenance
11704911	2A - Preventive Maintenance	D50357101950 - S - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 11	Maintenance
11704921	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 11	Maintenance
11704943	2A - Preventive Maintenance	D5035710195005 - S - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 11	Maintenance
11704944	2A - Preventive Maintenance	D5035710195005 - S - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 11	Maintenance
11704945	2A - Preventive Maintenance	D5035710195005 - S - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 11	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11704946	2A - Preventive Maintenance	D5035710195005 - S - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 11	Maintenance
11704947	2A - Preventive Maintenance	D5035710195005 - S - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 11	Maintenance
11704948	2A - Preventive Maintenance	D5035710195005 - S - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 11	Maintenance
11704949	2A - Preventive Maintenance	D5035710195005 - S - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 11	Maintenance
11704978	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 11	Maintenance
11704979	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 11	Maintenance
11704980	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 11	Maintenance
11704981	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 11	Maintenance
11704982	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 11	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11704983	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 11	Maintenance
11704984	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 11	Maintenance
11705047	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705048	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705049	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705056	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705057	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705058	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705120	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705121	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11705122	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705123	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705124	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705125	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705126	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705127	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705144	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705145	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705146	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11705147	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705148	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705149	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705150	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705151	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705238	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705239	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705240	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705242	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11705243	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705254	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705255	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705256	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705257	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705258	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 28	Maintenance
11705427	2A - Preventive Maintenance	D5035710195008 - AF4 - FACP 101 to 300 Smoke Devices - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 42	Maintenance
11705428	2A - Preventive Maintenance	D5035710195008 - AF4 - FACP 101 to 300 Smoke Devices - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 42	Maintenance
11705429	2A - Preventive Maintenance	D5035710195008 - AF4 - FACP 101 to 300 Smoke Devices - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 42	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11705430	2A - Preventive Maintenance	D5035710195008 - AF4 - FACP 101 to 300 Smoke Devices - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 42	Maintenance
11705431	2A - Preventive Maintenance	D5035710195008 - AF4 - FACP 101 to 300 Smoke Devices - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 42	Maintenance
11705467	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 25	Maintenance
11705468	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 25	Maintenance
11705469	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 25	Maintenance
11705470	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 25	Maintenance
11705471	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 25	Maintenance
11705472	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 25	Maintenance
11705485	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 25	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11705486	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 25	Maintenance
11705487	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 25	Maintenance
11705488	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 25	Maintenance
11705489	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 25	Maintenance
11705490	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 25	Maintenance
11705547	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 34	Maintenance
11705548	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 34	Maintenance
11705549	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 34	Maintenance
11705550	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 34	Maintenance
11705572	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 34	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11705573	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 34	Maintenance
11705616	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 34	Maintenance
11705617	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 34	Maintenance
11705618	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 34	Maintenance
11705619	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 34	Maintenance
11705620	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 34	Maintenance
11705621	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 34	Maintenance
11705622	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 34	Maintenance
11705623	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 34	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11705624	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 34	Maintenance
11705625	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 34	Maintenance
11705681	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 48	Maintenance
11705682	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 48	Maintenance
11705683	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 48	Maintenance
11705684	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 48	Maintenance
11705685	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 48	Maintenance
11705686	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 48	Maintenance
11705687	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 48	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11705688	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 48	Maintenance
11708220	3B - Medium Sustain	3B - 9001 Post E-20 - WT - TAC STRUCT - Entry door knob by cage needs to be fixed - repair - [redacted] - 582-4105	Repair
11708267	3B - Medium Sustain	3B - 9001 Post X-35 - WT - TAC HVAC - A/C is leaking water on two desks - repair - [redacted] - 582-4196	Repair
11708771	3B - Medium Sustain	3B - 9001 PostC-70 men's R/R - WT - Intplumb- 2 urinals are barely draining - repair - [redacted] - 323-0319	Repair
11709601	2A - Preventive Maintenance	D5035710195008 - AF4 - FACP 101 to 300 Smoke Devices - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 44	Maintenance
11709602	2A - Preventive Maintenance	D5035710195008 - AF4 - FACP 101 to 300 Smoke Devices - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 44	Maintenance
11709603	2A - Preventive Maintenance	D5035710195008 - AF4 - FACP 101 to 300 Smoke Devices - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 44	Maintenance
11709614	3C - Low Sustain	3C - 9001 POST V 19 - WT - TAC HVAC - VERIFY OPERATION OF UNITS IN AREA - Repair - [redacted] - 5824496	Repair
11709727	2A - Preventive Maintenance	D5035710195008 - AF4 - FACP 101 to 300 Smoke Devices - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 40	Maintenance
11709730	2A - Preventive Maintenance	D5035710195008 - AF4 - FACP 101 to 300 Smoke Devices - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 40	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11709765	2A - Preventive Maintenance	D5035710195008 - BE - FACP 101 to 300 Smoke Devices - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 40	Maintenance
11709766	2A - Preventive Maintenance	D5035710195008 - BE - FACP 101 to 300 Smoke Devices - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 40	Maintenance
11710322	3C - Low Sustain	3C - 9001 - WT - INT ELEC - REF 11599164 ASSIST PLUMBING W/ DISCONNECT OF WATER HEATER & RECONNECT OF NEW UNIT - REPAIR - [redacted] 734-2753	Repair
11711175	3C - Low Sustain	REJECT - ICE MACHINES BELONG TO M.A.D. - DEFAULT - Work Task Template - Corrective Maintenance-Leaks	Repair
11711227	3B - Medium Sustain	3B - 9001 POST V40 - WT - TAC HVAC - A/C NOT WORKING - REPAIR - [redacted] 582-4196	Repair
11711941	3C - Low Sustain	3C - 9001 AA40 - WT - INT PLUMB - FF EVALUATE/REPAIR ISSUE WITH WATER HEATER - REPAIR - [redacted] 734-2753	Repair
11712143	3C - Low Sustain	3C - 9001 CHANNEL 2 - WT - TAC ALARM - (PART 09-07/11/18/2022)SHOWING MISSING DEVICE POST X41 - REPAIR - [redacted] 582-4496 - 9001-FA-1398A	Repair
11712277	3B - Medium Sustain	3B - 9001 DR S54 FOYER - WT - TAC HVAC - CHECK/REPAIR LEAKS ABOVE DROP CEILING - REPAIR - [redacted] 622-7846	Repair
11712300	3B - Medium Sustain	3B - 9001 EXT DR S54 FOYER - WT - INT ELEC - EMERGENCY/EXIT LIGHT COMBO DOES NOT TEST/WORK - REPAIR - [redacted] 622-7846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11712326	3B - Medium Sustain	3B - 9001 DR S47 FOYER - WT - INT ELEC - EMERGENCY/EXIT LIGHT COMBO DOES NOT TEST/WORK - REPAIR - [redacted] 622-7846	Repair
11712446	3C - Low Sustain	3C - 9001 POST 2W40 WOMENS RR - WT - TAC STRUC - REPLACE MISSING CEILING TILE - REPAIR - [redacted] - 622-7846	Repair
11712481	3C - Low Sustain	3C - 9001 DR S47 FOYER - WT - TAC HVAC - CHECK/REPAIR LEAKS ABOVE CEILING INSIDE FOYER - REPAIR - [redacted] 622-7846	Repair
11712538	3C - Low Sustain	3C - 9001 DR S47 FOYER - WT - TAC HVAC - UNIT IS VERY DIRTY AND NOT WORKING WELL - REPAIR - [redacted] 622-7846	Repair
11712562	3B - Medium Sustain	3B - 9001 DR S31 - WT - INT ELEC - EXTERIOR LIGHT IS MISSING - REPAIR - [redacted] 622-7846	Repair
11712846	3C - Low Sustain	3C - 9001 U38/39 ASH 71 - WT - HONEYWELL - TURNED OFF DUE TO CHRONIC LEAK ISSUE - REPAIR - [redacted] 622-7846	Repair
11712872	3B - Medium Sustain	3B - 9001 R19 - WT - INT ELEC - DOOR WR2 EMERGENCY EXIT LIGHT MISSING COVER - REPAIR - [redacted] 622-7846	Repair
11712891	3B - Medium Sustain	3B - 9001 2T42 JAYHAWK CAFE - WT - TAC HVAC - A/C HAS NOT BEEN WORKING FOR A LONG TIME - REPAIR - [redacted] 622-7846	Repair
11712910	3C - Low Sustain	3C - 9001 B5 - WT - INSULATOR - PLUG 2 SMALL HOLES IN EXTERIOR WALL - REPAIR - [redacted] 622-7846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11713201	3C - Low Sustain	3C - 9001 DD52 WRR - WT - INT PLUMB - SINK/TOILET WATER IS ORANGE AND LOOKS SANDY - REPAIR - [redacted] 582-4496	Repair
11713338	3B - Medium Sustain	3B - 9001 H45 - WT - TAC STRUC - DOOR CLOSER NOT CLOSING ALL THE WAY FOR ACCESS CONTROL - REPAIR - [redacted] 582-1118	Repair
11713363	3C - Low Sustain	3C - 9001 S ADMIN RM 155 - WT - INT PLUMB - HANDICAP STALL NOT FLUSHING - REPAIR - [redacted] 582-1118	Repair
11713405	3B - Medium Sustain	3B - 9001 POST E45 - WT - SPRINK - FIRE SUPRESSION SYSTEM DRIPPING - REPAIR - [redacted] 582-1118	Repair
11713449	3B - Medium Sustain	3B - 9001 KC46 POST B52 - WT - SUB ELEVATOR - ELEVATOR MAKING GRINDING NOISE - REPAIR - [redacted] 582-1118	Repair
11713538	3C - Low Sustain	3C - 9001 POST D23 CAGE - WT - TAC STRUC - DOOR KNOB LOOSE AND NEEDS TIGHTENED - REPAIR - [redacted] 582-4105	Repair
11713799	4A - High Enhance	4A - 9001 M50- P55W - construct admin lab space - SVC FLOORING - 20128 - [redacted] - 405 736 4622	Repair
11714030	3C - Low Sustain	3C - 9001 DD25 - WT - TAC ALARM - FF NEED TO MOVE PULL STATION TO NEW BLDG - REPAIR - [redacted] 582-4496	Repair
11714051	3C - Low Sustain	3C - 9001 AH41 - WT - TAC ALARM - FF AH41 SUPPLY DUCT DETECTOR SHOWING EXCESSIVLY DIRTY @ K40 - REPAIR - [redacted] 582-4496	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11714098	3C - Low Sustain	3C - 9001 AH110 - WT - TAC ALARM - FF AH110 SUPPLY DUCT DETECTOR SHOWING EXCESSIVELY DIRTY - REPAIR - [redacted] 582-4496	Repair
11714998	3B - Medium Sustain	3B - 9001 A22 - WT - DOOR ELEC - AUTO OPEN/CLOSE FOR INT. PEDESTRIAN DOORS S22 DOES NOT WORK; CURRENTLY PROPPED OPEN - REPAIR - [redacted] 622-7846	Repair
11717953	3A - High Sustain	3A - 9001 ROOM 144 - WT - TAC STRUC - DOOR DOESNT CLOSE - Repair - [redacted] 7368784	Repair
11718893	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 9	Maintenance
11718894	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 9	Maintenance
11718897	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 9	Maintenance
11718898	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 9	Maintenance
11718900	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 9	Maintenance
11718903	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 9	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11718906	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 9	Maintenance
11718910	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 9	Maintenance
11718911	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 9	Maintenance
11718912	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 9	Maintenance
11718917	2A - Preventive Maintenance	D5035710195005 - Q - Unmonitored FACP (Monthly) - TINKER AFB - 9001 - TACX_ALARMS - ANNUALWEEK 9	Maintenance
11724138	3C - Low Sustain	3C - 9001 B5 - WT - TAC STRUC - PATCH HOLES IN WALL - REPAIR - [redacted] 582-4496	Repair
11724230	3C - Low Sustain	3C - 9001 B5 - WT - SHEET METAL - PATCH HOLES IN SHEET METAL F/U 11712910 - REPAIR - [redacted] [redacted] 622-7846	Repair
11724329	3B - Medium Sustain	3B - 9001 2C11 MRR - WT - INT PLUMB - LITTLE TO NO WATER PRESSURE IN TOILETS/URINALS; 1 TOILET BAGGED - REPAIR - [redacted] 582-4105	Repair
11724573	3B - Medium Sustain	3B - 9001 C70 MRR - WT - INT PLUMB - URINAL OVERFLOWING ONTO THE FLOOR - REPAIR - [redacted] 622-7846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11724604	3A - High Sustain	3A - 9001 D11 UPSTAIRS - WT - INT PLUMB - RR OVERFLOWING - REPAIR - [redacted] 582-4496	Repair
11726045	3C - Low Sustain	3C - 9001 FA PANEL - WT - TAC ALARM - ASSISTING JCI WITH FIRE ALARM TESTING - REPAIR - [redacted] - 582-4496	Repair
11726072	3B - Medium Sustain	3B- 9001 LEAN TO POST X-19/Y-19- WT - SPRINK - TROUBLESHOOT/REPAIR SPRINK SYSTEM -REPAIR - [redacted] 582-4496	Repair
11726078	3C - Low Sustain	3C - 9001 LEAN TO POST X-19/Y-19 - WT - TAC ALARM - TROUBLESHOOTING/REPAIR OF SPRINK SYSTEM - REPAIR - [redacted] 582-4496	Repair
11726307	4A - High Enhance	4A - 9001 G32 - CBR - REVIEW LOCATION OF CONTRACTOR FOUNDATION - [redacted] - 405 582 4095	Repair
11727468	3C - Low Sustain	3C - 9001 - WT - PLUMB INT - F/U 11708771 UNCLOG URINALS - REPAIR - [redacted] - 405-734-7098	Repair
11729178	3B - Medium Sustain	3B - 9001 Post W-43 - WT - Sub elevator - Elevator isn't working properly - [redacted] - 274-2656	Repair
11729472	3B - Medium Sustain	3B - 9001 POST V45 - WT - INT PLUMB - INOP BAGGED URINAL IN MENS ROOM - REPAIR - [redacted] 582-4105	Repair
11730509	3C - Low Sustain	3C - 9001 KC46 AHU - WT - HONEYWELL - F/U 11540416 CHECK HONEYWELL UNIT TO SEE IF RUNNING (JAVA CAFE) - REPAIR - [redacted] -582-4496	Repair
11730821	3C - Low Sustain	3C - 9001 ROOM 216 MEZZ 3 - WT - TAC HVAC - AIR DUCTS ARE MAKING A RATTLING NOISE BY CUBICLES 7 & 9 - REPAIR - [redacted] 623-0072	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11731608	3C - Low Sustain	3C - 9001 ROOF SECTION 3 - WT-TAC STRUC - (parts 08-16/ 09-16?) REPAIR WITH RAM COLD TAR - REPAIR - [redacted] 582-4496	Repair
11731825	3B - Medium Sustain	3B - 9001 Q19 - WT - INT ELEC - EXIT LIGHT IS NOT TURNED ON - REPAIR - [redacted] 622-7846	Repair
11732184	3C - Low Sustain	3C - 9001 POST L44 - INT ELEC - CHANGE OUT 2 LIGHT SWITCHES TO SENSOR LIGHTS - REPAIR - [redacted] 582-4105	Repair
11732712	3C - Low Sustain	3C - 9001 POST 2V40 & 2V41 - WT - LOCK - INSTALL NEW CORES THAT LOCK THE DOOR FROM BOTH SIDES - REPAIR - [redacted] 582-4196	Repair
11733100	3C - Low Sustain	REJECT TEST: DEFAULT - Work Task Template - Corrective Maintenance-Emergency Exit Signs	Repair
11734841	3C - Low Sustain	3C - 9001 POST 2T41 - WT - LOCK - CHANGE OUT CORE LOCKS - REPAIR - [redacted] 582-4105	Repair
11734855	3C - Low Sustain	3C - 9001 2ND FLR MEZZ - WT - TAC STRUC - REPAIR LATCHES ON FIRE DOORS - REPAIR - [redacted] - 582-4105	Repair
11734901	3C - Low Sustain	3C - 9001 NW PARKING LOT - WT - EXT ELEC - OVERHANG HAS LIGHTS OUT - REPAIR - [redacted] 582-4105	Repair
11735112	3C - Low Sustain	3C - 9001 POST Y41 SUPERVISORS OFFICE - WT - LOCK - LOCK IS DIFFICULT TO OPEN/POSSIBLE NEW CORE KEY #747734 - REPAIR - [redacted] 582-4196	Repair
11735215	3B - Medium Sustain	3B - 9001 BETWEEN POSTS M20 & N20 - WT - TAC HVAC - PIPES ON ROOF LABELED HOT/CHILL WATER SUPPLY ARE LEAKING - REPAIR - [redacted] 582-4105	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11735747	3C - Low Sustain	3C - 9503 FIRE ALARM SYSTEM - WT - TAC ALARM - DISABLE FIRE ALARM FOR CONTRACTOR FOR OUTAGE - REPAIR - [redacted] [redacted] 582-4496	Repair
11736359	3A - High Sustain	3A - 9001 SW END - WT - PEST - DOG RUNNING AROUND BLDG - REPAIR - [redacted] - 361-2972	Repair
11736405	3B - Medium Sustain	3B - 9001 BREAKRM MEZZ 2 - WT - INT PLUMB - ONLY HOT WATER IN SINK - REPAIR - [redacted] 405-623-0072	Repair
11736472	3C - Low Sustain	3C - 9001 POST A15 EXTERIOR DOUBLE DOORS - WT - TAC STRUC - DOOR HANDLES ARE DIFFICULT TO OPEN - REPAIR - [redacted] 622-7846	Repair
11736757	3C - Low Sustain	3C - 9001 DD25 - WT - TAC HVAC - FF HELP ALARM SHOP TO MOVE PULL STATION TO NEW BLDG - REPAIR - [redacted] 582-4496	Repair
11736828	3C - Low Sustain	3C - 9001 EXTERIOR DOOR S59 POST A59 - WT - TAC STRUC - DOOR CAN'T BE OPENED FROM OUTSIDE/REPAIR/NEEDS TO LOCK - REPAIR [redacted] 622-7846	Repair
11736926	3C - Low Sustain	3C - 9001 EXTERIOR DOOR S26 POST A26 - WT - TAC STRUC - DOOR CAN'T BE OPENED FROM OUTSIDE/REPAIR/NEEDS TO LOCK - REPAIR [redacted] 622-7846	Repair
11736940	3B - Medium Sustain	3B - 9001 EXTERIOR DOOR N28 POST EE28 - WT - INT ELEC - EXIT LIGHT IS INOP - REPAIR - [redacted] [redacted] 622-7846	Repair
11736955	3C - Low Sustain	3C - 9001 EXTERIOR DOUBLE DOOR N45 POST EE45 - WT - TAC STRUC - DOOR HANDLES HARD TO TURN/REPAIR - REPAIR - [redacted] 622-7846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11737949	2A - Preventive Maintenance	D10151101950 - A - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11737954	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11737955	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11738070	2A - Preventive Maintenance	D10151101950 - A - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11738071	2A - Preventive Maintenance	D10151101950 - A - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11738080	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11738081	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11738189	2A - Preventive Maintenance	D10151101950 - A - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11738199	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11738217	2A - Preventive Maintenance	D10151101950 - A - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11738222	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 9001 - ELEVATORS - ANNUALWEEK 44	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11741331	3C - Low Sustain	3C - 9001 POST J39 - WT - HONEYWELL - OVERHEAD LIGHT OUT - REPAIR - [redacted] 582-4105	Repair
11741440	3A - High Sustain	3A - 9001 POST Q53 M/WRR - WT - INT PLUMB - SEWAGE BACK UP IN BOTH RR'S - REPAIR - [redacted] 274-2656	Repair
11741491	3B - Medium Sustain	3B - 9001 - WT - TAC HVAC - AC INSULATED LINE IS DRIPPING WATER - REPAIR - [redacted] 736-8784	Repair
11742294	3C - Low Sustain	3C - 9001 POST C15 -WT - LOCK - NEED TO FIND OUT WHAT CORE IS INSTALLED IN OFFICE DOOR KNOB - REPAIR - [redacted] 582-4105	Repair
11742480	4A - High Enhance	4A - 9001 D54 - WT - CBR - INSTALL 4 TON CONDENSER - [redacted] - 405 734 7954	Repair
11742595	3C - Low Sustain	3C - 9001 EXT DOOR M19 - WT - TAC STRUC - DOOR WILL NOT LATCH/CLOSE - REPAIR - [redacted] 622-7846	Repair
11742688	3C - Low Sustain	3C - 9001 EE38 - WT - TAC HVAC - CHECK FOR AND REPAIR LEAKS - REPAIR - [redacted] 622-7846	Repair
11742786	4A - High Enhance	4A - 9001 F31 - WT - ENG EVAL - ANALYZE EXISTING & PROPOSED EQUIP INSTALLATION - [redacted] - 405 582 4095	Repair
11742832	3C - Low Sustain	3C - 9001 BETWEEN POSTS F30 & G31 - WT - 3 CYPHER LOCK DOORS THAT NEED TO HAVE CORES INSTALLED - REPAIR - [redacted] 582-4105	Repair
11742839	3C - Low Sustain	3C - 9001 POST 2F32 - WT - LOCK - INSTALL LOCKING DOOR KNOB WITH MECHANICAL KEY CORE THAT IS MISSING DOOR KNOB - REPAIR - [redacted] 582-4105	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11745880	3C - Low Sustain	3C - 9001 NW PARKING LOT - WT - INT ELEC - WALK THROUGH GATE LIGHTS NOT WORKING - REPAIR - [redacted] 734-6281	Repair
11746063	3A - High Sustain	3A - 9001 POST L52 - WT - TAC HVAC - CLOGGED CONDENSATE DRAIN - Repair - [redacted] 5509580	Repair
11746065	3B - Medium Sustain	3B - 9001 POST M45 - WT - INT PLUMB - HANDICAPPED STALL TOILET IS CLOGGED AND WON'T FLUSH & NEEDS TOILET SEAT REPLACED - REPAIR [redacted] 582-4105	Repair
11746078	3C - Low Sustain	3C - 9001 POST M45 - WT - TAC STRUC - PARTS (09-08 TO 09-16)HANDICAPPED MENS BATHROOM STALL NEEDS NEW LATCH - [redacted] 582-4105	Repair
11746413	3B - Medium Sustain	3B - 9001 ROOM 149 - WT - LOCK - NEED ROOM UNLOCKED - REPAIR - [redacted] 582-5477	Repair
11746508	3C - Low Sustain	3C - 9001 POST E30 - INT PLUMB - HANDICAP TOILET STALL NEEDS TOILET SEAT REPLACED - REAPIR - [redacted] 582-4105	Repair
11748086	3B - Medium Sustain	3B - 9001 MRR POST Q52 - WT - INT PLUMB - TOILETS FLUSHING SLOWLY, HAVE LOW WATER PRESSURE - REPAIR - [redacted] 819-9862	Repair
11749689	3C - Low Sustain	3C - 9001 X19 - WT - TAC ALARM - FF ASSIST SPRINKLER GUYS BY DISABLING PANEL FOR SPRINKLER SYSTEM - REPAIR - [redacted] 582-4496	Repair
11750208	3C - Low Sustain	3C - 9001 EE38 - WT - TAC STRUC - F/U 11742688 REPAIR ROOF LEAK AT EE38 - REPAIR - [redacted] 582-4496	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11752376	3C - Low Sustain	3C - 9001 POST G30 - WT - LOCK - NEED A 713D5 CORE MADE &INSTALLED IN INTERIOR DOOR & 2 KEYS MADE SAME AS CORE 713D5 - REPAIR - [redacted] 582-4105	Repair
11752462	3C - Low Sustain	3C - 9001 B62/63 - WT - TAC HVAC - F/U 11695192 CHILLED WATER SUPPY LINE IS DRIPPING OR HAS CONDENSATION - REPAIR - [redacted] 582-4496	Repair
11752720	3C - Low Sustain	3C - 9001 B62/63 - WT - INSULATE - F/U 11752462 6" CHW LINE IN RAFTERS LEAKING/CHECK ALL ROOFTOP [redacted] IN AREA - [redacted] - 582-4496	Repair
11752916	3B - Medium Sustain	3B - 9001 U38/39 ASH 71 - WT - TAC HVAC - REPAIR CONDENSATE ISSUES/CONTINOUS PROBLEM - REPAIR - [redacted] 734-2328	Repair
11752944	3B - Medium Sustain	3B - 9001 ASH 203 - WT - TAC HVAC - CLEAN CLOGGED COIL - REPAIR - [redacted] 734-2328	Repair
11753276	3C - Low Sustain	3C - 9001 TAC OFFICES AND BREAKROOM - WT - TAC HVAC - TROUBLESHOOT AND REPAIR HVAC UNIT - REPAIR - [redacted] 582-4496	Repair
11753599	3B - Medium Sustain	3B - 9001 S ADMIN - WT - TAC HVAC - (PARTS picked up) REPAIR BAD BEARING - REPAIR - [redacted] - 734-7554	Repair
11753781	3B - Medium Sustain	3B - 9001 - WT - EXT PLUMB - repair or replace a PIV located near door W/Y on the outside west middle of building - REPAIR - [redacted] 734-4202	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11755121	3A - High Sustain	3A - 9001 POST KC46 - WT - TAC HVAC - AHU 1A OFFLINE - Repair - [redacted] 5825454	Repair
11755333	3B - Medium Sustain	3B - 9001 W SIDE BY DOOR WY - WT - EXT PLUMB - RISER HAS RUPTURED UNDERGROUND - [redacted] 326-7992	Repair
11757014	3B - Medium Sustain	3B - 9001N - WT - POWER - LOW COOLANT LEVEL FAULT/SENSOR IS BAD AND GENERATOR WILL NOT RUN WITH THIS FAULT - [redacted] - 734-5806 - EG09001-N	Repair
11757350	3C - Low Sustain	3C - 9001 POST E30 - INT PLUMB - F/U 11746508 HANDICAP TOILET STALL NEEDS TOILET SEAT REPLACED - REAPIR - [redacted] - 734-7098	Repair
11757366	3C - Low Sustain	3C - 9001 POST M45 - WT - INT PLUMB - F/U 11746065 HANDICAPPED STALL TOILET IS CLOGGED/WON'T FLUSH & NEEDS TOILET SEAT REPLACED - [redacted] 7347098	Repair
11759573	3C - Low Sustain	3C - 9001 N51 - WT - OP - relocation/demolition of mass notification & fire suppression equipment - [redacted] - 405 734 5763	Repair
11761325	3C - Low Sustain	3C - 9001 POST EE21 - WT - TAC HVAC - (PARTS PICKED UP)TROUBLESHOOT INOP EXHAUST FAN - [redacted] - 582-4496 - EF-201	Repair
11761332	3B - Medium Sustain	3B - 9001 PRECISION GRIND - WT - TAC HVAC - REPLACE 2 IGNITORS FOR BOILER TO MAINTAIN TEMPS 68-69 DEG - [redacted] - 582-4496	Repair
11762890	4A - High Enhance	4A - 9001 LAB WORKLOAD AREA-CBM - WALL PENETRATIONS - [redacted] -405 622 7078	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11763052	3C - Low Sustain	3C - 9001 B 62 - WT - TAC HVAC - EXHAUST FAN INOP - [redacted] 2092082	Repair
11763064	3C - Low Sustain	3C - 9001 ASH HOUSE 105 - WT - TAC HVAC - REPLACE BELTS AND CLEAN DRAIN - [redacted] 2092082	Repair
11766906	3B - Medium Sustain	3B - 9001 POST X40 - WT - INT PLUMB - BREAKROOM SINK IS CLOGGED & LEAKING WATER - [redacted] - 582-4196	Repair
11766930	3B - Medium Sustain	3B - 9001 POST 2V40 WRR - WT - INT PLUMB - HANDICAP STALL CLOGGED - [redacted] 582-4196	Repair
11767388	3C - Low Sustain	3C - 9001 ROOF TOP Q/P 36/37 - WT - INT PLUMB - F/U 11626130 DRAIN PIPE CLOGGED - REPAIR - [redacted] - 622-7846	Repair
11767785	3B - Medium Sustain	3B - 9001 - WT - TAC HVAC - AIR HANDLER 1 IS DOWN/CHILLER IS OFF KC46 - [redacted] - 736-7554	Repair
11768333	3C - Low Sustain	3C - 9001 ROOF H42&K22 - WT - TAC HVAC - REMOVE&DISPOSE OF OLD PARTS, BELTS, BOXES, TRASH & DEBRIS AROUND ASH AND MECH ROOMS - [redacted] - 622-7846	Repair
11768359	3C - Low Sustain	3C - 9001 ROOF J22 - WT - TAC HVAC - (10/11 TO 10/31) EXHAUST FAN MAKING NOISE - [redacted] - 622-7846 - UID 9001-EF-42	Repair
11768369	3C - Low Sustain	3C - 9001 ROOF J/K 32/33 ASH37 · WT - TAC STRUC - BROKEN DOOR HANDLE NEEDS REPAIR/REPLACE · [redacted] 622-7846	Repair
11768385	3C - Low Sustain	3C - 9001 ROOF J/K 34/35 ASH38 · WT - TAC STRUC - DOOR/FRAME/HINGES ARE BROKEN/LOOSE/DAMAGED - [redacted] 622-7846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11768395	3C - Low Sustain	3C - 9001 ROOF J/K 46/47 ASH44 · WT - TAC STRUC - DOORS/HANDLES/LOCKS NEED FIXED/REPAIRED SO THEY OPEN/CLOSE PROPERLY - [redacted] 622-7846	Repair
11768403	3C - Low Sustain	3C - 9001 2G39 M/WRR - WT - TAC HVAC - HOT AND HUMID IN RESTROOMS -9001-ac-3 [redacted] 622-7846	Repair
11769165	3C - Low Sustain	3C - 9001 EE44 - WT - INT PLUMB - ROOF DRAIN LEAK - [redacted] - 582-4496	Repair
11769580	3C - Low Sustain	3C - 9001 POST M45 - WT - INT PLUMB - MENS RR HANDICAP TOILET WATER PRESSURE IS TOO HIGH - [redacted] - 582-4105	Repair
11770472	3C - Low Sustain	3C - 9001 CRAC UNIT 5 - WT - TAC HVAC - F/U 11535871 UNIT IS TRIPPING ON HIGH PRESSURE - [redacted] - 582-4496	Repair
11774286	3C - Low Sustain	3C - 9001 - WT - SPRINK - REPLACE 2 FIRE HOSE VALVES IN FIRE PUMP ROOM LOCATED ON SW CORNER - [redacted] - 734-4202	Repair
11775843	3B - Medium Sustain	3B - 9001 A32 Facility Managers Office WRR - WT - INT PLUMB - water leak coming from back of toilet/wall - [redacted] - 622-7846	Repair
11776733	3C - Low Sustain	3C - 9001 EE22 - WT - Intelec - replace old exit light with new LED unit - repair - [redacted] - 622-7846 - SR3095225	Repair
11776741	3C - Low Sustain	3C - 9001 EE20 - WT - Intelec - Exit light won't test, replace with LED unit - repair - [redacted] - 622-7846 - SR3095231	Repair
11776749	3C - Low Sustain	3C - 9001 Q-63 - WT - Intelec - Exit light to dim, replace with LED unit - repair - [redacted] - 622-7846 - SR3095238	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11776765	3C - Low Sustain	3C - 9001 L31 breakroom - WT - Intplumb - Water heater, check press. and for leaks - repair - [redacted] - 622-7846 - SR3095246	Repair
11776772	3C - Low Sustain	3C - 9001 T48 - WT - Intplumb - clear clogged line in fixture storage, scope line for problems - repair - [redacted] - 622-7846 - SR3095249	Repair
11776820	3C - Low Sustain	3C- 9001 E-23 Breakroom - WT - TAC Struc - repair break rm dr handle / latch / lock - repair - [redacted] - 622-7846 - SR3095286	Repair
11776827	3C - Low Sustain	3C - 9001 G5 Exit light - WT - Intelec - cover fell off, unit to dim, won't test, needs LED lights - repair - [redacted] - 405-622-7846 - SR3095292	Repair
11777559	3C - Low Sustain	3C - 9001 EE22 - WT - TAC Struc - move N22 door sign so it won't intefere with exit sign test - repair - [redacted] - 622-7846	Repair
11778031	3C - Low Sustain	REJECT DEFAULT - Work Task Template - Corrective Maintenance-Elevator	Repair
11778042	3C - Low Sustain	3C - 9001 POST P30 - WT - SUB ELEVATOR - ELEVATOR HAS BEEN BROKEN FOR QUITE A WHILE; WOULD LIKE IT LOOKED AT - [redacted] 582-4105	Repair
11778130	3C - Low Sustain	3C- 9001 B5- WT - TAC HVAC - ASSISTED ROOF SHOP PATCHING/CAULKING HOLES - [redacted] - 582-4496	Repair
11778133	3C - Low Sustain	3C - 9001 M38 - WT - TAC HVAC - ASSIST ROOF SHOP IN INSTALLING NEW SINK BASE AND CAULK - [redacted] - 582-4496	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11778455	3C - Low Sustain	3C - 9001 WHOLE BUILDING - WT - TAC ALARM - ASSIST CONTRACTOR WITH FIRE ALARM TEST - [redacted] - 582-4496	Repair
11778459	3C - Low Sustain	3C - 9001 WHOLE BUILDING - WT - TAC HVAC - ASSIST FIRE ALARM SHOP WITH TESTING FIRE ALARM - [redacted] - 582-4496	Repair
11778728	3C - Low Sustain	3C 9001 - FACILITY MANAGERS OFFICE - WT - UFIXIT - PEST MANAGEMENT SUPPLIES - REPAIR - [redacted] 405-622-7846	Maintenance
11779542	3B - Medium Sustain	3B - 9001 DRTC OFFICE POST DX33 - WT - INT PLUMB - ACAP DRAIN CLOGGED - [redacted] - 622-7846	Repair
11781165	3C - Low Sustain	3C - 9001 PARKING LOT F - WT - EXTELECT- THERE'S A CONCRETE FOOTER THAT NEEDS TO BE ASSESSED TO MAKE MORE VISIBLE - [redacted] - 582-4105	Repair
11781447	3C - Low Sustain	3C - 9001 EE22 - WT - TAC hvac - Help structures move N22 door sign so it won't intefere with exit sign test - [redacted] - 622-7846	Repair
11781510	3B - Medium Sustain	3B - 9001 G11 & H11 - WT - TAC STRUC - REPAIR/REPLACE INOP LOCKS TO PREVENT UNAUTHORIZED ACCESS - [redacted] - 622-7846 - EGD-47	Repair
11781747	3C - Low Sustain	3C - 9001 G10 MECH RM - WT - TAC STRUC - INT DOOR DOES NOT LATCH CORRECTLY - [redacted] - 622-7846	Repair
11781750	3C - Low Sustain	3C - 9001 G9 - WT - INT ELEC - EXIT light has been damaged and has paint on it, replace old unit with a new LED - [redacted] - 622-7846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11783579	1-Emergency	1 - 9001 POST 2W41 - WT - TAC HVAC - ENGINEERING OFFICE IS OVER 80 DEGREES - [redacted] 582-4105	Repair
11785401	3B - Medium Sustain	3B - 9001 POST G32 - WT - INT ELEC - RM HAS 2 EMERGENCY EXIT SIGNS INOP - [redacted] - 582-4105	Repair
11785408	3C - Low Sustain	3C - 9001 POST G32 - WT - INT ELEC - TEST EMERGENCY LIGHTS TO ENSURE PROPER FUNCTION - [redacted] - 582-4105	Repair
11785416	3B - Medium Sustain	3B - 9001 POST G32 - WT - STRUC - REPAIR PANIC BAR - [redacted] - 582-4105	Repair
11785435	3B - Medium Sustain	3B - 9001 POST G32 - WT - INT ELEC - SEVERAL OVERHEAD LIGHTS ARE HANGING DOWN - [redacted] - 582-4105	Repair
11785496	3C - Low Sustain	3C - 9001 NODE 20 - WT - TAC HVAC - ASSIST ALARM SHOP WITH SPEAKER INSTALL - [redacted] - 582-4496	Repair
11785499	3C - Low Sustain	3C - 9001 POST P30 - WT - SUB ELEVATOR - NEED ESTIMATE FOR NON OPERATING ELEVATOR - [redacted] 582-4105	Repair
11785659	3C - Low Sustain	3C - 9001 CC53 - WT - SHEET METAL - NEED 2 SMOKE DAMPERS COVERED WITH SHEET METAL - [redacted] - 582-4496	Repair
11785669	3C - Low Sustain	3C - 9001 B51 - WT - TAC CONTROLS - HOT WATER PUMP # 1 SEALS LEAKING COORDINATION WITH 11785684 - [redacted] - 582-4496	Repair
11785684	3C - Low Sustain	3C - 9001 B51 - WT - TAC HVAC - (SEALS 09-07/10-25)HOT WATER PUMP #1 SEALS LEAKING - [redacted] - 582-4496	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11786246	3C - Low Sustain	3C - 1091 FUEL YARD - WT - PIPE - FABRICATE 2" PIPE LOW POINT DRAINS - [redacted] - 582-4496	Repair
11786408	3B - Medium Sustain	3B - 9001 2C10 - WT - INT ELEC - DISCONNECT POWER TO OLD HOT WATER HEATER TO ASSIST PLUMBERS - [redacted] 622-7846	Repair
11786422	3B - Medium Sustain	3B - 9001 L32 BRKRM - WT - INT ELEC - DISCONNECT POWER TO OLD HOT WATER HEATER - [redacted] - 622-7846	Repair
11788536	3C - Low Sustain	3C - 9001 NODE 20 - WT - TAC ALARM - INVESTIGATE KC46 FF NODE 20 SHOWING GROUND FAULT - [redacted] - 582-4496	Repair
11790073	3C - Low Sustain	3C - 9001 G32 - WT - TAC HVAC - HELP STRUCTURES SHOP REPAIR TWO END CAPS ON PANIC BAR DOORS - [redacted] - 582-4496	Repair
11796751	3B - Medium Sustain	3B - 9001 POST F30 - WT - TAC HVAC - ROOM IS TOO COLD - [redacted] 582-4105	Repair
11797493	3B - Medium Sustain	3B - 9001 POST K44 - WT - TAC STRUC - ROOF LEAKS BLACK TAR LOOKING SUBSTANCE - [redacted] - 582-4105	Repair
11797817	3B - Medium Sustain	3B - 9001 DRTC OFFICE POST DX33 - WT - EXT PLUMB - F/U 11779542 NEED VAC TRUCK TO SUCK OUT DRAIN - [redacted] - 405-734-7098	Repair
11798258	3C - Low Sustain	3C - 9001 POST M28 - WT - TAC STRUC - TOOL ROOM HAS ROOF LEAK - [redacted] - 582-4105	Repair
11799193	3C - Low Sustain	3C- 9001 CHEM STORAGE- WT- TAC HVAC CONTROLS- CHECK TROBULE CODE ON HVAC UNIT ON ROOF- [redacted] -582-4496	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11799763	3C - Low Sustain	3C - 9001 POST H45 - WT - PEST - TREAT FOR ROACHES & FRUIT FLIES - [redacted] - 736-8784	Services
11800551	3B - Medium Sustain	3B - 9001 L32 - WT - INT ELEC - ELECTRICAL PLUG IS TO FAR FROM NEW HOT WATER HEATER TO PLUG INTO/MOVE CLOSER - [redacted] - 622-7846	Repair
11800968	3C - Low Sustain	3C - 9001 EE38 - WT - TAC HVAC - F/U 11742688 HELP STRUC SHOP REPAIR ROOF LEAK AT EE38 - [redacted] - 582-4496	Repair
11801020	3C - Low Sustain	3C - 9001 ASH HOUSE 6 - WT - TAC HVAC - REPLACE BELTS - [redacted] - 582-4496	Repair
11801032	3C - Low Sustain	3C - 9001 ROOF H42&K22 - WT - BAS - CLEAN ASH & MECH RMS - [redacted] - 582-4496	Repair
11803441	3B - Medium Sustain	3B - 9001 POST G39 - WT - TAC STRUC - REPAIR OFFICE DOOR LATCH - [redacted] - 582-4105	Repair
11803721	3B - Medium Sustain	3B - 9001 S ADMIN - WT - TAC HVAC - TROUBLESHOOT INOP BOILER - [redacted] - 582-4496 - BLR-103A	Repair
11805349	3C - Low Sustain	3C - 9001 ASH HOUSE 19 - WT - TAC HVAC - REPLACE BELTS - [redacted] - 582-4496	Repair
11805358	3C - Low Sustain	3C - 9001 ASH HOUSE 45 - WT - TAC HVAC - REPLACE CONDENSATE DRAIN LINE - [redacted] - 582-4496	Repair
11805430	3C - Low Sustain	3C - 9001 CX33 - WT - PAINT - REPAINT FACILITY MANAGER'S GARAGE DOOR BOTH SIDES - [redacted] - 622-7846	Repair
11805527	3C - Low Sustain	3C - 9001 BX32 - WT - PAINT - REPAINT TRIM TO TINKER CHOCOLATE BROWN AROUND DOORS FOR FACILITY MANAGER OFFICE - [redacted] 323-0319 - PAINT	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11805630	3C - Low Sustain	3C - 9001 E PARKING LOT - WT - PAVE - PARKING CURBS FOR MOTORCYCLES NEEDS TO BE MOVED BACK INTO PLACE - [redacted] - 622-7846	Repair
11806157	3C - Low Sustain	3C - 9001 EB - WT - INT ELEC - TROUBLE SHOOT WHY THERE'S NO POWER TO NEW INSTALLED LIGHTS - [redacted] - 622-7846	Repair
11807972	3C - Low Sustain	3C - 9001 - WT - PAINT - PAINT BOLLARDS FOR MOTORCYCLE PARKING - [redacted] - 734-5053	Repair
11808380	3C - Low Sustain	3C - 9001 C10 WOMEN'S RR - WT - INT ELEC - 1 LIGHT INOP - [redacted] - 622-7846	Repair
11808428	3C - Low Sustain	3C - 9001 T45 - WT - TAC STRUC - REPAIR SMALL POTHOLE IN AISLE BETWEEN S44 & T45 - [redacted] - 622-7846	Repair
11808432	3B - Medium Sustain	3B - 9001 S ADMIN RM 147 - WT - TAC HVAC - UNIT LEAKING INTO WOMENS RR - [redacted] - 582-4496	Repair
11808442	3B - Medium Sustain	3B - 9001 POST K44 - WT - TAC HVAC - ASSIST REPAIRING ROOF LEAK - [redacted] - 582-4105	Repair
11809094	3B - Medium Sustain	REJECT; SEE NOTES	Repair
11810190	3C - Low Sustain	3C - 9001 ASH-81 COL AA33 - WT - HONEYWELL - REPAIR/REPLACE CHILL WATER VALVE - REPAIR - [redacted] - 405-886-5386 - SR 3109088	Repair
11810488	3B - Medium Sustain	3B - 9001 POST K32 - WT - TAC STRUC - SEVERAL LEAKS, ONE IS LEAKING ON LAPTOP CABINET - [redacted] - 582-4105	Repair
11810600	3B - Medium Sustain	3B - 9001 POSTS A46-A47 - WT - TAC STRUC - LEAK FROM CEILING, LOOKS LIKE OIL - [redacted] - 736-5233	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11811983	3B - Medium Sustain	3B - 9001 POST S32 - WT - TAC STRUC - WATER LEAK - [redacted] - 582-4196	Repair
11812188	3C - Low Sustain	3C - 9001 THROUGHOUT BUILDING - WT - SPRINK - REPAIR/REPLACE TEST HEADER - [redacted] - 734-5806	Repair
11812624	3C - Low Sustain	3C - 9001 ROOF 3D54 - WT - INSULATOR - REPLACE THE DAMAGED INSULATION OF REFRIGERANT LINES - [redacted] - 622-7846 - 9001-CU-MD103 & 9001-CU-MD103	Repair
11812856	3B - Medium Sustain	3B - 9001 ROOF F54 - WT - TAC HVAC - REPAIR/REPLACE LEAKING CONDENSATION LINE OF AC-7 - [redacted] - 622-7846 - PKG-F54	Repair
11812873	3C - Low Sustain	3C - 9001 ROOF F54 - WT - TAC STRUC - CLEAN/CLEAR ROOF DRAIN OF DEBRIS & CLEAN TRASH - [redacted] - 622-7846	Repair
11812910	3C - Low Sustain	3C - 9001 ROOF F54 - WT - TAC HVAC- REPLACE DAMAGED WEATHER STRIPPING ON ACCESS DOOR TO HVAC UNIT AC-7 - [redacted] - 323-0319 - PKG-F54	Repair
11812959	3B - Medium Sustain	3B - 9001 A32 - WT - INT ELEC - REPAIR BAD PHOTOCELL ON ROOF - [redacted] - 734-2328	Repair
11812961	3C - Low Sustain	3C - 9001 ROOM M58 ASH 212 - WT - TAC HVAC - REPAIR/REPLACE CONDENSATION LINE THAT IS MISSING & CAUSING WATER TO FORM ON ROOF - [redacted] . 622-7846	Repair
11812987	3C - Low Sustain	3C - 9001 ROOF M59/J-K 55/56 - WT - TAC STRUC - CLEAR TRASH FROM REPAIRS TO ASH HOUSES - [redacted] - 622-7846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11813061	3B - Medium Sustain	3B - 9001 ROOF M60 - WT - TAC HVAC - WATER POURING OUT OF ASH 211, CHECK CONDENSATE DRAIN LINE -	Repair
11813104	3C - Low Sustain	3C - 9001 ROOF N62 - WT - TAC HVAC - REPAIR/REPLACE MISSING CONDENSATE DRAIN LINE FOR ASH 210 - [redacted] - 622-7846	Repair
11815779	4A - High Enhance	4A - 9001 S 22 - WT - INT ELEC - ISWP - Correct the lighting deficiency - [redacted] - 405 622 7846	Repair
11815823	4A - High Enhance	4A - 9001 - WT - OPS PLAN SIGN ISWP - PROVIDE SMOKING AREA MAP & SIGNAGE - [redacted] - 405 622 7846	Repair
11816007	3B - Medium Sustain	3B - 9001 G11 & H11 - WT - LOCK - F/U 11781510 REPAIR/REPLACE INOP LOCKS TO PREVENT UNAUTHORIZED ACCESS - [redacted] - 622-7846 - EGD-47	Repair
11818245	3C - Low Sustain	3C - 9001 2V42 - WT - FAC PROJ - ISWP - Replace doors & locking hardware - [redacted] - 405 582 4196 FP# 1019094	Repair
11818357	4A - High Enhance	3C - 9001 N 52 - WT -TAC ALARM - Remove pull station/horn - [redacted] - 405 736 4316	Repair
11818369	3C - Low Sustain	3C - 9001 N52 & M53 - WT - SPRINK - REMOVE FIRE SUPPRESSION DRAIN LINE - [redacted] - 736-4316	Repair
11818595	3C - Low Sustain	3C - 9001 ASH 52 - WT - TAC HVAC - REPAIR CONDENSATE LEAK - [redacted] - 582-4496	Repair
11818657	3C - Low Sustain	PAINT - 3C - 9001 A32 - WT - PAINT - PREP & PAINT BOTH SIDES OF 3 INTERIOR DOORS AF BLUE - [redacted] - 323-0319	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11818670	3C - Low Sustain	3C - 9001 BX33 - WT - PAINT - PREP & PAINT FIRE ALARM RM DOOR & FRAME - [redacted] - 622-7846	Repair
11818717	3C - Low Sustain	3C - 9001 TRF 5 - WT - TAC ALARM - NODE 7 SHOWING MAPNET ISOLATOR TROUBLE, NEED TO INVESTIGATE - [redacted] - 582-4496 - FA-279	Repair
11818762	3C - Low Sustain	3C - 9001 PRECISION GRIND - WT - TAC ALARM - FF NODE 10 SHOWING TROUBLE AT THE TSW. NEED TO INVESTIGATE - [redacted] - 582-4496 - 9001-FA-1588	Repair
11818825	3C - Low Sustain	3C - 9001 WHITE HOUSE 5 - WT - TAC ALARM - FF/NODE 21 SHOWING SYSTEM SUEDO STATUS TROUBLE, NEED TO INVESTIGATE - [redacted] - 582-4496	Repair
11818937	3C - Low Sustain	PAINT - 3C - 9001 A31 - WT - PAINT - PREP & PAINT A31 EXTERIOR DOOR/CHOCOLATE CHIP BROWN OUTSIDE/AF BLUE INSIDE - [redacted] - 323-0319	Repair
11820284	3B - Medium Sustain	3B - 9001 ASH 1 - WT - TAC HVAC - SA FAN FAIL TO START - [redacted] - 622-7846	Repair
11820646	3B - Medium Sustain	3B - 9001 POST M60 AND L60 - WT - TAC HVAC - CONDENSATION LEAK - [redacted] - 8553012	Repair
11820706	3B - Medium Sustain	3B - 9001 EK-2 O/H - WT - MACH MAINT - O/H DOOR HAS SOMETHING HANGING - [redacted] - 855-3012	Repair
11821617	3B - Medium Sustain	3B - 9001 ASH 65 - WT - TAC HVAC - ASH 65 SHOULD BE RUNNING BUT ISN'T/SA FAN FAIL TO START - [redacted] - 323-0319	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11821775	3B - Medium Sustain	3B - 9001 ASH 74 - WT - TAC HVAC - SHOULD BE RUNNING BUT IS NOT/SAN FAN FAIL TO START - [redacted] - 323-0319	Repair
11824762	3A - High Sustain	3A - 9001 POST M60 - WT - TAC STRUC - AK0002 WATER LEAKING DOWN POLE, 3-4" FROM ELEC BOX - [redacted] - 219-7894	Repair
11830133	3C - Low Sustain	REJECTED SEE WORK DETAILS	Repair
11830383	3C - Low Sustain	3C - 9001 BREAKROOM - WT - TAC STRUC - CABINETS/COUNTERTOPS NEED TO BE REPAIRED/REPLACED DUE TO WATER DAMAGE - [redacted] - 582-4196	Repair
11831072	3A - High Sustain	3A - 9001 2ND FLR KC 46 AREA - WT - TAC HVAC - AHUS BLOWING 72 DEG AIR EVEN THOUGH GRAPHICS SHOW CHILLER RUNNING - [redacted] - 582-5454	Repair
11831117	3A - High Sustain	3A - 9001 COMPOSITES LAB - WT - TAC HVAC - HUMIDITY OUT OF TOLERANCE, NEED T-STAT CONTROL - [redacted] - 408-0683	Repair
11832586	3B - Medium Sustain	3B - 9001 2ND FLR KC46 AREA - WT - TAC CONTROLS - F/U 11831072 TROUBLESHOOT CHILL WATER PUMPS - [redacted] - 582-5454	Repair
11833763	3C - Low Sustain	3C - 9001 COMPOSITES LAB - WT - TAC CONTROLS - F/U 11831117 HUMIDITY OUT OF TOLERANCE, NEED T-STAT CONTROL - [redacted] - 408-0683	Repair
11837164	3B - Medium Sustain	3B - 9001 KC46 AREA - WT - TAC HVAC - REHEAT PUMPS HAVE FLOODED AREA - [redacted] - 736-7554	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11839959	3B - Medium Sustain	3B - 9001 DOOR 54 - WT - EXT PLUMB - REPAIR/REPLACE PIV#33 THAT IS BROKEN IN CLOSED POSITION - [redacted] - 734-4202	Repair
11843031	3C - Low Sustain	3C - 9001 ASH 73 - WT - TAC HVAC - WATER LEAKING FROM DRAIN PANS INTO BLDG - [redacted] - 582-4496	Repair
11843188	3C - Low Sustain	3C - 9001 - WT - POWER PRO - REFUILING GENERATOR - [redacted] - 734-5806 - EG09001	Repair
11843564	3B - Medium Sustain	3B - 9001 POSTS A46-A47 - WT - TAC HVAC - ASSIST TAC STRUC WITH LEAK FROM CEILING, LOOKS LIKE OIL - [redacted] - 736-5233	Repair
11844012	3C - Low Sustain	3B - 9001 - WT - TAC HVAC CONTROLS - AIR HANDLER 1 IS DOWN/CHILLER IS OFF KC46 - [redacted] - 736-7554	Repair
11844545	3B - Medium Sustain	3B - 9001 AGS-82 CIK AA36 - WT - HONEYWELL - TROUBLE SHOOT CHILL WATER VALVE - [redacted] - 886-5386	Repair
11844602	3B - Medium Sustain	3B - 9001 POST S32 - WT - TAC HVAC- ASSIST TAC STRUCTURES WITH WATER LEAK - [redacted] - 582-4196	Repair
11844625	3B - Medium Sustain	3B - 9001 POSTS A46-A47 - WT - TAC HVAC - ASSIST TAC STRUCTURES WITH LEAK FROM CEILING, LOOKS LIKE OIL - [redacted] - 736-5233	Repair
11845730	3B - Medium Sustain	3B - 9001 POST E-16 COMPOSITES LAY UP RM - WT - INT ELEC - BREAKERS TRIPPING WHEN USING HEAT GUNS - [redacted] - 582-4105	Repair
11849671	3C - Low Sustain	3C - 9001 ROOF A n55 - WT - TAC STRUC - ROOF PENETRATIONS- [redacted] - 582-4496	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11849678	3C - Low Sustain	3C - 9001 ROOF B N55 - WT - TAC STRUC - ROOF PENETRATIONS - [redacted] - 582-4496	Repair
11849681	3C - Low Sustain	3C - 9001 - WT - SPRINKLER - OUTAGE SUPPORT TRACKING # 22-399 - [redacted] - 734-5806	Repair
11849683	3C - Low Sustain	3C - ROOF PENETRATION 9001 ROOF C N55- WT - TAC STRUC - ROOF PENETRATIONS - [redacted] - 582-4496	Repair
11849774	3C - Low Sustain	3C-9001 J59-WT- TAC ALARM- ASSIST CONTRACTOR BY DISABLING AND ENABLING ALARMS DURING SPRINKLER LINE TIE INS AND FIRE ALARM [redacted] -582-449	Repair
11852318	3A - High Sustain	3A - 9001 POST DD40- WT - INT PLUMB - LEAK FLOOD BREAKROOM - [redacted] - 5824196	Repair
11852380	3C - Low Sustain	3C - 9001 N55 - WT - TAC HVAC - ASSISTING TAC STRUCTURES WITH ROOF PENETRATIONS - [redacted] - 582-4496	Repair
11854285	3B - Medium Sustain	3B - 9001 2ND FLR KC46 AREA - WT - TAC HVAC- F/U 11831072 ASSIST CONTROL SHOP TO TROUBLESHOOT CHILL WATER PUMPS - [redacted] - 582-5454	Repair
11854420	3C - Low Sustain	3C - 9001 SYSTEM 76 - WT - TAC ALARM - FF CHECK WATER FLOW MODULE FOR PROPER OPERATION - [redacted] - 582-4496	Repair
11854817	3C - Low Sustain	3C - 9001 POST 2J23 - WT - TAC HVAC CONTROLS - (PARTS DIFF WT) ASSISTING HVAC EXHAUST FANS NEED CHECKED - REPAIR - [redacted] -582-4496	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11855568	3C - Low Sustain	3B - 9001 2ND FLR KC46 AREA - WT - TAC CONTROLS - F/U 11832586 TROUBLESHOOT CHILL WATER PUMPS - [redacted] [redacted]-582-4496	Repair
11862680	3C - Low Sustain	3C - 9001 POST DD31 - WT - INT PLUMB - HOTWATER HEATER DAMAGED AND INOP - [redacted] [redacted] - 5824196	Repair
11862726	3C - Low Sustain	3C - 9001 X31 WOMENS RR - WT - TAC STRUC - REPAIR/REPLACE 2 DAMAGED SOAP DISPENSERS - [redacted] - 582-4196	Repair
11864179	3C - Low Sustain	3C - 9001 POST L30 BRKRM 3 - WT - INT PLUMB - BROKEN HOT WATER HANDLE ON SINK - [redacted] - 582-4105	Repair
11864232	3C - Low Sustain	3C - 9001 MENS RR POST C10 - WT - INT PLUMB - URINAL DRAIN IS CLOGGED, HAS BEEN BAGGED - [redacted] - 405.622.7846/323.0319	Repair
11865132	3C - Low Sustain	3C - 9001 LADDER 28 - WT - WELD - NEEDS SUPPORT BRACKET WELDED TO MAIN BEAM. WOBBLY AND UNSTABLE - [redacted] - 582-4496 - 9001-LDR-28	Repair
11865811	3C - Low Sustain	3C - 9001 MENS RR 2W43 - WT - INT ELEC - LIGHTS ARE OUT IN MENS RR - [redacted], 405.622.7846/323.0319	Repair
11866166	3C - Low Sustain	3C - FPM 9001 post 44-47- WT- TAC ALARM -(10/04 TO 10/17) FF PANEL NEEDS NEW 12V 12 AMP BATTERIES - [redacted] [redacted] - 582-4496 - 9001-FA-1375A	Repair
11866216	3C - Low Sustain	3C - 9001 ROOF DD35 - WT - TAC STRUCTURES - PENTHOUSE ACCESS DOOR MISSING HANDLE & LOCK CORE (701C17) - [redacted] [redacted] - 622-7846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11866374	3A - High Sustain	3A - 9001 between Posts A34 & A35 - Chilled water line leaking - [redacted] 623-0072	Repair
11868161	3C - Low Sustain	3C - FPM 9001 post 44-47 - WT - TAC ALARM - (10/04 TO 10/17) FF PANEL NEEDS NEW 12V 12 AMP BATTERIES - [redacted] - 582-4496-9001 - FA-1375B	Repair
11868171	3C - Low Sustain	3C - FPM 9001 POST 44-47 - WT - TAC ALARM -10/04 TO 10/17) FF PANEL NEEDS NEW 12V 12AMP BATTERIES - [redacted] - 582-4496-9001 - FA-1375C	Repair
11868265	3B - Medium Sustain	3B - 9001 POST W26 - WT - INT PLUMB - WATER LEAKING ONTO THE FLOOR FROM POST - [redacted] - 582-4105	Repair
11868286	3C - Low Sustain	3C - 9001 N 28 - WT - INT ELEC - NEED TO HAVE A 220 OUTLET PLUG CHANGED OUT FOR A 110 OUTLET - [redacted] - 582-4105	Repair
11868305	3C - Low Sustain	3C - FPM 9001 POST 44-47 - WT - TAC ALARM -(10/04 TO 10/17) FF PANEL NEEDS NEW 12V 12 AMP BATTERIES - [redacted] - 582-4496-9001 - FA-1375D	Repair
11868479	3C - Low Sustain	3C - 9001 A34-A35 - WT - TAC HVAC - F/U 11866374 CHECK FOR WATER LEAK TO DETERMINE IF HVAC ISSUE - [redacted] - 582-4496	Repair
11868958	2A - Preventive Maintenance	C10251103950 - S - Fire doors, overhead - TINKER AFB - 9001 - METALS - ANNUALWEEK 16	Maintenance
11868959	2A - Preventive Maintenance	C10251103950 - S - Fire doors, overhead - TINKER AFB - 9001 - METALS - ANNUALWEEK 16	Maintenance
11869650	3C - Low Sustain	3C - 9001 ROOF PENTHOUSE DOORS - WT - LOCK - [redacted] ARE REQUESTING KEYS BE ISSUED TO THEM - [redacted] - 622-7846	Services

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.