

Darlington Nuclear Generating Station REGDOC-3.1.1 Reporting Q1-2024

<i>Report Number</i>	<i>Event Title</i>
D-2024-00062	Missed Test: As-Found Test of Pressure and Inventory Control System Bleed Condenser Relief Valve
D-2024-00184	Degradation: Impairment of Negative Pressure Containment System, due to Inadvertent Operation of Circuit Breaker, no Safety or Operability Impacts
D-2024-01131	Unplanned Power Change: Unit 3 Transient due to Boiler Feed Pump Trip, no Operability Impact
D-2024-01140	Regulatory Interest: Tubing Penetration Insulation Assumptions at the Feeder Cabinet, no Safety or Operability Impacts
D-2024-01399	Licence Non-Compliance: Heavy Water Management Building, West Annex, Fixed Area Alarming Gamma Monitors Found in Service Beyond Calibration Due Date
D-2024-01731	Environmental Action Level Exceedance: Tritium Removal Facility, Elemental Tritium, Safely Resolved
D-2024-03701	Licence Non-Compliance: Non-Dose Management System Active Worker Entered a Radiological Area, no Exposure Levels or Dose Limits Exceeded