

## **Tarrawonga Site Monitoring**

These monitors are used as operation management tools (no criteria apply)



PM<sub>10</sub>: particle matter 10 micron or less in size.
 (C): recalculation of the 24hr average as some data unavailable due to rain, power or communications.

Noise (LF)<sup>23</sup>

Average reading for the period of 06 October 2022


Day: 7am-6pm Evening 6pm-10pm Nights 10pm-7am

33.6dB(A) 30.7dB(A) 34dB(A)

Operational Response:

No Action Required

- 2. LF is estimated equivalent mining noise (LF = low frequency for band 20-630 HZ); Monitoring results may include noise from other sources.
  - \*Elevated levels affected by non- related mining event.
  - N/A: Data Not available due to servicing, power outage or communication issue.
  - (C): recalculation of the average as some data unavailable due to rain, power or communications.



For further information contact:

02 6741 5009 or TarrawongaEnvironment@whitehavencoal.com.au