# The Following information regarding this incident has been reported:

**Reporting Date:** 11/12/2024 1:41:05 PM **Incident Date:** 11/6/2024 @ 8:55 a.m.

**Reported By:** Paul C. Pimentel, Principal Manager **Utility Name:** Southern California Edison Company

Phone Number: (626)302-5830

Email Address: <a href="mailto:paul.pimentel@sce.com">paul.pimentel@sce.com</a>

**Incident Location:** Balcom Canyon Road Somis, Ventura County

## **Reasons For Reporting:**

- Fatalities? No (Utility: , Others: )
- Names of Fatalities:
- Injuries? (Utility: , Others: )
- Names of Injured:
- Damage? Yes (Utility: , Others: )
- Interruption? (Total Customers: , Total Hours: )
- Operator Judgement? Yes
- Media Coverage? Yes

Cause of Incident: Unknown (Other Cause: )

# **Agencies on Scene:**

#### **Facilities Affected:**

- Utilities Facilities: Rainbow
- Voltage (KV): 16 kV
- Customer's Facilities:

### **DigIn Information:**

- Excavator Name:
- Contact:
- Phone: (\_\_\_)\_\_-

### **Incident Recovery:**

- On Scene Date & Time: @ 00:00 a.m.
- Service Restored: @ 00:00 a.m.

**Summary:** SCE submits this report out of an abundance of caution because the incident may meet the reporting criteria. The Mountain Fire has received significant media attention and has caused property damage exceeding \$50,000. SCE has received a copy of a complaint alleging that its electric facilities may have ignited the Mountain Fire; the incident is therefore allegedly attributable to utility facilities, which technically triggers this report. To date, no fire agency has suggested that SCE's electric facilities were involved in the ignition or requested the removal and retention of any SCE equipment. Additionally, preliminary information indicates that SCE had no interruptions or operations on the section of the circuit nearest where SCE understands to be the suspected origin location of the fire close in time to its ignition. Aside from the plaintiffs in this lawsuit alleging SCE's potential involvement, we do not believe this incident meets the reporting requirements.