

SAFETY RECALL

Dorel Juvenile Group, Inc. in the U.S.A (DJ USA) announces a voluntary safety recall of certain Safety 1st and Maxi-Cosi infant car seats

When these car seats are installed into the vehicle with the base secured using the lower anchors, they may detach which will not adequately protect the child from injury in the event of a crash. Also, installing Coral XP into a vehicle with only its inner carrier is not sufficient to restrain a child without the use of the outer carrier.



**Safety 1st onBoard 35
SecureTech**



**Safety 1st SecureTech
Infant Base**



Maxi-Cosi Coral XP



Maxi-Cosi Mico XP



Maxi-Cosi Mico XP Max



Maxi-Cosi Mico Luxe+



Maxi-Cosi Infant Base

The following models, from all dates of manufacture, are included in this recall: IC313FNA, IC313FNB, IC313FNC, IC313FND, IC313GHT, IC335BLK, IC336FYH, IC336FZA, IC336FNA, IC336FZH, IC336FZJ, IC336FZL, IC336FZO, IC336GCA, IC336GCB, IC337FNA, IC337FNB, IC337FZF, IC337FZG, IC337FZH, IC337GKE, IC337GKF, IC338FNA, IC338FNB, IC351GKN, IC351GKO, IC351GKP, IC351GKQ, IC351HAS, IC351HAY, IC370FNA, IC370FNG, IC370GKE, IC370GKF, IC372BLK

You may continue to use each of these car seats with or without the base when installed using the vehicle belt restraint. Coral XP's inner carrier may continue to be used when attached to the outer carrier when installed in a vehicle. A free replacement base will be sent to registered non-Coral XP owners when they become available. Coral XP registered owners will receive a free replacement car seat or a refund. To become a registered owner, or if you have any questions regarding this recall, please contact DJ USA by calling 1-877-657-9546 Monday through Friday from 8AM to 5PM EST or email us at RetractableLatchRecall@djgusa.com.

Safety Notice: Maxi Cosi & Safety 1st Infant Car Seat Voluntary Recall

NHTSA Recall Nos. 23C002 & 23C003

Dorel Juvenile Group, Inc. in the U.S.A. (DJ USA) has decided all USA models of Maxi-Cosi Coral XP, Mico XP, Mico XP Max, and Mico Luxe+ and Safety 1st onBoard 35 SecureTech rear facing infant car seats and Maxi-Cosi Infant Car Seat Base with self-retracting lower anchor systems fail to conform to the requirements of Federal Motor Vehicle Safety Standard (FMVSS) No. 213 "Child Restraint Systems".

Maxi-Cosi Coral XP:

For owners of Maxi-Cosi Coral XP as well as Travel Systems containing Coral XP, you may continue to safely use your inner carrier when attached to the outer carrier and the outer carrier is installed with or without the base using the vehicle belt restraint system, consistent with the existing instruction booklet and labels. A free replacement car seat will be sent directly to you when it is available or if preferred, we will provide a full refund of your original purchase price. Please see further details below regarding model numbers impacted as well as how to register for a replacement car seat or refund.

Maxi-Cosi Mico XP, Mico XP Max, Mico Luxe+, Safety 1st Onboard 35 SecureTech:

For owners of Maxi-Cosi Mico XP, Mico XP Max, Mico Luxe+ and Safety 1st Onboard 35 SecureTech car seats/bases you may continue to safely use your car seat with the base when secured using the vehicle belt restraint system, or with shell only installation secured using the vehicle belt restraint system, consistent with the existing instruction booklet and labels. A free replacement base will be sent directly to you when it becomes available. Please see further details below regarding model numbers impacted as well as how to register for a replacement base.

FAQ's:

1. Which models does this recall include?

The below US car seat/base models are affected for all dates of manufacture ranging from May 1, 2020 to February 28th, 2023. Note that the complete model number has 3 characters following indicating the color/fashion. ALL color/fashions for these models are impacted.

IC313 MAXI COSI CORAL XP CAR SEAT
IC335 MAXI COSI INFANT CAR SEAT BASE
IC336 MAXI COSI MICO XP MAX INFANT CARSEAT
IC337 MAXI COSI MICO XP MAX INFANT CARSEAT
IC338 MAXI COSI MICO XP MAX INFANT CARSEAT
IC351 SAFETY 1ST ONBOARD 35 SECURETECH CARSEAT
IC370 MAXI COSI MICO LUXE + INFANT CAR SEAT
IC372 SAFETY 1ST SECURETECH INFANT CAR SEAT BASE



Safety Notice: Maxi Cosi & Safety 1st Infant Car Seat Voluntary Recall

NHTSA Recall Nos. 23C002 & 23C003

Some recalled models were purchased at retailers together with a stroller as part of a Travel System. Note that the complete model number has 3 characters following indicating the color/fashion. ALL color/fashions for these models are impacted.

TR416 MAXI COSI GIA XP TRAVEL SYSTEM W/MICO XP
TR427 MAXI COSI ZELIA 2 MAX TRAVEL SYSTEM MXP
TR428 MAXI COSI TAYLA TRAVEL SYSTEM W/MICO XP
TR430 MAXI COSI ADORRA TRAVEL SYSTEM W/MICO XP
TR433 MAXI COSI TAYLA XP TRAVEL SYS W/CORAL XP
TR434 MAXI COSI MARA XT TRAVEL SYS W/ CORAL XP

Please locate your product's model number and date of manufacture by looking at the label included on the carrier shell and/or base of your car seat as shown below:



2. Does this recall involve any Infant Seats sold in Canada or other countries?

Yes, Canadian models are below:

01371 CAN MAXI COSI LILA CP TRAVEL SYSTEM
22304 CAN MAXI COSI CORAL XP INFANT CAR SEAT
22321 CAN MICO XP MAX CAR SEAT
22334 CAN MAXI COSI MICO XP MAX
22524 CAN MAXI COSI CORAL XP BASE
22526 CAN MAXI COSI MICO XP BASE

Shipments were also made to other countries. Those companies are being notified and are working with local experts and respective regulatory agencies to determine actions.

3. Does this recall involve any Infant Seats sold in Europe including the U.K.?

No, as the design is different for the lower anchors. The design complies and is certified to Europe standards.

4. Does this recall involve all Maxi Cosi and Safety 1st Infant Seats?

No. This only affects certain infant car seats with self-retracting latch systems in their base as noted above.

Safety Notice: Maxi Cosi & Safety 1st Infant Car Seat Voluntary Recall

NHTSA Recall Nos. 23C002 & 23C003

5. Can I still safely use my Coral XP Infant Seat and Base until my replacement car seat arrives?

Yes, you may continue to safely use your inner carrier when attached to the outer carrier and the outer carrier is installed with or without the base using the vehicle belt restraint system, consistent with the existing instruction booklet and labels. until your replacement car seat arrives. See our installation videos on YouTube: [Maxi Cosi Models](#)

6. Can I still safely use my Non-Coral XP Infant Seat and Base until my replacement base arrives?

Yes, you may continue to safely use these car seats with the base installed using the vehicle belt, or with outer carrier shell only installation using the vehicle belt, consistent with the existing instruction manual and labels until your replacement base arrives. See our installation videos on YouTube: [Maxi Cosi Models](#) [Safety First Models](#)

7. How will I be notified with updates regarding the recall or replacements?

If you have registered your car seat and have an affected model, you will receive a notification letter via mail, or e-mail.

8. How do I register my car seat?

You may register your car seat at:
<https://www.maxicosi.com/us-en/registration/>
<https://www.safety1st.com/us-en/registration/>

You may also contact the Dorel Juvenile Consumer Care team at 1-877-657-9546 or RetractableLatchRecall@djgusa.com

9. What do I do with my recalled car seat once my replacement car seat or base arrives?

For **Coral XP** owners, once your replacement car seat arrives or you receive your refund, please cut the anchor webs and harness off the old base & carrier shell (if you haven't already done so), then properly dispose of the entire Coral XP unit including the base, outer shell and inner shell.

For **non-Coral XP** owners, once your replacement base arrives, please cut the anchor webs off the old base (if you haven't already done so) and properly dispose of the old base. You may continue to use the infant carrier outside the vehicle in all modes of use.

10. When will the updated base or replacement car seat be available?

Safety Notice: Maxi Cosi & Safety 1st Infant Car Seat Voluntary Recall

NHTSA Recall Nos. 23C002 & 23C003

We will be sending updates regarding availability so please ensure you have registered following the instructions above. We are taking measures to accelerate the availability of the replacement base.